

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Jun-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1038 U

1 pc	Rear o/s fender	\$	1,205.00
1 pc	Rear windscreen moulding	\$	87.00
1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
1 pc	Rear bumper o/s & o/s side bracket @ \$29.00	\$	29.00
1 pc	Rear o/s wheel cover	\$	116.00
			\$ 2,339.00
Less 10%			\$ 233.90
			\$ 2,105.10

S/NETT

1 set	Rear bumper clips	\$	48.00
1 pc	Rear o/s fender sticker	\$	60.00
1 set	o/s door stickers	\$	100.00
1 set	Sealant	\$	50.00
Sundry		\$	50.00 20
To dismantle and refit old windscreen glass onto new moulding		\$	120.00 60
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	1,200.00 600
To putty and spray painting on rear bumper, rear o/s fender, o/s rocker panel garnish, rear o/s door		\$	800.00 500
To apply rustproofing on the repaired and replaced panels.		\$	120.00 50
			\$ 4,833.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin (UKE)
26/6/19 17:05h
4 Pm
L/S
Allen Rep & PHL