

(MSP/01)

INS. CASE OWNER:

CC 4/AIG1901 1318, K26639

LKK:

IDAC:

Surveyor:

Karlun

DOI:

ASSIGNMENT

206/19

Date / Time:

25/6/19

Registered in Merimen:

20/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUP 3712H

Claim No.:

81667404556

Name of Insured:

YEH LHM HSIANG & YEH MYSON

Policy No.:

130004411-02

Insured Tel No.:

HP:

Make / Model:

MERCEDES

Excess Sec II :SS

D.O.A.:

27/6/19

Place of Accident:

YIO LHM KANG RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHA 29377



INSRS:

WSP:

Tel:

Liability:

RMKS:

CUT 46



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

5/10/19 - 2

6/10/19 - 1

2/12/19 - FILE AMS TO WP TO 4016

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call 01:

After call 1st to 01:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to 01:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 16/10/19

Confirm with: Kaza;

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/621)

SS 4357.92

Loss of Rental (LOR):

SS 500.76

(4 days) x 125.19

Loss of Use (LOU):

SS -

(5 x 4 days)

Loss of Income (LOI):

SS 200.00

(5 50 x 4 days)

LOR only ☐ LOU only ☐

LOR + LOI

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 2.49

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

3320

Total:

SS 5066.17

Global Sum SS: 5000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 5000.00

Name 1:

Comfort Delgro Engineering Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REPAIR ESTIMATE*

VEHICLE NO : SHA 2937J

DATE 25/6/2019 15:01

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>not p/h</i>			\$ 2,480.40
	Boot Lid Lock Upper <i>X</i>			\$ 224.00
	Boot Lid 'H' Emblem <i>X</i>			\$ 28.00
	Emblem -Hybrid <i>m</i>			\$ 24.30
	Emblem -Ioniq <i>m</i>			\$ 31.30
	Boot Lid Glass, Lower <i>X</i>			\$ 384.90
	Rear Bumper <i>not p/h</i>			\$ 459.40
	Rear Bumper Centre Moulding Assy <i>m</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>X</i>			\$ 47.50
	Rear Bumper Stay <i>X</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>X</i>		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips <i>m</i>			\$ 22.00
	Rear Windscreen Glass <i>X</i>			\$ 607.20
	Rear Windscreen Moulding <i>X</i>			\$ 28.20
	SUB TOTAL			\$ 4,992.75
	LESS 20%			\$ 998.55
	DISCOUNTED TOTAL			\$ 3,994.20
	Boot Lid Comfort Logo Sticker <i>m</i>			\$ 30.00
	Boot Lid Tel No.Sticker <i>m</i>			\$ 30.00
	Rear No.Plake <i>m</i>			\$ 25.00
	Rear Bumper Reverse Sensor <i>not p/h</i>			\$ 135.70
	Rear Windscreen Sealant <i>not p/h</i>			\$ 46.00
				\$ 266.70
	Labour Charge			300
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,490.00
	ESTIMATE TOTAL			\$ 5,750.90
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

A/C

Cheng

Like Auto Care, we are happy to help you with your car insurance claim. We will provide you with a quote for the repair work. We will also provide you with a list of recommended repair shops. We will also provide you with a list of recommended parts suppliers. We will also provide you with a list of recommended labourers. We will also provide you with a list of recommended painters. We will also provide you with a list of recommended sealers. We will also provide you with a list of recommended stickers. We will also provide you with a list of recommended no. plates. We will also provide you with a list of recommended reverse sensors. We will also provide you with a list of recommended sealants. We will also provide you with a list of recommended labour charges. We will also provide you with a list of recommended panel beating charges. We will also provide you with a list of recommended spray painting charges. We will also provide you with a list of recommended wiring charges. We will also provide you with a list of recommended tuff kote charges. We will also provide you with a list of recommended remove/refix cushion & upholstery rear charges. We will also provide you with a list of recommended remove/refix rear windscreen glass charges. We will also provide you with a list of recommended remove/refix reverse sensor charges. We will also provide you with a list of recommended total labour charges. We will also provide you with a list of recommended estimate total charges.

Kalin Uka

26/6/19 10 50h

3 P/h

PIP

Before Paint p/h

REPAIR ESTIMATE*

DATE 25/6/2019 15:01

MODEL : HYUNDAI IONIO

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 2,480.40
	Boot Lid Lock Upper ✕			\$ 224.00
	Boot Lid 'H' Emblem ✓			\$ 28.00
	Emblem -Hybrid ✓			\$ 24.30
	Emblem -Ioniq ✓			\$ 31.30
	Boot Lid Glass, Lower ✕			\$ 384.90
	Rear Bumper ✓			\$ 459.40
	Rear Bumper Centre Moulding Assy ✓			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy ✕			\$ 47.50
	Rear Bumper Stay ✕			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) ✕		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips ✓			\$ 22.00
	Rear Windscreen Glass ✕			\$ 607.20
	Rear Windscreen Moulding ✕			\$ 28.20
	SUB TOTAL			\$ 4,992.75
	LESS 20%			\$ 998.55
	DISCOUNTED TOTAL			\$ 3,994.20
	Boot Lid Comfort Logo Sticker ✓			\$ 30.00
	Boot Lid Tel No.Sticker ✓			\$ 30.00
	Rear No.Plates ✓			\$ 25.00
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Windscreen Sealant ✓			\$ 46.00
				\$ 266.70
	Labour Charge			
	Panel Beating			\$ 400.00 300
	Spray Painting Charge			\$ 600.00 400
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 ✕
	Remove/Refix Rear Windscreen Glass			\$ 120.00 100
	Remove/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 1,490.00
	ESTIMATE TOTAL			\$ 5,750.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORT DELGRO

Date/Time: 25.06.2019 13:56 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JO No: 305306245

CUSTOMER

REGN NO:

SHA2937J

MILEAGE

MS: COMFORT TRANSPORTATION PTE LTD

MAKE:

HYUNDAI

FUEL

CUSTOMER NO: 7010045

E 1/2 F

ADDRESS: 383 SIN MING DRIVE

MODEL:

IONIQ(G2)

DATE/TIME IN

25.06.2019 11:00

Singapore SINGAPORE 575717

YR OF MANU:

15.08.2018

TARGET DATE

(R) 65508755

(D)

(P)

CHASSIS CODE

KMHC851CVKU106524

COMPLETION DATE/TIME

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 23.06.2019

NATURE: 3P 23.06.2019

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

C

S:

S No:

SHA2937J

CHIANG

vehicle No.:

SHA2937J

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305306245
Date : 28/06/19

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No : SHA2937J

Fax :
23/06/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- 2 The repair job shall bill to: AIG SLP3712H
- 2 The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | \$3202.82 |
| (b) Labour Charges | \$ 870.00 |
| Total for Part-By-Part Repair Cost | \$ 4072.82 |
| (c) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |
- 3 Estimated normal period for repairs: 3 working days.
- 4 We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- 5 Thank you for your assistance
- We confirm the estimates and finalized amount
- Signature : [Signature] Signature : [Signature]
Name : CHIANG Name : Koh
Tel : 62148314 Date : 2/7/19
Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305306245
 REGN NO : SHA2937J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 15.08.2018
 DATE/TIME IN : 25.06.2019 11:00
 ACCIDENT DATE : 23.06.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2256-G	IONIQ PANEL ASSY-TAIL GAT	1	2,480.40	20.00	1,984.32
0002	05-01-0199-0032-A	(ALL)WINDSCREEN AHESIVE-3	2	46.00	2.00-	46.00
0003	04-01-0104-2270-G	IONIQ EMBLEM-HYBRID	1	24.30	20.00	19.44
0004	04-01-0104-2271-G	IONIQ EMBLEM-IONIQ	1	31.30	20.00	25.04
0005	28-01-0103-0005-A	(I40/SONATA)REAR BOOT LOG	1	30.00	2.00-	30.00
0006	28-01-0103-0006-A	(I40/SONATA)REAR BOOT TEL	1	30.00	0.20	30.00
0007	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0008	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00
0009	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	2.00-	135.70
0010	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0011	FNPS	NO PLATE(S)	1 N	25.00	2.00-	25.00
0012	04-01-0104-2370-G	IONIQ LAMP ASSY-REAR FOG	1	201.50	^{2%} 0.20	201.50

SUB-TOTAL : 3,243.12

JOB NATURE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305306245
 REGN NO : SHA2937J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 15.08.2018
 DATE/TIME IN : 25.06.2019 11:00
 ACCIDENT DATE : 23.06.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING	300.00				
0001 SP	SPRAYPAINT CHARGE	400.00				
0002 17-01	CHECK ALL LIGHTING	20.00				
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00				
0004 20-06-210R	REMOVE & REPLACE REAR W/SCREEN.	100.00				
0005 20-22	REMOVE/REFIX REVERSE SENSOR	30.00				
SUB-TOTAL :						870.00
TOTAL :						4,113.12

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

RE: SHA2937J VS SLP3712H THIRD PARTY CLAIMS

AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>

Tue 25/6/2019 3:41 PM

To: Chiang Liat Choon <chianglc@cdge.com.sg>

WITHOUT PREJUDICE

Hi Sir,

We'll appoint LKK to survey.

Thanks.

AIG Claims Survey

From: Chiang Liat Choon [mailto:chianglc@cdge.com.sg]

Sent: Tuesday, June 25, 2019 3:27 PM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] Fw: SHA2937J VS SLP3712H THIRD PARTY CLAIMS

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Attached herewith repair estimate & gia.

Best Regards

Chiang Liat Choon

Taxi Crash Repair ComfortDelGro Engineering Pte Ltd

Off: 62148314 Fax: 65468156

From: ApeosPort-IV C5570 <sbs-singnalling@sbstransit.com.sg>

Sent: Tuesday, 25 June 2019 3:22 PM

To: Chiang Liat Choon

Subject: Scan Data from CDG_LO_AW_A5570

Number of Images: 12

Attachment File Type: PDF

Device Name: ApeosPort-IV C5570

Device Location:

SHA2937J VS SLP3712H THIRD PARTY CLAIMS

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 6/25/2019 3:40:44 PM
Attachments:  img-625152202-0001.pdf

Hi LKK,

Kindly assist to survey.

4.18pm @ 25/6/19
vehicle in
sur @ kelvin

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Chiang Liat Choon [mailto:chianglc@cdge.com.sg]
Sent: Tuesday, June 25, 2019 3:27 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] Fw: SHA2937J VS SLP3712H THIRD PARTY CLAIMS

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Attached herewith repair estimate & gia.

Best Regards
Chiang Liat Choon
Taxi Crash Repair ComfortDelGro Engineering Pte Ltd
Off: 62148314 Fax: 65468156

From: ApeosPort-IV C5570 <sbs-singnalling@sbstransit.com.sg>
Sent: Tuesday, 25 June 2019 3:22 PM
To: Chiang Liat Choon
Subject: Scan Data from CDG_LO_AW_A5570

Number of Images: 12
Attachment File Type: PDF

Device Name: ApeosPort-IV C5570

Device Location:

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199508048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Defu
6 Defu Avenue 1
Singapore 539537

Marymount
600 Sin Ming Avenue
Singapore 575733

Our Ref : 305306245

Date : 250619

Time of Fax : _____

AIG

Via Fax : EMAIL

Your Insured : SLP 3712H

Date of Acc : 23 06 19

Attn : Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHA2937J

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find :
 - i) Our initial estimate of repairs of the damaged vehicle.
 - ii) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Tel no. 62148316 or Hp no. 98240811

Jumari Masudin Tel no. 62148315 or Hp no. 96355305

Chiang Liat Choon Tel no. 62148314

Lim Tien Siong Tel no. 62148398 or Hp no. 96358546

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.

- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

- 7 Thank you.

Yours faithfully

for Vice President

Crash Repairs & Claims Recovery

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jun 2019 Edit Reg		25 Jun 2019 00:00 Edit Adj Rpt	S\$4,072.82 Edit Estimates	S\$4,072.82 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	YEH CHIA HSIANG @YEH JAYSON, ID: S2583236A								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA2937J	Date of Loss:	23/06/2019 10:00 - :59 [10 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8988725045SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLP3712H	Policy No. (Claimant):	D-18088936MFSH						
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 05/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA2937J (8988725045SG)
[SLP3712H]
TP
COMFORT TRANSPORTATION PTE LTD
Jun 23 2019 10:00AM
[YEH CHIA HSIANG @YEH JAYSON]
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
------------------	--	---------------	--	--------------------	--	--------------	--	--------------	--	---	--

Letters/Correspondences										1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown								Edit		

Photos/Images										3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	27/06/19 08:49	General View								Load JPG	☒	
2	27/06/19 08:49	General View								Load JPG	☒	
3	27/06/19 08:49	General View								Load JPG	☒	
4	27/06/19 08:49	General View								Load JPG	☒	
5	27/06/19 08:49	General View								Load JPG	☒	
6	27/06/19 08:49	General View								Load JPG	☒	
7	27/06/19 08:49	General View								Load JPG	☒	
8	27/06/19 08:49	General View								Load JPG	☒	
9	27/06/19 08:49	General View								Load JPG	☒	
10	27/06/19 08:49	General View								Load JPG	☒	
11	27/06/19 08:49	General View								Load JPG	☒	
12	27/06/19 08:49	General View								Load JPG	☒	
13	27/06/19 08:49	General View								Load JPG	☒	
14	27/06/19 08:49	General View								Load JPG	☒	
15	27/06/19 08:49	General View								Load JPG	☒	
16	27/06/19 08:49	General View								Load JPG	☒	
17	27/06/19 08:49	General View								Load JPG	☒	
18	27/06/19 08:49	General View								Load JPG	☒	
19	27/06/19 08:49	General View								Load JPG	☒	
20	27/06/19 08:49	General View								Load JPG	☒	
21	27/06/19 08:49	General View								Load JPG	☒	
22	27/06/19 08:49	General View								Load JPG	☒	
23	27/06/19 08:49	General View								Load JPG	☒	
24	27/06/19 08:49	General View								Load JPG	☒	
25	27/06/19 08:49	General View								Load JPG	☒	
26	27/06/19 08:49	General View								Load JPG	☒	
27	27/06/19 08:49	General View								Load JPG	☒	
28	28/06/19 09:12	Reinspection Photo								Load JPG	☒	
29	28/06/19 09:12	Reinspection Photo								Load JPG	☒	
30	28/06/19 09:12	Reinspection Photo								Load JPG	☒	
31	28/06/19 09:12	Reinspection Photo								Load JPG	☒	
32	28/06/19 09:12	Reinspection Photo								Load JPG	☒	
33	28/06/19 09:12	Reinspection Photo								Load JPG	☒	

Documentation										1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	26/06/19 15:52	TP EST & GIA REPORT								Load PDF		
2	26/06/19 15:52	EMAIL FROM AIG DD 25062019								Load PDF		
3	27/06/19 18:10	TP ESTIMATE- MARKED								Load PDF		
4	06/08/19 15:54	Authorisation to Act								Load PDF		
5	06/08/19 15:54	LOD								Load PDF		

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
6	06/08/19 15:54	LTA SEARCH		Load PDF	
7	06/08/19 15:54	RENTAL RECEIPT & MILEAGE		Load PDF	
8	06/08/19 15:54	WKSP INVOICE		Load PDF	
9	06/12/19 08:27	Release Voucher		Load PDF	
10	06/12/19 08:27	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	27/06/19 09:46	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLP3712H (Insd veh)	Model:	HYUNDAI IONIQ HYBRID 1.6
	SHA2937J (TP veh)		GLS DCT (A)
Date of Accident:	23/06/2019		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No
Repair Estimate	:	\$	6,325.95
Final Repair Cost	:	\$	5,000.00
Loss of Use	:	\$	4.00 days at \$50.00 per day
Rental (if any)	:	\$	4 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	5,000.00

Is Third Party Workshop GIA Registered? ☒ [X] YES ☐ [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/~~No~~ BOLA Scenario No: _____
 27
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 5,000.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

06 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
 Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011318/K1DB3Q2

Date: 06/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SHA2937J Insured Vehicle No : SLP3712H

Date of Loss: 23/06/2019 Nature of Claim: TP Claim No: 8988725045SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA2937J**
 Make & Model: **HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)** Engine No: **G4LEJU076131**
 Reg. Date: **15/08/2018 (Man. Year: 2018)** Chassis No: **KMHC851CVKU106524**
 Colour: **Blue** Odometer: **94189 km**
 Engine Capacity: **1580 cc**
 Market Value/New Car Price: **N/A**
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Davanti 7 mm Rear Left Side: Davanti 7 mm
 Front Right Side: Davanti 7 mm Rear Right Side: Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,422.10	3,202.82	1,219.28	27.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	870.00	620.00	41.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,912.10	4,072.82	1,839.28	31.11
+ GST 7.00/7.00% (S\$)	413.85	285.10	128.75	31.11
Nett Amount (S\$)	6,325.95	4,357.92	1,968.03	31.11
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		5,066.17		
Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date of Assignment: 25/06/2019

Date Inspected: 26/06/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
 (Loyang)
 59 Loyang Drive
 Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID LOCK UPPER	Serviceable	224.00 FL	*- FL
3	1		*BOOT LID H EMBLEM	Serviceable	28.00 FL	*- FL
4	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
5	1		*EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
6	1		*BOOT LID GLASS ,LOWER	Serviceable	384.90 FL	*- FL
7	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
8	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	*451.25 FL
9	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Serviceable	47.50 FL	*- FL
10	1		*REAR BUMPER STAY	Serviceable	138.10 FL	*- FL
11	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Serviceable	66.20 FL	*- FL
12	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
13	1		*REAR WINDSCREEN GLASS	Serviceable	607.20 FL	*- FL
14	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.20 FL	*- FL
15	1		*BOOT LID COMFORT LOGO STICKER	Necessary	30.00 FS	*30.00 FS
16	1		*BOOT LID TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS
17	1		*REAR NO.PLATE	Cracked	25.00 FS	*25.00 FS
18	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
20	1		*REAR FOG LAMP	Cracked	201.50 FL	*201.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,460.95	3,936.85
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,038.85	734.03
Total Parts (\$\$)	4,422.10	3,202.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING CHARGE	New	600.00	400.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	0.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	100.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (S\$)			1,490.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >