

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

10/7/18

Owner : WELLMY RACHMATULLAH
FARYONO

Accident Date : 6-Jun-19

Vehicle No : FBK 4122 Z

Vehicle Model : YAMAHA MT09

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Fork inner tubes	\$ 11 440.00 X
2	Fork outer tubes	\$ 11 460.00 X
1	Headlamp	\$ 11 380.00 X
1	Handle-bar	\$ 2 135.00 X
1	Brake lever	\$ 11 22.00 X
1	Top fairing	\$ 1 210.00 X
1	Main stand	\$ 1 105.00 X
1	Front footrest	\$ 2 38.00 X
1	Front footrest bracket	\$ 2 90.00 X
1	Brake pedal	\$ 1 45.00 ✓
1	Rear footrest	\$ 1 42.00 ✓
1	Exhaust protector R/H	\$ 5 120.00 ✓
1	Crash bar (1 set)	\$ 5 350.00 ✓
		\$ 2,437.00
	Less 10%	\$ 243.70
		\$ 2,193.30

not about
the
height of the
3 day.
28/6/18

c/f: \$ 2,193.30

Special Nett Items

1	Number plate (1 set)	\$ 11	28.00	X
2	Fork oils	\$ 11	30.00	X
2	Fork oil seals	\$ 11	56.00	X
1	Steering cone (1 set)	\$ 11	95.00	X
1	Lever guard (1 set)	\$ (11)	280.00	
		\$	489.00	

S/No. **Labour**

1	To provide towing service.	\$ 11	50.00	X
2	To provide labour.	\$ 200	380.00	
3	To check wiring and reset headlamp focusing	\$ 11	80.00	X
		\$	510.00	

Grand Total **\$ 3,192.30**



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: