

Kw

威利摩托 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

1/7 - Konlat
11/11/11
LKK

Not withanw
Clerk @ 800p
Resurvey After claim
2-1 days

25, June 2019

INDIA INT'L INS PTE LTD
64 Cecil Street #04/#05/#06-02
IOB Building
S 049711

Attn : Motor claim dept—3rd party claim
Claiming against your insured vehicle no: SHC1094L
Accident involving vehicle no: SKG1763H/SHC1094L
DOA: 06/06/2019 At Along Upp Cross Street

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SKG1763H

To supply--

Description	Qty	Amount
Rear bumper	1	CM 482.00 ✓
Rear bumper retainer @72.70	2	Sm 145.40 X
Rear bumper sponge	1	Sm 117.50 X
Rear bumper fpglamp	1	Sm 37.20 X
End panel	1	R 581.20 X
End panel top garnish	1	Sm 185.20 X
Lid-1.6 emblem	1	na 32.10 X
Lid-VVTI emblem	1	na 38.40 X
Lid—altis emblem	1	na 42.35 X
Lid-corolla emblem	1	na 45.00 X
Rear bumper clip		na 42.00 ✓
Parts		1,748.35
Parts less 25%		437.08
		1,311.27

Reverse sensor
To remove damaged parts and attachments.
Repair/reshape dented areas.
Replace/align above parts into position.
To spray paint

Sm 220.00 X

800.00 200
750.00 400

LKK Auto Consultants hereby notify 3,081.27
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: