

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

25, June 2019

INDIA INT'L INS PTE LTD
64 Cecil Street #04/#05/#06—02
IOB Building
S 049711

Attn : Motor claim dept—3rd party claim
Claiming against your insured vehicle no: SHC1094L
Accident involving vehicle no: SKG1763H/SHC1094L
DOA: 06/06/2019 At Along Upp Cross Street

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SKG1763H
To supply--

Description	Qty	Amount
Rear bumper	1 <i>CM</i>	482.00 ✓
Rear bumper retainer @72.70	2 <i>pn</i>	145.40 X
Rear bumper sponge	1	117.50 ?
Rear bumper fplamp	1 <i>h</i>	37.20 X
End panel	1	581.20 ?
End panel top garnish	1 <i>pn</i>	185.20 X
Lid-1.6 emblem	1 <i>nn</i>	32.10 X
Lid-VVTI emblem	1 <i>nn</i>	38.40 X
Lid—altis emblem	1 <i>nn</i>	42.35 X
Lid-corolla emblem	1 <i>nn</i>	45.00 X
Rear bumper clip	<i>he</i>	42.00 ✓
Parts		1,748.35
Parts less 25%		437.08
		1,311.27

Reverse sensor
To remove damaged parts and attachments.
Repair/reshape dented areas.
Replace/align above parts into position.
To spray paint

pn 220.00 X

800.00 ?
750.00 *400*

LKK Auto Consultants hence notify 3,081.27
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Withheld
C/Ly 87
Running After Rain
2-4 days*