

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : **b1 51680**  
Date Estimated : **25/06/2019**  
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

**REPAIR FOR -**  
**Gerald Faust**  
**Kim Seng Road**  
**#22-03**

**- ACCOUNT - 40000**  
**Cash Sales - Service**  
**Singapore**

**Singapore 239432**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKL691L</b>	<b>F095724</b>	<b>08/03/2012</b>	<b>335i/4 (A)</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the front bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident	850.00		850.00
To spray paint front bumper	934.00		934.00
To check electrical wiring systems at the front section for proper function	150.00		150.00
To replace RH adaptive xenon headlight include programming and conducting tests for proper function	408.00		408.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH COVER SPRAY NOZZLE PRIMED	43.25	1.00		43.25
PLAQUE 82MM	71.25	1.00		71.25
HEADLIGHT RH (XENON/ADAPTIVE)	2,501.25	1.00		2,501.25

# SUPPLEMENTARY ITEMS

Total Labour :	2,422.00
Total Parts :	2,615.75
Total Labour & Parts :	5,037.75
Deduction for Excess :	
Total Repair Costs less Excess:	5,037.75
GST @7%:	352.64
Grand Total :	5,390.39