

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 51680** Page No. :
Date Estimated : **25/06/2019**
Prepared By : **Inthiran A/L Thurasamy**

REPAIR FOR -
Gerald Faust
Kim Seng Road
#22-03

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 239432

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL691L	F095724	08/03/2012	335i/4 (A)	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the front bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident	850.00		850.00 ✓
To spray paint front bumper	934.00		934.00 ✓
To check electrical wiring systems at the front section for proper function	150.00		150.00 ✓
To replace RH adaptive xenon headlight include programming and conducting tests for proper function	408.00		408.00 ✓
Sundries	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH COVER SPRAY NOZZLE PRIMED	43.25	1.00		43.25 ✓
PLAQUE 82MM	71.25	1.00		71.25 ✓
HEADLIGHT RH (XENON/ADAPTIVE)	2,501.25	1.00		2,501.25 ✓

SUPPLEMENTARY ITEMS

Total Labour :	2,422.00
Total Parts :	2,615.75
Total Labour & Parts :	5,037.75
Deduction for Excess :	
Total Repair Costs less Excess:	5,037.75
GST @7%:	352.64
Grand Total :	5,390.39