

INS. CASE OWNER:

KE

CC 4, ASM 190 (1324, E ga3)

LKK: 123497  
IDAC:

123497

Surveyor:

Steve

DOI:

ASSIGNMENT

26/6/2019

Date / Time:

26/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBL 2498U

Claim No.:

59M01R32

Name of Insured:

Loke Song Gas Supplier

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 26/6/19

Place of Accident:

Is driver the owner?

( YES /  NO )

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT  YES / NO ; TP GIA REPORT:  YES / NO

Driver Tel No.:

(V/L:  YES / NO )

Insured Liability: % Final ? Yes / No

LL 92324



INSRS:  
WSP: LAF 112  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time	STAGE	DATE / PIC
5/9/2019	Non-Reporting ltr (1st)	
	Non-Reporting ltr (2nd)	
	Non-Reporting ltr (Final)	
	Notification ltr (if non-pickup)	
	Call OI:	
	After call ltr to OI:	
12/6/19	Documentation Check List:	Handler Typist
20/6/19	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: Steve

Repair Cost: PIP \$5 3261.75 ( 5 days) Reduction: 1220.75 % 39 Email  Call

FINAL SETTLEMENT Date/Time: 16/11/2020 Confirm with: Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 15 IF NO or B 28, Ass. Lia :

Repair Cost: (W/AST) \$5 3440.07

Loss of Rental (LOR): \$5 - ( days)

Loss of Use (LOU): \$5 350.00 (\$ 50 x 7 days)

Loss of Income (LOI): \$5 - (\$ x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search \$5 2.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5 3842.07 Global Sum \$5:

FINAL PAYMENT Date/Time: Confirm with: Email  Call

Payee 1: \$5 3842.07 Name 1: Loke Lion City Rentals Pte Ltd

Payee 2 (Strike if N.A.) \$5 Name 2:

Payee 3 (Strike if N.A.) \$5 Name 3:

COPY SENT 6/11/2020

✓GIA



(Cecilia)

**LCRF PTE LTD**  
**CARROS CENTER**  
 60 JALAN LAM HUAT #04-01 S(737869)  
 Main +65 62524991

**Axa Insurance**

8 Shenton Way, #24-01 AXA Tower,  
 Singapore 068811  
 Tel:

Attn : MOTOR CLAIMS DEPT

**ESTIMATE**

VEHICLE NO. : SLL9232H  
 CHASSIS NO : NHP1707067354  
 MAKE / MODEL : TOYOTA SIENTA HYBRID  
 DATE OF ACCIDENT : 17 JUN 2019  
 YOUR INSURED VEHICLE NUMBER : GBC2498C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

	<u>PARTS DISCRPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER / <i>IR</i>	1PC	\$450.00	\$450.00 /
2	FRONT BUMPER SIDE RETAINER / <i>IR</i>	1PC	\$120.00	\$120.00 /
3	FRONT BUMPER FOG LAMP GARNISH / <i>CVT</i>	1PC	\$144.00	\$144.00 /
4	FRONT BUMPER SIDE BRACKET / <i>MS</i>	1PC	\$75.00	\$75.00 /
5	HEADLAMP RH / <i>IR</i>	1PC	\$990.00	\$990.00 /
6	HEADLAMP PANEL RH / <i>Q x R</i>	1PC	\$175.00	\$175.00 X
7	FRONT FENDER RH / <i>IR</i>	1PC	\$540.00	\$540.00 /
8	FRONT FENDER EMBLEM / <i>MC</i>	1PC	\$45.00	\$45.00 /
9	FRONT FENDER INNER SHIELD / <i>CR</i>	1PC	\$225.00	\$225.00 /
10	BONNET X <i>R</i>	1PC	\$570.00	\$570.00 X
11	BONNET HINGE X <i>MI</i>	1PC	\$96.00	\$96.00 X

LIST TOTAL S\$: 53,430.00 *2589*  
 25.00% DISCOUNT S\$: 857.50 *-75%*  
 \$2,572.50 *1941.75*

<u>SPECIAL NETT</u>			
1	FRONT BUMPER CLIP	1 SET	\$35.00 30 ✓
2	FRONT FENDER INNER SHIELD CLIP	1 SET	\$35.00 30 ✓

Special Nett Total S\$: 70.00 50

LABOUR CHARGES

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.FRONT FENDER ,FRONT HEADLAMP PANEL,BONNET	\$1,200.00	550
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)FRONT FENDER,FRONT BUMPER,HEADLAMP PANEL	\$1,200.00	600
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO	\$120.00	50
4	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS.	\$100.00	30
5	TO CONDUCT ALL WHEEL ALIGNMENT CHECK	\$120.00	300

LABOUR TOTAL S\$: 2,740.00 1270  
 TOTAL S\$: 5,382.50  
 7% GST 376.78  
 GRAND TOTAL S\$: 5,759.28

Stew (LKK)  
 8322 8813  
 Steering @ IKK out com

incl. 26/6/19, 2.00 pm  
 5 # days  
 P/P  
 Rj # spj  
 Bk

P-1941.75  
 N-50  
 L-1279

P/P-3261.75

Prepared By: -  
 Henry Ng  
 Motor Claims  
 TEL: 62524991  
 EMAIL: henry@lioncityrentals.com.sg

LCRF PTE LTD  
 CARROS CENTER  
 60 JALAN LAM HUAT #04-01 S(737869)  
 Main +65 62524991

**Axa Insurance**

8 Shenton Way, #24-01 AXA Tower,  
 Singapore 068811  
 Tel:

Attn : MOTOR CLAIMS DEPT

**ESTIMATE**

VEHICLE NO. : SLL9232H  
 CHASSIS NO : NHP1707067354  
 MAKE / MODEL : TOYOTA SIENTA HYBRID  
 DATE OF ACCIDENT : 17 JUN 2019  
 YOUR INSURED VEHICLE NUMBER : GBC2498C

	<u>PARTS DISCRPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER / <i>IB</i>	1PC	\$450.00	\$450.00
2	FRONT BUMPER SIDE RETAINER / <i>BR</i>	1PC	\$120.00	\$120.00
3	FRONT BUMPER FOG LAMP GARNISH / <i>CVT</i>	1PC	\$144.00	\$144.00
4	FRONT BUMPER SIDE BRACKET / <i>M.S</i>	1PC	\$75.00	\$75.00
5	HEADLAMP RH / <i>BR</i>	1PC	\$990.00	\$990.00
6	HEADLAMP PANEL RH / <i>BR</i>	1PC	<del>\$175.00</del>	<del>\$175.00</del>
7	FRONT FENDER RH / <i>BR</i>	1PC	\$540.00	\$540.00
8	FRONT FENDER EMBLEM / <i>MC</i>	1PC	\$45.00	\$45.00
9	FRONT FENDER INNER SHIELD / <i>CR4</i>	1PC	\$225.00	\$225.00
10	<del>BONNET / <i>BR</i></del>	<del>1PC</del>	<del>\$570.00</del>	<del>\$570.00</del>
11	<del>BONNET HINGE / <i>X</i></del>	<del>1PC</del>	<del>\$96.00</del>	<del>\$96.00</del>

LIST TOTAL S\$: \$3,430.00 *2589*  
 25.00% DISCOUNT S\$: \$857.50  
\$2,572.50 *1941.75*

**SPECIAL NETT**

1	FRONT BUMPER CLIP	1 SET	\$35.00	30 ✓
2	FRONT FENDER INNER SHIELD CLIP	1 SET	\$35.00	30 ✓

Special Nett Total S\$:       \$70.00       50

**LABOUR CHARGES**

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.FRONT FENDER ,FRONT HEADLAMP PANEL,BONNET	\$1,200.00	550
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)FRONT FENDER,FRONT BUMPER,HEADLAMP PANEL	\$1,200.00	600
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO	\$120.00	30
4	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS.	\$100.00	20
5	TO CONDUCT ALL WHEEL ALIGNMENT CHECK	\$120.00	200

LABOUR TOTAL S\$:	<u>\$2,740.00</u>	1270
TOTAL S\$:	\$5,382.50	
7% GST	\$376.78	
GRAND TOTAL S\$:	<u>\$5,759.28</u>	

Steve (LKK)  
8322 8817  
Steve@lkk.com

incl. 26/6/19, 2.00 pm 3261.75  
54 days

PIF  
Ry # sy  
Bch

PI: 3000.75  
26/6/19

Prepared By :-  
Henry Ng  
Motor Claims  
TEL: 62524991  
EMAIL: henry@lioncityrentals.com.sg

Parts 2,589.00  
1 on 2/19 647.25  
SN 1,941.75  
50.00  
Labour 1,270.00  
Net 3,261.75

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 4597K

#### Vehicle Details

Vehicle No.: SLL9232H  
Vehicle to be Exported: No  
Intended Deregistration Date: 26 Jun 2019  
Vehicle Make: TOYOTA  
Vehicle Model: SIENTA HYBRID 1.5G CVT  
Primary Colour: Silver  
Manufacturing Year: 2016  
Engine No.: 1NZR459355  
Chassis No.: NHP1707067354  
Maximum Power Output: 73.0 kW (97 bhp)  
Open Market Value: \$26,934.00  
Original Registration Date: 15 Mar 2017  
First Registration Date: 15 Mar 2017  
Transfer Count: 0  
Actual ARF Paid: \$5,000.00

#### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 14 Mar 2027  
PARF Rebate Amount: \$3,750.00

#### Intended COE Rebate Details

COE Expiry Date: 14 Mar 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$49,751.00  
COE Rebate Amount: \$38,359.00  
**Total Rebate Amount: \$42,109.00**

The information contained herein is correct as at 26 Jun 2019

OK

LCRF PTE LTD  
 CARROS CENTER  
 60 JALAN LAM HUAT #04-01 S(737869)  
 Main +65 62524991

**Axa Insurance**

8 Shenton Way, #24-01 AXA Tower,  
 Singapore 068811  
 Tel:

Attn : MOTOR CLAIMS DEPT

**ESTIMATE**

VEHICLE NO. : SLL9232H  
 CHASSIS NO : NHP1707067354  
 MAKE / MODEL : TOYOTA SIENTA HYBRID  
 DATE OF ACCIDENT : 17 JUN 2019  
 YOUR INSURED VEHICLE NUMBER : GBC2498C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

	<u>PARTS DISCRPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER / <i>LR</i>	1PC	\$450.00	\$450.00
2	FRONT BUMPER SIDE RETAINER / <i>LR</i>	1PC	\$120.00	\$120.00
3	FRONT BUMPER FOG LAMP GARNISH / <i>LR CVT</i>	1PC	\$144.00	\$144.00
4	FRONT BUMPER SIDE BRACKET / <i>LR MIS</i>	1PC	\$75.00	\$75.00
5	HEADLAMP RH / <i>LR</i>	1PC	\$990.00	\$990.00
6	HEADLAMP PANEL RH / <i>LR X R</i>	1PC	\$175.00	\$175.00
7	FRONT FENDER RH / <i>LR</i>	1PC	\$540.00	\$540.00
8	FRONT FENDER EMBLEM / <i>LR</i>	1PC	\$45.00	\$45.00
9	FRONT FENDER INNER SHIELD / <i>LR</i>	1PC	\$225.00	\$225.00
10	BONNET / <i>LR</i>	1PC	\$570.00	\$570.00
11	BONNET HINGE / <i>LR</i>	1PC	\$96.00	\$96.00

LIST TOTAL S\$:	\$3,430.00
25.00% DISCOUNT S\$:	\$857.50
	\$2,572.50

**SPECIAL NETT**

1	FRONT BUMPER CLIP <i>Acc</i>	1 SET	\$35.00	<i>30 ✓</i>
2	FRONT FENDER INNER SHIELD CLIP <i>Acc</i>	1 SET	\$35.00	<i>20 ✓</i>

Special Nett Total S\$:            \$70.00

**LABOUR CHARGES**

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.FRONT FENDER ,FRONT HEADLAMP PANEL,BONNET	\$1,200.00	<i>550</i>
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)FRONT FENDER,FRONT BUMPER,HEADLAMP PANEL	\$1,200.00	<i>600</i>
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO	\$120.00	<i>70</i>
4	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS.	\$100.00	<i>20 ✓ 30</i>
5	TO CONDUCT ALL WHEEL ALIGNMENT CHECK	\$120.00	<i>300</i>

LABOUR TOTAL S\$:	\$2,740.00
TOTAL S\$:	\$5,382.50
7% GST	\$376.78
GRAND TOTAL S\$:	<u>\$5,759.28</u>

*Steve (LKK)  
8322 8813  
Stevechan@lkkauto.com*

*incl Acc/ndc 26/6/19, 2.00 pm  
5 # days  
45 P/P  
Ry # spj  
Beh*

Prepared By :-  
Henry Ng  
Motor Claims  
TEL: 62524991  
EMAIL: henry@lioncityrentals.com.sg

## ◀ Service Request Details

Claim  
S9M01R32

Reference  
None 

Loss Date  
June 17, 2019

Report Date  
Jun 26, 2019 8:54:00 AM

Request Date  
June 26, 2019

Due Date  
July 3, 2019

Vendor Name  
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss  
Third Party Vehicle Damage

Services  
Pending verification - Direct Settlement

*P: Henry*  
*T: 10.430.m*  
*V: In*  
*E: ✓*

### Actions

Next Step  
Agree to perform service

### Vehicle Information

Incident Vehicle Registration #  
SLL9232H

ISSUE

SIENTA HYBRID-1.5 X CVT (A)

Service Address

...

Primary Contact/Insured

KOK SENG GAS SUPPLIER  
50 BUKIT BATOK STREET 23, #07-13 MIDVIEW BUILDING, 659578, Singapore  
64671422  
KOKSENGGAS@GMAIL.COM

Claim Handler

CHAN Kian Chuan  
6568804269  
kianchuan.chan@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

**Catherine Chong (LKK Auto)**

---

**From:** Henry Estimator <henry@lioncityrentals.com.sg>  
**Sent:** Tuesday, 25 June, 2019 4:23 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey; LCR Insurance Team; Lion City Rentals ARC  
**Subject:** Request for Third Party Survey and Liability Our Veh :SLL9232H Your Insured :GBC2498U  
  
**Categories:** Shekhar

Hi Sir / Madam


We would like to request for a third-party motor claim survey and liability, details as follow;

Our Vehicle: SLL9232H  
Your Insured: GBC2498U  
DOA: 16 JUN 2019

**Henry (62524991)**

**Senior Estimator**

**Email:** [henry@lioncityrentals.com.sg](mailto:henry@lioncityrentals.com.sg)



60 Jalan Lam Huat  
#04- 01  
Carros Centre  
Singapore 737869

REGISTRY OF COMPANIES AND BUSINESSES (RCB)  
COMPUTER INFORMATION (BUSINESS PROFILE) REPORT

10 ANSON ROAD #05-01/02, INTERNATIONAL PLAZA SINGAPORE 07990. TEL: (90) 272626 (TOLL-FREE) FAX: 2751676. EMAIL: rcb@edboard.com.sg

WHILE EVERY ENDEAVOUR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS CORRECT, THE REGISTRY  
DECLINES ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

1 ) NAME : SIM HUAY SENG  
SOLE-PROPRIETOR /  
PARTNER ID : S125B711B NATIONALITY : SINGAPOREAN  
SOLE PROPRIETOR /  
PARTNER ADDRESS : 214 PETIR ROAD  
#10-457  
DATE OF ENTRY : ( 670214 ) DATE OF CHANGE OF ADDRESS : 09/12/1987  
( 06/04/1983

2 ) NAME : SIM HOCK SENG  
SOLE-PROPRIETOR /  
PARTNER ID : S1380663B NATIONALITY : SINGAPOREAN  
SOURCE OF ADDRESS : NATIONAL REGISTRATION DEPARTMENT (NRD)  
SOLE PROPRIETOR /  
PARTNER ADDRESS : 203 BUKIT BATOK STREET 21  
#04-40  
( 650203 ) DATE OF REPORT TO NRD : 27/12/1999  
( 06/04/1983



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/8/2019

### Survey Details:

Date of loss	17-Jun-19
Date of appointment	26-Jun-19
Date of survey	26-Jun-19
Location of survey	LCRF PTE LTD

### Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLL9232H
Make and Model	TOYOTA SIENTA HYBRID 1.5G CVT
Date of registration	15-Mar-17
Parf Rebate	
Market Value	\$ 73,000.00
Parf Rebate	\$ 42,109.00
Nett Loss	\$ 30,891.00

### Repair details:

Initial Estimate	5,382.50
------------------	----------

### Proposed/Revised repair cost:

Parts	\$ 1,991.75
Check items (estimate)	\$ -
Labour	\$ 1,270.00
<b>Total</b>	<b>\$ 3,261.75</b>
Lump Sum(if applicable)	\$ -

Number of days for repair	5.0
---------------------------	-----



**Remarks:**

05 RECOMMENDED REPAIR DAYS + 2 PRS= 7 DAYS

**Mandate:**

Liability(TP)		100%	
Proposed repair cost	\$	3,490.07	W/GST
Loss of use	\$	420.00	7days x \$60
Loss of rental	\$	-	
Loss of income	\$	-	
LTA search fees	\$	2.00	
Others	\$	-	
<b>Proposed Total</b>	<b>\$</b>	<b>3,912.07</b>	

 <MANDATE IA> - S9M01R32 {ACCIDENT INVOLVING GBC 2498U (OI) & SLL 9232H (TP) ON 17/06/2019 }

Type

 Question

Message

LIABILITY: 100% BOLA S15: INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$3912.07 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED INTO SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

[Reply](#)

**AXA INSURANCE SINGAPORE PTE LTD**

 8 Shenton Way  
 #27-01  
 AXA Tower  
 Singapore 068811

**Tax Invoice**

Inv No. : WIN190800797

Date : 10 Aug 2019

Ref : GBC2498U

Currency : SGD

Terms : 7 Days

Veh No. : SLL9232H

#	Description	Qty	UOM	Unit Price	Tax Amt	Tax Type	Taxable Amt
1	Front bumper	1		337.50	23.63	GST (SR) (7%)	337.50
2	Front bumper side retainer	1		90.00	6.30	GST (SR) (7%)	90.00
3	Front bumper fog lamp garnish	1		108.00	7.56	GST (SR) (7%)	108.00
4	Front bumper side bracket	1		56.25	3.94	GST (SR) (7%)	56.25
5	RH headlamp	1		742.50	51.98	GST (SR) (7%)	742.50
6	F/R fender	1		405.00	28.35	GST (SR) (7%)	405.00
7	F/R fender emblem	1		33.75	2.36	GST (SR) (7%)	33.75
8	F/R fender inner shield	1		168.75	11.81	GST (SR) (7%)	168.75
9	Front bumper clips	1		30.00	2.10	GST (SR) (7%)	30.00
10	F/R fender inner shield clips	1		20.00	1.40	GST (SR) (7%)	20.00
11	GIA search fee	1		1.87	0.13	GST (SR) (7%)	1.87
12	To remove accident damaged parts in order to repair including panel beat, cut/weld, straighten panel ,Front fender, F/R headlamp panel and bonnet	1		550.00	38.50	GST (SR) (7%)	550.00
13	To putty & spray paint all affected areas(Inner/Outer) Front fender, F/R headlamp panel and bonnet	1		600.00	42.00	GST (SR) (7%)	600.00

Continue on next page...

**AXA INSURANCE SINGAPORE PTE LTD**

 8 Shenton Way  
 #27-01  
 AXA Tower  
 Singapore 068811

**Tax Invoice**
**Inv No. :** WIN190800797

**Date :** 10 Aug 2019

**Ref :** GBC2498U

**Currency :** SGD

**Terms :** 7 Days


**Veh No. :** SLL9232H

#	Description	Qty	UOM	Unit Price	Tax Amt	Tax Type	Taxable Amt
14	To apply rust proofing/tuffcoating treatment on all damaged parts	1		30.00	2.10	GST (SR) (7%)	30.00
15	To check wiring system	1		30.00	2.10	GST (SR) (7%)	30.00
16	To conduct wheel alignment	1		60.00	4.20	GST (SR) (7%)	60.00
17	Loss of use 5 Days	5		80.00	0.00	No GST (0%)	400.00
18	Pre-Repair Inspection 2 Days	2		80.00	0.00	No GST (0%)	160.00

Subtotal : S\$ 3,823.62

Total Tax : S\$ 228.46

**Total : S\$ 4,052.08**

 For Lion City Rentals Pte Ltd
 



Re:RE: Re:RE: Re:RE: Re:RE: Re:<MANDATE IA> -  
S9M01R32 {ACCIDENT INVOLVING GBC 2498U (OI) &  
SLL 9232H (TP) ON 17/06/2019 }

Type

🗨 Question

Message

PLS PROCEED FOR SETTLEMENT AS PROPOSED

Reply



Your Reference: GBC2498C

Our Reference: SLL9232H

Contact person: siaktong@lioncityrentals.com.sg

Date: 17/06/2019

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01

AXA Tower Singapore 068811

Dear sirs

Accident involving SLL9232H/GBC2498U dated on 17/06/2019

Your insured driving vehicle no: GBC2498U had negligently collided into our said vehicle.

As a result of the said collision, our car has suffered loss and damage as follows:

Cost of repairs	\$	3,490.07 (Inclusive GST)
Search Fee	\$	2.00 (Inclusive GST)
Loss of use \$80x 5 days	\$	400.00
Pre-Repair Inspection \$80x2 days	\$	160.00
Grand Total	\$	4,052.07

We enclosed herewith a copy of LTA search fee, GIA report and invoices of our said vehicle for your reference and further actions.

Yours Faithfully

S.T. Sim

Lion City Rentals Pte Ltd

1090 Lower Delta Road  
#05-12 Singapore 169201

LCR Hotline : 3138 1884  
www.lioncityrentals.com.sg  
rentals@lioncityrentals.com.sg

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19011324/Ega3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 10-03-2020	
ATTN:KIAN CHUAN		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 2498U	Veh. Inspected	SLL 9232H
Policy No.	GA397036	Coverage (\$)	0.00
Claim No.	S9M01R32	Excess (\$)	0.00
Assign From		Assign Date	26/06/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NHP1707067354	Colour	SILVER
Odometer	194578	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	FIRENZA	7 mm
L/H Front Tyre	185/60 R15	FIRENZA	7 mm
R/H Rear Tyre	185/60 R15	FIRENZA	7 mm
L/H Rear Tyre	185/60 R15	FIRENZA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/06/2019	Inspection Date	26/06/2019
Survey held at	60 JALAN LAM HUAT #04-01		
Repairer	LION CITY ELECTRIC PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9232H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	BROKEN	450.00	450.00
1	FRONT BUMPER SIDE RETAINER (CONSISTENT)	BROKEN	120.00	120.00
1	FRONT BUMPER FOG LAMP GARNISH (CONSISTENT)	CUT	144.00	144.00
1	FRONT BUMPER SIDE BRACKET (CONSISTENT)	MISSING	75.00	75.00
1	HEADLAMP RH (CONSISTENT)	BROKEN	990.00	990.00
1	HEADLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	175.00	-
1	FRONT FENDER RH (CONSISTENT)	DENTED	540.00	540.00
1	FRONT FENDER EMBLEM (CONSISTENT)	NECESSARY	45.00	45.00
1	FRONT FENDER INNER SHIELD (CONSISTENT)	CRUSHED	225.00	225.00
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	570.00	-
1	BONNET HINGE (CONSISTENT)	NOT NECESSARY	96.00	-
	LESS 25% DISCOUNT		-857.50	-647.25
			2,572.50	1,941.75
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	35.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN) (CONSISTENT)	NECESSARY	35.00	20.00
			70.00	50.00
<b>LABOUR</b>				
	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT , CUT/WELD , STRAIGHTEN PANEL WHERE STRAIGHTEN , FRONT FENDER , FRONT HEADLAMP PANEL , BONNET , INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL RH AND BONNET.		1,200.00	550.00
	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER) FRONT FENDER , FRONT BUMPER , HEADLAMP PANEL.		1,200.00	600.00
	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO.		120.00	30.00
	TO CHECK REAR WIRES ,CONNECTORS ,REPLACE DAMAGED LAMPS.		100.00	30.00

Report Ref No. CC4/ASM19011324/Ega3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT ALL WHEEL ALIGNMENT CHECK.		120.00	60.00
			2,740.00	1,270.00
<b>GRAND TOTAL</b>			<b>5,382.50</b>	<b>3,261.75</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,261.75</b>

Report Ref No. CC4/ASM19011324/Ega3q2

**CHEN TSUE YEE**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

### Service Request Details

Claim	59M01R32
Reference	CC4/ASM459011224/Eqa3q2
Loss Date	17 June 2019
Report Date	26 Jun 2019 8:54:00 AM
Request Date	26 June 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

**Actions**

Next Step: Wait for Approve invoice

[Add Events](#)

Vehicle Information	
Incident Vehicle Registration #	SL19232H
Make	TPVO TOYOTA
Model	SIENTA HYBRID-1.5 X CVT 1A
Service Address	

Primary Contact/Insured	
KOK SENG GAS SUPPLIER 50 BUNIT BATOK STREET 23, #07-13 MIDVIEW BUILDING, 659578, Singapore 64671422 KOKSENGGAS@GMAIL.COM	

Claim Handler	
CHAN Kian Chuan 68805444 kianchuan.chan@axa.com.sg	

#### Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

[Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (8).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
LKKAdjustment1a (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Subsidiary / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
DI CO ACR1.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	13 January 2020
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
LDD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
MANDATE M DO 20082019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
TP EST LIST MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
PAGE COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
TP ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	2 July 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKX SURVEY PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 July 2019
 TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	1 July 2019
 78E19FB5-5876-46F3-8C08-130B4C25FEE6.MP4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 June 2019
 EMAIL TP Pflumg	Letters and Correspondence	Third Party	VISHNU BATHAM Shekhar	26 June 2019
 GIA SLL9232H TSPDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	26 June 2019