

Cecilia

LCRF PTE LTD  
CARROS CENTER  
60 JALAN LAM HUAT #04-01 S(737869)  
Main +65 62524991

**Axa Insurance**  
8 Shenton Way, #24-01 AXA Tower,  
Singapore 068811  
Tel:

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLL9232H  
CHASSIS NO : NHP1707067354  
MAKE / MODEL : TOYOTA SIENTA HYBRID  
DATE OF ACCIDENT : 17 JUN 2019  
YOUR INSURED VEHICLE NUMBER : GBC2498C

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

	<u>PARTS DISCRPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER / <i>NR</i>	1PC	\$450.00	\$450.00 /
2	FRONT BUMPER SIDE RETAINER / <i>NR</i>	1PC	\$120.00	\$120.00 /
3	FRONT BUMPER FOG LAMP GARNISH / <i>RVT</i>	1PC	\$144.00	\$144.00 /
4	FRONT BUMPER SIDE BRACKET / <i>M/S</i>	1PC	\$75.00	\$75.00 /
5	HEADLAMP RH / <i>NR</i>	1PC	\$990.00	\$990.00 /
6	HEADLAMP PANEL RH / <i>Q x R</i>	1PC	\$175.00	\$175.00 X
7	FRONT FENDER RH / <i>NR</i>	1PC	\$540.00	\$540.00 /
8	FRONT FENDER EMBLEM / <i>M/C</i>	1PC	\$45.00	\$45.00 /
9	FRONT FENDER INNER SHIELD / <i>CR4</i>	1PC	\$225.00	\$225.00 /
10	BONNET X <i>R</i>	1PC	\$570.00	\$570.00 X
11	BONNET HINGE X <i>M/I</i>	1PC	\$96.00	\$96.00 X

LIST TOTAL S\$:	\$3,430.00	<i>2589</i>
25.00% DISCOUNT S\$:	\$857.50	<i>-25%</i>
	\$2,572.50	<i>1941.75</i>

**SPECIAL NETT**

1	FRONT BUMPER CLIP <i>APC</i>	1 SET	\$35.00	<i>30</i>
2	FRONT FENDER INNER SHIELD CLIP <i>11"</i>	1 SET	\$35.00	<i>20</i>

Special Nett Total S\$:       \$70.00       *50*

**LABOUR CHARGES**

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.FRONT FENDER ,FRONT HEADLAMP PANEL,BONNET	\$1,200.00	<i>550</i>
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)FRONT FENDER,FRONT BUMPER,HEADLAMP PANEL	\$1,200.00	<i>600</i>
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO	\$120.00	<i>70</i>
4	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS.	\$100.00	<i>* 70</i>
5	TO CONDUCT ALL WHEEL ALIGNMENT CHECK	\$120.00	<i>300</i>

LABOUR TOTAL S\$:	<u>      \$2,740.00      </u>	<i>1270</i>
TOTAL S\$:	\$5,382.50	
7% GST	\$376.78	
GRAND TOTAL S\$:	<u>      \$5,759.28      </u>	

*Steve (LKK)*  
*8322 8813*  
*Stevecho@lkkaut.com*

*incl. include 26/6/19, 2.00 pm*  
*5 # days*  
~~*48*~~ *P/P*  
*Ry # spy*  
*Beh*

Prepared By : -  
 Henry Ng  
 Motor Claims  
 TEL: 62524991  
 EMAIL: henry@lioncityrentals.com.sg

*P-1941.75*  
*A1-50*  
*L-1279*  
*P/P-3261.75*

LCRF PTE LTD  
 CARROS CENTER  
 60 JALAN LAM HUAT #04-01 S(737869)  
 Main +65 62524991

**Axa Insurance**

8 Shenton Way, #24-01 AXA Tower,  
 Singapore 068811  
 Tel:

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLL9232H  
 CHASSIS NO : NHP1707067354  
 MAKE / MODEL : TOYOTA SIENTA HYBRID  
 DATE OF ACCIDENT : 17 JUN 2019  
 YOUR INSURED VEHICLE NUMBER : GBC2498C

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER / <i>NR</i>	1PC	\$450.00	\$450.00
2	FRONT BUMPER SIDE RETAINER / <i>NR</i>	1PC	\$120.00	\$120.00
3	FRONT BUMPER FOG LAMP GARNISH / <i>CVT</i>	1PC	\$144.00	\$144.00
4	FRONT BUMPER SIDE BRACKET / <i>MIS</i>	1PC	\$75.00	\$75.00
5	HEADLAMP RH / <i>NR</i>	1PC	\$990.00	\$990.00
6	HEADLAMP PANEL RH / <i>NR</i>	1PC	<del>\$175.00</del>	<del>\$175.00</del>
7	FRONT FENDER RH / <i>NR</i>	1PC	\$540.00	\$540.00
8	FRONT FENDER EMBLEM / <i>MIC</i>	1PC	\$45.00	\$45.00
9	FRONT FENDER INNER SHIELD / <i>CR4</i>	1PC	\$225.00	\$225.00
10	BONNET / <i>X R</i>	1PC	<del>\$570.00</del>	<del>\$570.00</del>
11	BONNET HINGE / <i>X</i>	1PC	<del>\$96.00</del>	<del>\$96.00</del>

LIST TOTAL S\$: \$3,430.00 *2589*  
 25.00% DISCOUNT S\$: \$857.50  
 \$2,572.50 *1941.75*

**SPECIAL NETT**

1	FRONT BUMPER CLIP <i>Mc</i>	1 SET	\$35.00	<i>30 /</i>
2	FRONT FENDER INNER SHIELD CLIP <i>Mc</i>	1 SET	\$35.00	<i>20 /</i>

Special Nett Total S\$: ----- \$70.00 *50*

**LABOUR CHARGES**

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.FRONT FENDER ,FRONT HEADLAMP PANEL,BONNET	\$1,200.00	<i>550</i>
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)FRONT FENDER,FRONT BUMPER,HEADLAMP PANEL	\$1,200.00	<i>600</i>
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO	\$120.00	<i>70</i>
4	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS.	\$100.00	<i>20 / 30</i>
5	TO CONDUCT ALL WHEEL ALIGNMENT CHECK	\$120.00	<i>200</i>

LABOUR TOTAL S\$: ----- \$2,740.00 *1270*  
 TOTAL S\$: \$5,382.50  
 7% GST \$376.78  
 GRAND TOTAL S\$: ----- \$5,759.28

*Stev (LKK)*  
*8322 8813*  
*Stevchen@lkkaut.com*

*mil Mr/ndu 26/6/19, 2.00 pm 3261.75*  
*5 days*  
*PIB*  
*Ry At sy*  
*Beh*

Prepared By :-  
 Henry Ng  
 Motor Claims  
 TEL: 62524991  
 EMAIL: henry@lioncityrentals.com.sg

*parts 2,589.00*  
*len 253 647.25*  
*SN 1,941.75*  
*50.00*  
*Labu 1,270.00*  
*Med 3,261.75*

*PIB 3261.75*  
*2,600.00*