



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLM 3077 Z

*Not Authorized
Performing B4 painting*

Parts	(a) Cost / List Price Items	\$	2,639.00
	Plus/Less 25%	\$	659.75
	Total of Cost / List	\$	1,979.25
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	2,179.25
Labour		\$	1,470.00
Total		\$	3,649.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 26/8/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : De Date: 26/8/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLM 3077 Z**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU303554064**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	1	\$200.00	S.N	X
2	Rear bumper <i>Bul / Sn</i>	1	\$497.50		✓
3	Rear bumper clip <i>Sn</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>Sn</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70		X
6	Rear bumper reinforcement <i>Sn</i>	1	\$398.90		X
7	Rear bumper lower garnish centre <i>Del / Sn</i>	1	\$582.60		✓
8	Rear bumper lower garnish RH <i>Bul / Sn</i>	1	\$149.70		✓
9	Rear bumper tow cover <i>Sn</i>	1	\$31.70		X
10	Rear bumper under cover RH <i>Sn</i>	1	\$187.60		X
11	Rear bumper under cover clip <i>nn</i>	4	\$14.00		X
12	Tail lamp RH - LOWER <i>nn</i>	1	\$511.60		X
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

