

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 553U

AAD1906-218

*Not Authorized
11 Sep 8 1500*

23 JUN 2019

Vehicle No.:	SHF 553U
Chassis No.:	VF1ABL15AUC278401
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	24.6.19
Third Party Insurer :	AXA
Date of Registration :	20/6/2014

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>n</i> 1,108.46 X
2	1 BUMPER LOWER REAR	\$	<i>nd/111</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>sn</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>sn</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	<i>sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>sn</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>B1</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95
13	1 OUTER PANEL REAR (End Panel)	\$	<i>n</i> 1,471.77
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>sn</i> 404.56
15	1 TAILLAMP RH	\$	<i>sn</i> 552.55
16	1 TAILLAMP PANEL RH	\$	<i>n</i> 986.70
17	1 TAILLAMP LH	\$	<i>sn</i> 552.55
18	1 TAILLAMP PANEL LH	\$	<i>n</i> 986.70
19	1 BOOT REAR	\$	<i>n</i> 2,872.68
20	1 BOOT FINISHER	\$	<i>sn</i> 470.06
21	1 BOOT WHEATERSTRIP	\$	<i>sn</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>sn</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	<i>sn</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36
25	1 BOOT BADGE	\$	<i>na</i> 225.36
26	1 BOOT STRUT LH	\$	<i>sn</i> 276.08
27	1 BOOT STRUT RH	\$	<i>sn</i> 276.08
28	1 BOOT HINGE LH	\$	<i>n</i> 367.84
29	1 BOOT HINGE RH	\$	<i>n</i> 367.84
30	1 BOOT INNER TRIM	\$	<i>sn</i> 586.45

Trans-cab Auto Services Pte Ltd

AAD1906-218

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 553U

31	1	BOOT SWITCH	\$	SL	168.13	X
32	1	BOOT LOCK	\$	n	202.67	X
33	1	BOOT LOCK CATCH	\$	n	74.40	X
34	1	EXHAUST REAR	\$	n	7,489.05	X
35	1	EXHAUST CAP REAR	\$	n	230.49	X
TOTAL			\$		23,766.42	
			10%	\$	2,376.64	
			\$		21,389.78	

Special Nett

1	1SET	PARKING AID	\$	SL	700.00	}
2	1SET	REAR BUMPER CLIP	\$	na	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	}
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	1	EXHAUST MOUNTING REAR	\$	na	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
14	1	WINDSCREEN MOULDING	\$	na	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
16	1	BOOT INNER TRIM CLIP	\$	na	45.00	
17	1SET	BOOT FINISHER CLIP	\$	na	24.20	
18	1	TAILLAMP CLIP LH	\$	na	5.00	
19	1	TAILLAMP CLIP RH	\$	na	5.00	
TOTAL			\$		1,384.02	

TOTAL PARTS \$ 22,773.80**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	10/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1906-218

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 553U

To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	<i>2001</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	<i>2201</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	X

TOTAL \$ 11,890.00

Over All Total \$ 34,663.80

LUMP SUM (REPAIR DAY)

15-DAYS

2 days

LKK Auto Consultants hence notified to the car of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer/Company

Acknowledged by Repairer
Signature:
Date: