

22032003

ASS. REC. BY:

REF: CS/FC119011371/TIad302

Special Instruction:

Surveyor: Tan Hui

CWS

ASSIGNMENT (Office)

From (Person): Hennykao

of FCI

Date/Time: 26/6/19 @ 5.52pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLZ 5644E

Insured: SHC 78362

at Workshop m/s

Ethoz Group

Tel: 88226339

of

30 Bukit Barok Crescent

Policy No:

Claim No: D19004126MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30/5/2019

CA / REV / REP. / REV 24 HRS

Date/Time: 9.58am @ 27/6/19

Person Contacted: Mr. Lee

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction
	Inspected ✓
	SHC 78362 : X
	SLZ 5644E : X
<u>26/6/19 @ 7.39pm</u>	<u>revised to Hennykao by email</u>

No.
photo
upload
28/6

Taufik

FCI

CL 2564E

2018 May

Toyota 4 His
Grey

1598

1278

MR053REM604581684

20/6/2015

07

7

7

2

27/6/2015 4pm

Elko 3 BR

RECEIVED 04 JUL 2019

4/7/19 \$2190.57, 4 days (led to 1669.08, 43%)

04/7/2019

Rec'd Report
Final Report

Days Of Repair

Recovery No. of Trip

Add Exp:

Sub. Exp:

Sub. Exp:

Sub. Exp:

Sub. Exp:

130
50
50
32

262

Report Form

TP

2190.57



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004126MFSH

Date: 28 June 2019

Our Ref: CS/FCI19011371/T1qd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLZ 5644E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/06/2019 at the premises of M/s ETHOZ, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,859.65</u> .
Revised Estimate Amount	: S\$ <u>2,190.58</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the o/s portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-06-2019	Our Ref No. D19004126MFSH
Accident Date	30-05-2019	Claim Type. Third Party
Insured Vehicle	SHC7836Z	Third Party Vehicle. SLZ5644E
Survey Location	30 BUKIT BATOK CRESCENT	
Contact Person.	LEE CHEN SIN	
Contact No.	66547520/ 88228339	Fax No. 66547542
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ETHOZ GROUP LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 28 June 2019 2:39 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004126MFSH/1
Attachments: CSFCI19011371T1qd3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SLZ 5644E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 27 June 2019 10:04 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004126MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 26 June 2019 5:52 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004126MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000052

Accident Date : 30/05/2019

Vehicle No : SLZ-5644-E

Make & Model : TOYOTA COROLLA ALTIS 1.6 STANDARD (A)


ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	FRONT FENDER RH	RESTORE Ky	
1	FRONT FENDER EMBLEM RH	40.00	Xnn
1	FRONT DOOR RH	1,078.60	bt
1	FRONT DOOR HINGE RH (UPPER)	75.50	bt
1	FRONT DOOR HINGE RH (LOWER)	75.50	Ky
1	FRONT DOOR STICKER RH (SET)(BLACK)	78.20	nn
1	REAR DOOR RH	1,069.20	Ky
1	REAR DOOR HINGE RH (UPPER)	75.50	Ky
1	REAR DOOR HINGE RH (LOWER)	75.50	Ky



Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000052

Accident Date : 30/05/2019

Vehicle No : SLZ-5644-E

Make & Model : TOYOTA COROLLA ALTIS 1.6 STANDARD (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR DOOR STICKER RH (SET)(BLACK)	78.20	X m.
1	ROCKER PANEL RH	RESTORE RY	
1	REAR FENDER RH	RESTORE RY	1154.10.
	Sub Total	2646.20	865.57.
	Discount 25% On Parts	(661.55)	
	Labour & Misc		
	LABOUR TO FACILIATE REPAIR	600.00	460-
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	✓
	TO SPRAY PAINT ON AFFECTED AREAS	1,000.00	800-
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	30-

Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000052 Accident Date : 30/05/2019

Vehicle No : SLZ-5644-E Make & Model : TOYOTA COROLLA ALTIS 1.6 STANDARD (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO TRANSFER FRT DOOR RH FITTING	100.00	60
	TO TRANSFER REAR DOOR RH FITTING	100.00	X nn
	Sub Total	1875.00	1325

\$2190.57
4 days

Remarks:

SUB TOTAL

GST 7.0 %

TOTAL

3,859.65

270.18

4,129.83

Surveyor's name:

Tanjik 97455749

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 27/6/19 @ 4pm

Resumy before paint
4 days
sure/kanan

Date : 03/07/2019
To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D19MTRENT000052 Accident Date : 30/05/2019
Vehicle No : SLZ-5644-E Make & Model : TOYOTA COROLLA ALTIS 1.6 STANDARD (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	FRONT FENDER RH RESTORE	0.00	0.00
1	FRONT FENDER EMBLEM RH	40.00	0.00
1	FRONT DOOR RH	1078.60	1078.60
1	FRONT DOOR HINGE RH (UPPER)	75.50	75.50
1	FRONT DOOR HINGE RH (LOWER)	75.50	0.00
1	FRONT DOOR STICKER RH (SET)(BLACK)	78.20	0.00
1	REAR DOOR RH	1069.20	0.00
1	REAR DOOR HINGE RH (UPPER)	75.50	0.00
1	REAR DOOR HINGE RH (LOWER)	75.50	0.00
1	REAR DOOR STICKER RH (SET)(BLACK)	78.20	0.00
1	ROCKER PANEL RH RESTORE	0.00	0.00
1	REAR FENDER RH RESTORE	0.00	0.00



Date : 03/07/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000052 Accident Date : 30/05/2019

Vehicle No : SLZ-5644-E Make & Model : TOYOTA COROLLA ALTIS 1.6 STANDARD (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	2646.20	1154.10
	Discount <u>25%</u> On Parts	(0.00)	(288.52)
	<u>Labour & Misc</u>		
	LABOUR TO FACILIATE REPAIR	600.00	400.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	35.00
	TO SPRAY PAINT ON AFFECTED AREAS	1000.00	800.00
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	30.00
	TO TRANSFER FRT DOOR RH FITTING	100.00	60.00
	TO TRANSFER REAR DOOR RH FITTING	100.00	0.00
	Sub Total	1875.00	1325.00

PAGE: 2



Date : 03/07/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000052 Accident Date : 30/05/2019

Vehicle No : SLZ-5644-E Make & Model : TOYOTA COROLLA ALTIS 1.6 STANDARD (A)

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	3,859.65	2,190.57
	GST 7.0 %	270.18	153.34
	Total	4,129.83	2,343.92

COR: \$ 2,190.57 (PART BY PART)

4 days repair

Surveyor Name : TAUFIK - LKK

Date & Time : 27/06/2019 4:00:00 PM

Lee Chen Sin

CLAIM DEPARTMENT

DID : 66547520

FAX :

PARTS - \$ 1,154.10 - 25%

- \$ 865.57

LABOUR - \$ 1,325.00

\$ 2,190.57

PAGE : 3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19011371/T1qd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7836Z	Veh. Inspected	SLZ 5644E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004126MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	26/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MR053REH604581684	Colour	GREY	
Odometer	1278	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	YOKOHAMA	7 mm	
L/H Front Tyre	205/65 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	205/65 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	205/65 R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/05/2019	Inspection Date	27/06/2019	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 5644E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER EMBLEM RH	NOT NECESSARY	40.00	-
1	FRONT DOOR RH	BENT	1,078.60	1,078.60
1	FRONT DOOR HINGE RH (UPPER)	BENT	75.50	75.50
1	FRONT DOOR HINGE RH (LOWER)	TO REPAIR SEE LABOUR	75.50	-
1	FRONT DOOR STICKER RH (SET)(BLACK)	NOT NECESSARY	78.20	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,069.20	-
1	REAR DOOR HINGE RH (UPPER)	TO REPAIR SEE LABOUR	75.50	-
1	REAR DOOR HINGE RH (LOWER)	TO REPAIR SEE LABOUR	75.50	-
1	REAR DOOR STICKER RH (SET)(BLACK)	NOT NECESSARY	78.20	-
1	ROCKER PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-661.55	-288.53
			1,984.65	865.57
LABOUR				
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH, FRONT DOOR HINGE RH (LOWER), REAR DOOR RH, REAR DOOR HINGE RH (UPPER), REAR DOOR HINGE RH (LOWER), ROCKER PANEL RH AND REAR FENDER RH.		600.00	400.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		35.00	35.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,000.00	800.00
	SPRAY RUST PROOF ON AFFECTED AREA.		40.00	30.00
	TO TRANSFER FRT DOOR RH FITTING.		100.00	60.00
	TO TRANSFER REAR DOOR RH FITTING.	NOT NECESSARY	100.00	-
			1,875.00	1,325.00

Report Ref No. CS/FCI19011371/T1qd3n2



GRAND TOTAL		3,859.65	2,190.57
RECOMMENDED COST OF REPAIRS			2,190.57

Report Ref No. CS/FCI19011371/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.