

KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 FAX : 64550902

The Motor Claims Dept.
AXA Insurance Pte Ltd

Not withash
11 Sep @ ?
Resurvey After Paint

DATE : 06/26/2019
VEHICLE NO : SJC 853X
MAKE/MODEL : Toyota Axio
ACC DATE : 05/31/2019

ESTIMATE

S/N	PC	List Items	Page . 1 .	AMOUNT S\$
1	1	Front RH door		<i>1000</i> 1,090.10 ✓
2	2	Front RH Door Hinges @\$70.40		<i>1000</i> 140.80 ✓
3	1	Front RH door inner lock		<i>1000</i> 632.40 X
4	1	Front Rh door weatherstrip		<i>1000</i> 172.40 X
5	1	Front RH door galss regulator		199.50 ?
6	1	Front RH door regulator motor		542.10 ?
7	1	Front RH door inner board		845.50 ?
8	1	Fromt RH door outer handle		<i>1000</i> 155.40 X
9	1	Front RH door quarter panel		<i>1000</i> 1,050.40 X
10	1	Front RH door mirror complete		<i>1000</i> 824.10 X
11	1	Fromt RH rocker panel garnish		<i>1000</i> 731.50 X
12	1	Front RH fender		<i>1000</i> 524.10 ✓
13	1	Front RH fender iner shield		<i>0.1</i> 271.50 ✓
14	1	Front RH fender light		<i>1000</i> 72.40 X
15	1	Fronjt RH center door pillar		<i>1000</i> 721.50 X
				7,973.70
Less 25%				(1,993.42)
				5,980.28

Special Items

1	1	Front RH door inner board clips (1set)	<i>ne</i>	25.00	✓
2	2	Front RH fender inner shield clips (1set)	<i>ne</i>	25.00	✓
				50.00	

Labour Charges

1	To remove and fix front door mechanism	150.00 <i>600</i>
2	To check up electrical wiring	80.00 <i>200</i>
3	Anti rust	100.00 <i>600</i>
4	To respray painting & etc	1,200.00 <i>7200</i>
5	Panel beat, remove and replacing above parts	1,200.00 <i>6000</i>
		2,730.00

Total Repair Cost

LKK Auto Consultants hence notify the Repairer of the following: **8,760.28**

(S/DLS : Eight Thousand Seven hundred sixty and cents twenty-eight only.)



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: