

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5478L**AAD1906-226***Not Authorized*
1/Sup &

26 JUN 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5478L

VF1ABL15AUC280962

RENAULT

LATITUDE

24.6.19

TOKIO MARINE

18/12/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	2,844.66
1	DOOR GUIDE REAR RH	\$	176.82
1	DOOR HINGE UPPER RH	\$	274.50
1	DOOR HINGE LOWER RH	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	203.06
1	DOOR CASING REAR RH	\$	1,509.06
1	DOOR WHEATHESTRIIP REAR RH	\$	410.66
1	DOOR SEAL REAR RH	\$	162.02
1	DOOR PANEL FRT RH	\$	2,844.66
1	DOOR CHECK FRT RH	\$	194.77
1	DOOR LOCK FRT RH	\$	908.75
1	DOOR CATCH FRT RH	\$	131.23
1	DOOR HANDLE OUTER FRT RH	\$	477.76
1	DOOR HANDLE COVER FRT RH	\$	13.22
1	DOOR HANDLE MODULE FRT RH	\$	133.60
1	DOOR REGULATOR FRT RH	\$	505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	120.97
1	DOOR WHEATHESTRIIP FRONT RH	\$	410.66
1	DOOR CASING FRONT RH	\$	1,509.06
1	DOOR BLIND FRONT RH	\$	741.80
1	DOOR SEAL FRONT RH	\$	162.02
1	DOOR GLASS RUNNER SEAL FRONT RH	\$	229.31
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	ROCKER PANEL CENTER RH	\$	990.25
1	DOOR MIRROR ASSY RH	\$	1,483.40
1	DOOR HARNESS WIRE RH	\$	2,670.00

Trans-cab Auto Services Pte Ltd**AAD1906-226**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5478L

TOTAL	\$	22,880.74
10%	\$	2,288.07
	\$	20,592.66

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	na	300.00	X
1	FRONT DOOR STICKER 'Trans-Cab'	\$	na	80.00	60na
1	FRONT DOOR STICKER 'Classic'	\$	na	80.00	15na
1	DOOR CHECK BOLT	\$	na	22.69	X
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
1	FRONT RIGHT TYRE	\$	na	300.00	
1	FRONT RIGHT TYRE RIM	\$	na	380.00	
1	FRONT WINDSCREEN SEALANT	\$	na	253.80	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1	FRONT WINDSCREEN MOULDING	\$	na	120.00	
TOTAL		\$		1,715.43	

TOTAL PARTS	\$	22,308.09
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	6,000.00	2001
----	----------	------

To check steering geometry and computer wheel alignment

\$	na	220.00	X
----	----	--------	---

To transfer of front windscreen fittings and conduct water seepage test.

\$	na	170.00	X
----	----	--------	---

Putty and spray painting of the affected portion.

\$	6,000.00	2201
----	----------	------

Trans-cab Auto Services Pte Ltd

AAD1906-226

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5478L

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	<i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>
To transfer of Front door fittings, attachment and perform water seepage test.	\$		380.00	<i>601</i>
To rust-proofing of the affected areas.	\$		170.00	<i>301</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i>	380.00	<i>X</i>
TOTAL	\$		14,800.00	
Over All Total	\$		37,108.09	

LUMP SUM (REPAIR DAY)**~~20~~ DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--