

2/00/2001

ASS. REC. BY:

REF: CS/CTI19011389109d3n2

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Chong Sun Sen

of CTI

Date/Time: 27/6/19 @ 9:20am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 9806P

Insured:

SKL 8946A

at Workshop m/s

Hock Wah Motor

Tel:

6441 5655

of

Blk 3011, Bedok North Ave 4 # 01-2008

Policy No:

mpc 30958619011

Claim No:

SNM19D26231402

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11am @ 27/6/19

Person Contacted:

Anyora

Vehicle IN/OUT

Date/Time	Action/Instruction
	SKL 8946A: X
	SKL 9806P: X
19/6/19 @ 3:40pm	Anyora said they still waiting for CTI issue liability.

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

CT1/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKL 986P
at Workshop m/s hockwale
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 15.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKL 986P Yr Regn: 1.14
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Mer Benz C200 C.C. 1796
Colour: Brown A/C: Insured / Std / NI / NA
Sp. Reading: 55387 T/Radio: Insured / Std / NI / NA
Eng/No: WDD2040482.A905298
C/No: _____
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 245/40R17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 16/5/19 D.O.I. 23/9/19
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
9/5 Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/10/19 17A 69510
Confund final by 760 wth Any. & Labours Only
no lump sum
Red 4828, 867.2
9/10/2019

RECEIVED 09 OCT 2019

Date/Time, File Pass to?

09/10 turner

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 760

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee:

☐ Site Insp (\$ _____) ☐ S + RS \$ _____
☐ Interview (\$ _____) ☐ Photos
☐ Tech. Invs (\$ _____) ☐ Others
☐ Weekend (\$ _____)

Survey Fee:

Transportation:

TOTAL

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 27 June 2019 9:21 AM
To: Hock Wah Motor Pte Ltd
Cc: assignments
Subject: RE: our ref: snm19d202314 / tp claim skl9806p and skl8946a doa: 16.5.19

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Hock Wah Motor Pte Ltd [mailto:motor@hockwah.com.sg]
Sent: Thursday, 27 June, 2019 9:15 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: our ref: snm19d202314 / tp claim skl9806p and skl8946a doa: 16.5.19

Dear Boon Sen

We would like to appoint Marcus Chua to survey above mention vehicle.

Please revert on liability matter for above mention claim.

Thank you.

Best Regards

Anysia Foo

Senior Claims Advisor

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 27 June, 2019 9:11 AM
To: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>
Subject: our ref: snm19d202314 / tp claim skl9806p and skl8946a doa: 16.5.19

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6366171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	156F
Vehicle Details	
Vehicle No.:	SKL9806P
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 SEDAN EDITION C (R17)
Primary Colour:	Brown
Manufacturing Year:	2013
Engine No.:	27186030703406
Chassis No.:	WDD2040482A905298
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$42,039.00
Original Registration Date:	15 Jan 2014
First Registration Date:	15 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$50,855.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jan 2024
PARF Rebate Amount:	\$35,598.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$78,700.00
COE Rebate Amount:	\$33,912.00
Total Rebate Amount:	\$69,510.00

The information contained herein is correct as at 23 Sep 2019

OK

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

#7601

TO : SXXX6156F
FOO CHEW HONG
NO

SINGAPORE
TEL : FAX :
PH : 85698220
ATTN :

*not allowed
Lak
take the Affair
24.
23/9/19*

ESTIMATE BILL

Number : EB00005200
Date : 26/06/2019
Case No : AD00010518
Vehicle No : SKL9806P
Chassis : WDD2040482A905298
Year of Mfr : 2013
Policy No : 5106963441
Model : MERCEDES BENZ
C200 SEDAN

Term:

Sn	DESCRIPTION	QTY	U PRICE	EDITION C (RT)	AMOUNT
1	REAR BUMPER	1.0	1,570.00	0	1,570.00
2	REAR BUMPER RETAINER RH	1.0	44.00	0	44.00
3	REAR BUMPER RETAINER LH	1.0	44.00	0	44.00
4	REAR WHEEL HUB BEARING RH	1.0	220.00	0	220.00
Nett Price - Parts Sub Total					1,878.00
5	REAR WHEEL RIM RH	1.0	900.00	0	900.00
6	REAR TYRE LH	1.0	580.00	0	580.00
7	REAR DOOR RH - REPAIR	1.0			
8	REAR FENDER RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					1,480.00
Parts Total					3,358.00
9	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
10	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
11	ANTI-RUST COATING	1.0	150.00	0	150.00
12	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
13	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
14	TO REMOVE & REFIT UNDERCARRIAGE	1.0	350.00	0	350.00
Labour 1 Sub Total					2,230.00
SINGAPORE DOLLARS : FIVE THOUSAND NINE HUNDRED SEVENTY-NINE AND CENTS SIXTEEN ONLY			Less Excess		0.00
			SUBTOTAL		5,588.00
			GST 7.00%		391.16
			TOTAL		5,979.16

Date of accident : 16/05/2019 05:00 PM. Place : JALAN ANGIN LAUT/GAN SOON AVE

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011389/UQD3N2

Date: 10/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30958619011
Claimant Vehicle No :	SKL9806P	Insured Vehicle No :	SKL8946A
Date of Loss:	16/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202314C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL9806P	Engine No:	27186030703406
Make & Model:	MERCEDES-BENZ C200, 1.8 (A)	Chassis No:	WDD2040482A905298
Reg. Date:	15/01/2014 (Man. Year: 2013)	Odometer:	55387 km
Colour:	Brown		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R17	Rear Tyre Size:	245/40R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,358.00	0.00	3,358.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	760.00	1,470.00	65.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,588.00	760.00	4,828.00	86.40
+ GST 7.00/7.00% (S\$)	391.16	53.20	337.96	86.40
Nett Amount (S\$)	5,979.16	813.20	5,165.96	86.40

INSPECTION

Date of Assignment: 24/09/2019

Date Inspected: 23/09/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2019)
Parts: 143	MERCEDES-BENZ C200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL9806P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,570.00 FS	*- FS
2	1		*REAR BUMPER RETAINER RH	Not Necessary	44.00 FS	*- FS
3	1		*REAR BUMPER RETAINER LH	Not Necessary	44.00 FS	*- FS
4	1		*REAR WHEEL HUB BEARING RH	Not Necessary	220.00 FS	*- FS
5	1		*REAR WHEEL RIM RH	Repair	900.00 FS	*- FS
6	1		*REAR TYRE RH	Serviceable	580.00 FS	*- FS
7	1		*REAR DOOR RH (NPA)	Not Necessary	0.00 FS	*- FS
8	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 3,358.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	600.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	400.00
3	ANTI-RUST COATING	New	150.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	0.00
5	FOUR WHEEL ALIGNMENT	New	180.00	60.00
6	TO REMOVE & REFIT UNDERCARRIAGE	New	350.00	0.00
Gross Labour Cost (\$\$)			2,230.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >