

# SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLP738D/1906089

26<sup>th</sup> June 2019

The Manager  
Motor Claim Department  
AIG Asia Pacific Insurance Pte Ltd  
CHARTIS Building  
78 Shenton Way #07-16  
Singapore 079120

rest Abdul  
ah  
Shirley  
2 day.  
P/P \$ 350/-

Date of Accident : 22th June 2019

Location : New Upper Changi Road (Bedok Mall)

Third Party Claim Vehicle No : SMD7067L

Repair Cost For Vehicle No : SLP738D (Renault Megane)

## Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	RR Bumper Fascia	1	600.00	\$ 600.00
2	RR Bumper Clips	1 set	50.00	\$ 50.00
				\$ 650.00

## Labour Charges :-

	Amounts
Remove & re-fix, renew, knocking & welding rear bumper, fascia, straighten & re-align body	\$ 420.00 /50
Spray painting on damage parts	\$ 400.00 200
Check all lighting after repairs	11 \$ 30.00 X
Labour Charge	\$ 850.00
Total Amount	\$ 1,500.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: