

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 127C

AAD1906-224

Not Authorized
1/1 Smp &

26 JUN 2019

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHD 127C
VF1ABL15AUC282228
RENAULT
LATITUDE
25.6.19
AIG
21/8/2015

	PART		LIST	
1	DOOR PANEL REAR LH	\$	<i>B1</i> 2,844.66	✓
1	DOOR GUIDE REAR LH	\$	<i>Su</i> 176.82	}
1	DOOR HINGE UPPER LH	\$	<i>M</i> 274.50	
1	DOOR HINGE LOWER LH	\$	<i>M</i> 300.55	
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Su</i> 203.06	
1	DOOR LOCK REAR LH	\$	<i>M</i> 908.75	
1	DOOR HANDLE OUTER REAR LH	\$	<i>Su</i> 126.49	
1	DOOR HANDLE CAP REAR LH	\$	<i>Su</i> 35.52	
1	DOOR HANDLE SEAL REAR LH	\$	<i>Su</i> 7.89	
1	DOOR HANDLE COVER REAR LH	\$	<i>Su</i> 13.22	
1	DOOR HANDLE MODULE REAR LH	\$	<i>Su</i> 133.60	
1	DOOR REGULATOR REAR LH	\$	1,135.10	7
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75	7
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Su</i> 12.43	}
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Su</i> 6.31	
1	DOOR FINISHER REAR LH	\$	<i>Su</i> 423.10	
1	DOOR MOULDING REAR LH	\$	<i>Su</i> 176.82	
1	DOOR MOULDING CLIP L70Y	\$	<i>na</i> 5.92	
1	DOOR MOULDING SCREW L70Y	\$	<i>Su</i> 6.91	
1	DOOR CASING REAR LH	\$	<i>Su</i> 1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	<i>Su</i> 30.39	
1	DOOR CASING CLIP	\$	<i>na</i> 12.63	
1	DOOR CASING LIGHT L70Y	\$	<i>na</i> 48.74	
1	DOOR FINISHER INNER REAR LH	\$	<i>Su</i> 323.44	}
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>M</i> 46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>M</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>M</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>M</i> 20.33	
1	DOOR GRAB HANDLE REAR LH	\$	<i>Su</i> 210.96	
1	DOOR BLIND REAR LH	\$	<i>Su</i> 741.80	

Trans-cab Auto Services Pte Ltd

AAD1906-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 127C

1	DOOR WHEATHESTRIIP REAR LH	\$	S ₂	410.66	X
1	DOOR SEAL REAR LH	\$	S ₂	162.02	X
1	DOOR GLASS RUNNER SEAL REAR LH	\$	S ₂	229.31	X
1	DOOR WAIST SEAL OUTER REAR LH	\$	S ₂	334.69	X
1	DOOR WAIST SEAL INNER REAR LH	\$	S ₂	115.64	X
1	DOOR PANEL FRT LH	\$	B ₂	2,844.66	✓
1	DOOR CHECK FRT LH	\$	S ₂	194.77	} X
1	DOOR LOCK FRT LH	\$	R	908.75	
1	DOOR CATCH FRT LH	\$	R	131.23	
1	DOOR HANDLE OUTER FRT LH	\$	S ₂	477.76	
1	DOOR HANDLE COVER FRT LH	\$	S ₂	13.22	
1	DOOR HANDLE MODULE FRT LH	\$	S ₂	133.60	
1	DOOR REGULATOR FRT LH	\$	R	505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	R	796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	S ₂	120.97	
1	DOOR MOULDING FRONT LH	\$	S ₂	176.82	
1	DOOR FINISHER FRONT LH	\$	S ₂	423.10	
1	DOOR CASING FRONT LH	\$	S ₂	1,509.06	
1	DOOR BLIND FRONT LH	\$	S ₂	741.80	
1	DOOR WHEATHESTRIIP FRONT LH	\$	S ₂	410.66	
1	DOOR SEAL FRONT LH	\$	S ₂	162.02	
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	S ₂	229.31	
1	DOOR WAIST SEAL OUTER FRONT LH	\$	S ₂	334.69	
1	DOOR WAIST SEAL INNER FRONT LH	\$	S ₂	115.64	
1	ROCKER PANEL INNER GARNISH LH	\$	S ₂	466.51	
1	ROCKER PANEL INNER LH	\$	R	1,024.79	
1	ROCKER PANEL OUTER LH	\$	R	1,184.99	
1	ROCKER PANEL CENTER LH	\$	R	990.25	
1	DOOR MIRROR ASSY LH	\$	R	1,483.40	
1	DOOR HARNESS WIRE LH	\$	S ₂	2,670.00	
1	FENDER PANEL REAR LH	\$	B ₂	3,299.13	✓
1	FENDER PANEL INNER TRIM REAR LH	\$	S ₂	671.45	X
1	WHEELARCH REAR LH	\$	S ₂	543.47	X
1	TAILLAMP LH	\$	S ₂	552.55	X
1	TAILLAMP PANEL LH	\$	R	986.70	X
1	BUMPER COVER REAR	\$	B ₂	1,108.46	✓
1	BUMPER LOWER REAR	\$	S ₂	768.84	X
1	BUMPER BRACKET CTR REAR	\$	S ₂	113.47	X

Trans-cab Auto Services Pte Ltd

AAD1906-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 127C

1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sc</i> 135.97	X
1	BUMPER RETAINER LH REAR	\$	<i>Sc</i> 44.99	X
1	BUMPER REFLECTOR LH	\$	<i>Sc</i> 43.61	X
1	BUMPER BEAM REAR	\$	<i>n</i> 777.52	X
1	BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95	X
TOTAL		\$	39,244.47	
		10% \$	3,924.45	
		\$	35,320.02	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>n</i> 100.00	<i>60sa</i>
1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>n</i> 80.00	<i>60sa</i>
1	FRONT DOOR STICKER 'Classic'	\$	<i>n</i> 80.00	<i>15sa</i>
1	DOOR CHECK BOLT	\$	<i>Sc</i> 22.69	} X
1	DOOR GUIDE SCREW	\$	<i>Sc</i> 10.85	
1	DOOR HINGE BOLT	\$	<i>Sc</i> 10.85	
1	DOOR HINGE NUT LH	\$	<i>Sc</i> 14.60	
1	DOOR CHECK NUT	\$	<i>Sc</i> 3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>Sc</i> 6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>Sc</i> 10.06	
1	REAR LEFT TYRE	\$	<i>Sc</i> 300.00	
1	REAR LEFT TYRE RIM	\$	<i>Sc</i> 380.00	
1	FRONT LEFT TYRE	\$	<i>Sc</i> 300.00	
1SET	WHEELARCH CLIP FRT LH	\$	<i>Sc</i> 30.50	
1	FENDER INNER TRIM CLIP LH	\$	<i>n</i> 28.00	
1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>n</i> 35.00	
1	FRONT LEFT TYRE RIM	\$	<i>Sc</i> 380.00	
2	REAR WINDSCREEN SEALANT	\$	<i>n</i> 80.00	
1	REAR WINDSCREEN MOULDING	\$	<i>n</i> 120.00	✓
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>n</i> 100.00	<i>30sa</i>
1	TAILLAMP CLIP LH	\$	<i>n</i> 5.00	X
1SET	PARKING AID	\$	<i>Sc</i> 700.00	X
1SET	REAR BUMPER CLIP	\$	<i>n</i> 66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	<i>n</i> 33.00	✓
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>n</i> 10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>n</i> 20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	<i>n</i> 22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	<i>n</i> 66.00	X

Trans-cab Auto Services Pte Ltd

AAD1906-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 127C

TOTAL	\$	3,014.44
TOTAL PARTS	\$	38,334.45

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100d
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	800d
To check steering geometry and computer wheel alignment	\$	220.00	nn X
Putty and spray painting of the affected portion.	\$	7,500.00	1100d
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	nn X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	12d
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60d
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00	60d
To Check Electrical Lighting Concerned.	\$	170.00	20d
To rust-proofing of the affected areas.	\$	170.00	90d

Trans-cab Auto Services Pte Ltd

AAD1906-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 127C

To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i> 380.00 <i>X</i>
To transfer of Rear Bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
TOTAL	\$	18,730.00
Over All Total	\$	57,064.45

LUMP SUM (REPAIR DAY)

~~25~~ **DAYS**

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: