

VIC

Sheet1

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

Steve (LKK) with Perjo dice 26/6/19, 3.00 pm
8322 8813 10 days

27th JUNE 2019

CARRO LEASING PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

PIP
Resurvey before spray

Accident date: 24th JUNE 2019

Estimated repair cost for : SMG5561Z Renault Fluence 1.5 '15

S/n	Qty	Items	U/price	Amount
				\$2,350.00 1800/
1	1	Rear boot lid / DD		\$95.00 /
2	1	boot lid emble logo / NPC		\$75.00 X
3	1	boot lid Fluence logo X NN		\$50.00 X
4	1	Rear Boot Lid Number Plate X NN		\$600.00 /
5	1	Rear Boot Lid Number Plate garnish / DR		\$80.00 30/
6	10	Rear Boot Lid Number Plate garnish clips / NPC	\$8.00	\$250.00 /
7	1	Rear boot lid windscreen seal / NPC		\$350.00 /
8	1	Rear boot lid inner lock / DT		\$650.00 /
9	1	Rear boot lid inner trim board / CRU		\$250.00 /
10	1	Rear boot lid inner rubber / CRU		\$188.00 X
11	1	Rear boot lid shock absorber-RH X NN		\$1,900.00 552 /
12	2	Rear tail lamp-LED LH NN RH / DR	\$950.00	\$32.00 200 16/
13	4	Rear tail lamp clips / NPC	\$8.00	\$1,850.00 1020 /
14	1	Rear Bumper / DR		\$380.00 X
15	1	Rear Bumper centre molding X NN		\$458.00 X
16	1	rear bumper lower cover X NN		\$376.00 188 /
17	2	Rear Bumper side reflector LH NN RH / DR	\$188.00	\$200.00 /
18	2	Rear Bumper Side Bracket / BR	\$100.00	\$500.00 /
19	1	Rear Bumper reinforcement / BR		\$400.00 X
20	2	Rear Bumper reinforcement bracket X NN	\$200.00	\$1,000.00 200 /
21	4	Rear Bumper Reverse Sensor / BR	\$250.00	\$60.00 30 /
22	10	Rear bumper clips / NPC	\$6.00	\$78.00 X
23	1	Rear Bumper towing cover X NN		\$900.00 /
24	1	Rear end panel / DD		\$300.00 /
25	1	Rear end panel top garnish / DR		\$34.00 15 /
26	4	Rear end panel top garnish clips / NPC	\$8.50	\$1,750.00 /
27	1	rear fender -RH / DD		

28	1	Rear fender inner trim board-RH	X	NN	\$665.00	X
29	1	rear fender Inner Trim Board clips -RH	X	NN	\$60.00	X
30	1	Rear axle assy	/		\$4,250.00	4167 ✓
31	1	Rear tyre -RH	/		\$300.00	150 ✓
32	1	Rear RIM -RH	/		\$350.00	/

14,363
- 10%
12,926.70

Subtotal :- \$20,781.00

Labour charges

to Remove & install raer windscreen	\$120.00	100
Gum	\$50.00	40
Remove & refix raer RH undercarriage & axle assy	\$380.00	200
Wheel alignment (computer)	\$120.00	60
Remove & refix rear petrol tank	\$120.00	X
Tuff kote	\$120.00	30
To remove & install rear reverse sensor	\$120.00	20
Towing charges (separate bill sent to insurance)	\$100.00	X
Panel beating	\$1,000.00	/
Spray painting	\$1,000.00	900

2350

Subtotal :- \$3,130.00

Total:- \$23,911.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 12,926.70
L - 2350
15,276.70
L15 - 12,221.36
= 12,290.00

Limit repair 10K