

ASS. REC. BY:

REF: CS / FC119011408 / Hd372

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Sithara

of FCI

Date/Time: 27.6.19 1.48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 8267A

Insured: SHA 9722 R

at Workshop m/s Lai Hui

Tel: 645 38110

of 160 Sin Ming Drive #04-01 Sin Ming Auto (Pty)

Policy No:

Claim No: D19004160MFS17

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27.6.19 2.00pm

Person Contacted:

Jenny

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SHA 9722R CS / FC119009980 / Eqd3 D.O.A. 24/05/2019

GBD 8267A X

47@11:28am - Revised via email preli advise

1/1pm 8 275d confirmed (red: 2003.33; 42%)

ASS. REC. BY:

ASSIGNMENT

From:

Date:

1.7.2019

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: GBD 8267A

at Workshop n/s Lai Huat

of 160 Sin May Drive #04-01/02

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

837k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBD 8267A Yr Regn: 05, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

C.C.

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

108767

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VSK YBAM 208 0094076

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Dun 175/70R14

R: Fullan

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

24/6/19

Rear

R/Bal.

7

mm

L/Bal.

7

mm

D.O.I.

11/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

cls body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 16 AUG 2019

Date/Time, File Pass to?

1) 8/8 Typast

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

G + RS, SI

Photos

Others:

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$ 2750/-)

135
50
19
204



Auto
Consultants
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004160MFSH

Date: 4/7/2019

Our Ref: CS/FCI19011408/Ktd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBD 8267A

Please be informed that we had conducted the inspection of the abovementioned vehicle
1/7/2019 at the premises of M/s Lai Huat have the following to report: -

Workshop Estimate Amount	: S\$ 4,753.33
Revised Estimate Amount	: S\$ 3,465.60
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:
The vehicle sustained damages at the
o/s body portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-06-2019	Our Ref No. D19004160MFSH
Accident Date	24-06-2019	Claim Type. Third Party
Insured Vehicle	SHA9722R	Third Party Vehicle. GBD8267A
Survey Location	160 SIN MING DRIVE #04-01, #04-02 & #07-03 SIN MING AUTOCITY	
Contact Person.	JENNY LIM	
Contact No.	6453 8110/ 0	Fax No. 6459 6267
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LAI HUAT (MENG KEE) MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 4 July 2019 11:29 AM
To: Sbk E; SUR
Subject: FBN 5048H-DOA: 13/6/2019

Dear Mr Kwan,

As instructed by our client , please proceed to repair the **insured vehicle FBN 5048H on Lump Sum Repair, (Excess \$600/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	GBD8267A
Vehicle Type:	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Chassis No.:	VSKYBAM20Z0094076
Propellant:	Diesel
Engine No.:	K9KC400D054269
Engine Capacity:	1461 cc
Maximum Power Output:	-
Maximum Laden Weight:	2030 kg
Unladen Weight:	1320 kg
Year Of Manufacture:	2014
Original Registration Date:	29 May 2015
Lifespan Expiry Date:	28 May 2035
COE Category:	C - Goods Vehicle & Bus
Quota Premium:	\$53,001.00
COE Expiry Date:	28 May 2025
Road Tax Expiry Date:	28 Nov 2019
Inspection Due Date:	28 May 2020
Intended Transfer Date:	08 Aug 2019
CO2 Emission:	138.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

This vehicle has a road tax Over Payment of \$105.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

[OK](#)

[Print](#)

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022572
Pro-Matrix Pte Ltd

Page 1 of 1
Your ref. TP-SHA 9722R MS FC
Job No 70619
Our ref 19.06.33
Payment
Date 26/6/2019

Attn

Vehicle No GBD 8267A
Vehicle Model : Nissan NV200
Accident on ... 24/6/2019

Not Approved
11/6/19
Recovery After Repair
5 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear bumper	624.80	10.00	562.32
1.00	Pc	Rear door RH	1,409.20	10.00	1,268.28
1.00	Pc	Front door RH	1,219.70	10.00	1,097.73
Special nett item:					
1.00	Pc	Company decal	15.00		15.00
Labour & Misc:					
1.00		To replace company logo lettering	160.00		160.00
1.00		To knock dents on front fender RH and renew of parts	650.00		650.00
1.00		To spray paint (including rear fender RH, fuel tank cover, rocker panel)	1,000.00		1,000.00

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

4,753.33
332.73
5,086.06

Acknowledged by Repairer

Signature:
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011408/Kid3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9722R	Veh. Inspected	GBD 8267A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004160MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	27/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VSKYBAM20Z0094076	Colour	SILVER	
Odometer	108767	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	DUNLOP	4 mm	
L/H Front Tyre	175/70 R14	DUNLOP	4 mm	
R/H Rear Tyre	175/70 R14	FALKEN	7 mm	
L/H Rear Tyre	175/70 R14	FALKEN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2019	Inspection Date	01/07/2019	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 8267A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (N)	DENTED / CUT	624.80	624.80
1	REAR DOOR RH (N)	BENT / WARPED	1,409.20	1,409.20
1	FRONT DOOR RH (N)	TO REPAIR SEE LABOUR	1,219.70	-
	LESS 10% DISCOUNT		-325.37	-203.40
			2,928.33	1,830.60
	<u>SPECIAL NETT ITEMS</u>			
1	COMPANY DECAL (SN)	NECESSARY	15.00	15.00
			15.00	15.00
	<u>LABOUR</u>			
	TO REPLACE COMPANY LOGO LETTERING.		160.00	120.00
	TO KNOCK DENTS ON FRONT FENDER RH AND RENEW OF PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR RH.		650.00	600.00
	TO SPRAY PAINT (INCLUDING REAR FENDER RH,FUEL TANK COVER,ROCKER PANEL).		1,000.00	900.00
			1,810.00	1,620.00
	GRAND TOTAL		4,753.33	3,465.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,750.00

Report Ref No. CS/FC119011408/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.