

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011411/BBA3Q2
Date: 19/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994155
Claimant Vehicle No :	SKD6572A	Insured Vehicle No :	SMF7878C
Date of Loss:	25/06/2019	Nature of Claim:	TP
		Claim No:	0347665578SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD6572A		
Make & Model:	AUDI TT, 2.0 COUPE (A)	Engine No:	CES015923
Reg. Date:	24/12/2011 (Man. Year: 2011)	Chassis No:	TRUZZZ8J2C1004568
Colour:	Metallic Grey	Odometer:	85646 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,949.00	3,802.96	7,146.04	65.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	2,080.00	1,710.00	45.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,739.00	5,882.96	8,856.04	60.09
Approved Total (Overridden) (S\$)		4,700.00		

Nett Amount (S\$)	14,739.00	4,700.00	10,039.00	68.11
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
(S\$)		5,300.00		
Liabe Amount (80.00%) (S\$)		4,240.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,276.45		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment: 27/06/2019

Date Inspected: 28/06/2019

Estimated Period of Repair: 6.0 days

Inspected At:

160 SIN MING DR #01-14 SIN MING AUTO
Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)**Adjuster:** Lim Teow Guan**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,968.00 FL	*1,968.00 FL
2	1		*REAR BUMPER CLIPS	Repeated	55.00 FL	*- FL
3	2		*REAR BUMPER RETAINER	Necessary	266.00 FL	*266.00 FL
4	1		*REAR FENDER RH	Repair	893.50 FL	*- FL
5	1		*REAR FENDER QUARTER GLASS MOULDING	Necessary	188.50 FL	*188.50 FL
6	1		*DOOR RH	Repair	2,655.00 FL	*- FL
7	1		*SIDE MIRROR RH	Not Damaged	385.30 FL	*- FL
8	1		*REAR SHOCK ABSORBER	Not Necessary	382.00 FL	*- FL
9	1		*REAR UPPER ARM RH	Not Necessary	675.00 FL	*- FL
10	1		*REAR CENTER ARM RH	Not Necessary	683.60 FL	*- FL
11	1		*REAR LOWER ARM	Not Necessary	684.00 FL	*- FL
12	1		*REAR WHEEL KNUCKLE ARM	Dented	1,690.00 FL	*981.25 FL
13	1		*REAR WHEEL KNUCKLE ARM BEARING	Necessary	252.00 FL	*252.00 FL
14	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
15	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*FRONT 18 ALLOY RIM (LOCAL REPAIR)	Necessary	600.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,487.90	3,985.75
- List Item Discount on L Items 5.00/5.00% (\$)	538.90	182.79
Total Parts (\$)	10,949.00	3,802.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REVERSE SENSOR	New	80.00	60.00
2	R&R REAR FENDER QUARTER GLASS RH	New	80.00	0.00
3	R&R OIL TANK	New	150.00	0.00
4	R&R UNDERCARRIAGE	New	250.00	100.00
5	4 WHEEL ALIGNMENT	New	80.00	60.00
6	PANEL BEAT	New	1,600.00	1,000.00
7	RUST PROOFING	New	150.00	60.00
8	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (S\$)			3,790.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >