

27/03/2002

ASS. REC. BY:

REF: CS/CTI19011414/4302

Special Instruction:

Surveyor: Marru

ASSIGNMENT (Office)

From (Person): Irene Tayof CTIDate/Time: 27.6.19 12.28 p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SDH 7886A

Insured:

SJA 6649R

at Workshop m/s

New Tee Automobile

Tel:

6702 3113

of

Synergy @ KB, 20 Kati Bukit Road 4 #01-61

Policy No:

MPPCSN17626918011

Claim No:

SNM190702968002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25.6.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

27.6.19 2.11 p.m

Person Contacted:

Shu Yi

H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJA 6649R : XSDH 7886A : NA/INC17087021d2D.O.A. 25/05/2015

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

Veh No: *SDH 7886A*Yr Regn: *7, 15*Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*

Make:

*Honda city*c.c. *1497*

Colour:

3/466

A/C: Insured / Std / NI / NA

Sp. Reading:

46354

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*MRHGM 666061000073*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/55-216

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

7 Alken

Front

Rear

R/Bal.

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

6

mm

D.O.A.

25/6/19

D.O.I.

27/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/7/19 *Dep \$500 next 9743*
1/5 \$3050 *confused with my. Used \$5049.64, 62%.*

RECEIVED 04 JUL 2019.

Date/Time, File Pass to?

☐

Preli. Report

10/3/19 *marcus*☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: *5*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) *S + RS* *SI*☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

) TOTAL

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

3050)

220

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 27 June 2019 12:28 PM
To: utauto2@singnet.com.sg
Cc: assignments
Subject: OUR REF : SNM19D202968/TAYHP - Accident involving SDH7886A (NTUC) claiming against SJA6649R (China Taiping) on 25.06.2019
Attachments: SAS.PDF

WITHOUT PREJUDICE

Dear Sir/Mdm (LKK),

Please proceed to get your surveyor to liaise with Yee Tee Automobile to conduct PRS.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Lim Shu Min
Sent: Wednesday, 26 June, 2019 10:24 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; utauto2@singnet.com.sg
Subject: OUR REF : SNM19D202968/TAYHP - Accident involving SDH7886A (NTUC) claiming against SJA6649R (China Taiping) on 25.06.2019

Dear Irene,

Please conduct PRS SDH7886A soonest possible.

File with Officer-In-Charge – Irene Tay – 63896192.

Thank you

Lim Shu Min

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: YT(HQ) [<mailto:utauto@singnet.com.sg>]

Sent: Tuesday, June 25, 2019 5:25 PM

To: Claims Dept of CTI

Cc: 'YT(HQ)'

Subject: RE: Accident involving SDH7886A (NTUC) claiming against SJA6649R (China Taiping) on 25.06.2019

Hi,

Attached GIA Report.

Best Regards

RAY



Yew Tee Automobile Tech Pte Ltd

Branch Office:

Synergy@ KB, 25 Kaki Bukit Road 4,

#01-61, Singapore 417800

Office: 6702 3113

Email: utauto2@singnet.com.sg

 Please consider the environment before printing this email

Notice: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Tuesday, 25 June, 2019 5:18 PM

To: YT(HQ) <utauto@singnet.com.sg>

Subject: RE: Accident involving SDH7886A (NTUC) claiming against SJA6649R (China Taiping) on 25.06.2019

Hi,

No attachment.

Thank you

Lim Shu Min

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: YT(HQ) [<mailto:utauto@singnet.com.sg>]

Sent: Tuesday, 25 June, 2019 3:34 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: 'YT(HQ)' <utauto@singnet.com.sg>

Subject: Accident involving SDH7886A (NTUC) claiming against SJA6649R (China Taiping) on 25.06.2019

Hi Motor Claim,

Attached GIA Report.

Kindly arrange PRI at **Kaki Bukit**.

Please let us have the list of surveyor for choose to conduct the pre-repair survey.

Kindly let us have the liability and officer-in-charge too.

Thank You ☺

Best Regards

MAY



Yew Tee Automobile Tech Pte Ltd

Branch Office:

Synergy@ KB, 25 Kaki Bukit Road 4,

#01-61, Singapore 417800

Officer 6702 3113

Email: utauto2@singnet.com.sg



Please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Honda City 1.5A SV](#)

Honda City 1.5A SV

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price **\$51,088**

Depreciation **\$8,610 /yr**
View models with similar depre

Reg Date **14-Jan-2015**
(5yrs 6mths 17days COE left)

Mileage **22,123 km (5k /yr)**

Manufactured **2014**

Road Tax **\$684 /yr**

Transmission **Auto**

Dereg Value **\$41,491 as of today (change)**

OMV **\$16,534**

COE **\$65,889**

ARF **\$6,534**

Engine Cap **1,497 cc**

Power **88.0 kW (118 bhp)**

Curb Weight **1,096 kg**

No. of Owners **1**

Type of Vehicle **Mid-Sized Sedan**

Features

Airbags, Cruise Control, Knockdown Rear Seats, Keyless Entry/Start/Stop. View specs of the Honda City (2014-2017)

Accessories

Multi Function Steering Wheel, Keyless Engine Start, Auto Headlights, Touch Screen Audio System, Retractable Side Mirrors, Reverse Camera And Sensors.

Description


One Careful Lady Owner Super Low Mileage(22,123km). Economical To Run. Comfortable To Drive, Plenty Of Room For Passengers In Front And Rear. Huge Boot. Regularly Serviced. Never Had A Major Problem With This Vehicle; Has Always Been A Reliable Car. Black. First To See It Will Probably Want It So Don't Hang About. Viewing By Appointment Only, No Brokers Or Agents Please.

Category

PART Car, Direct Owner Sale, Low Mileage Car

Status

Available for sale


[Shortlist](#)
[Compare](#)
[Report Error](#)
[More](#)

Seller Information

Contact Person(s)

Contact No.

ESSENTIAL TRANSACTION

» Indemnity form

» Receipt

» Ownership Transfer



GET HELP WITH
PAPERWORK

sgCarMart Connect handles all your paperwork - send us your car details and we'll help with **Car Loan & Ownership Transfer**. For all Adverised Vehicles.

Upload your

6/25/2019

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4962J

Vehicle Details

Vehicle No.: SDH7886A

Vehicle to be Exported: No

Intended Deregistration Date: 25 Jun 2019

Vehicle Make: HONDA

Vehicle Model: CITY 1.5 SV CVT

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: L15Z12702731

Chassis No.: MRHGM6660GP000073

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$17,647.00

Original Registration Date: 30 Jul 2015

First Registration Date: 30 Jul 2015

Transfer Count: 0

Actual ARF Paid: \$12,647.00 632}

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jul 2025

PARF Rebate Amount: \$9,485.00

Intended COE Rebate Details

COE Expiry Date: 29 Jul 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$58,700.00

COE Rebate Amount: \$35,772.00

Total Rebate Amount: \$45,257.00

The information contained herein is correct as at 25 Jun 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTKB/TP/1906/013
Policy No:	5081329389-02	Date of Loss:	25/06/2019
Vehicle Reg. No.:	SDH7886A	Driveable?	yes
Driver Age:	24/07/1955	Third Party Vehicle No.:	SJA6649R
Any Injuries?	no	Contact No:	93678956
Insured/Claimant:	LAU WAI SIM	Driver:	LAU WAI SIM

Make/Model:	Honda, City	Vehicle Reg. Date:	25/06/2019
Vehicle Colour:		Engine Number:	L15Z12702731
Chassis No:	MRHGM6660GP000073	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	4,714.64
Miscellaneous Items	500.00
Labour	1,990.00
Paintwork Labour	895.00
Towing	0.00
Gross Total(S\$):	8,099.64
GST 7.00%(S\$):	566.97
Nett Amount(S\$):	8,666.61

This claim is handled by: SHUYI

Insurance notice to the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not added
net
4/5 \$3050
5/5
Zhang Huiyong
27/6/19

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	0.00	463.20	-20.00	370.56
2	1	REAR BUMPER REFLECTOR LH	0.00	34.20	-20.00	27.36
3	1	REAR BUMPER REFLECTOR RH	0.00	34.20	-20.00	27.36
4	1	REAR BUMPER SIDE RETAINER LH	0.00	23.28	-20.00	18.62
5	1	REAR BUMPER SIDE RETAINER RH	0.00	23.28	-20.00	18.62
6	1	REAR BUMPER BRACKET LH	0.00	36.33	-20.00	29.06
7	1	REAR BUMPER BRACKET RH	0.00	36.33	-20.00	29.06
8	1	REAR BUMPER INNER SPONGE	0.00	452.10	-20.00	361.68
9	1	REAR BUMPER REINFORCEMENT	0.00	386.15	-20.00	308.92
10	1	BOOT LID	0.00	488.21	-20.00	390.57
11	1	BOOT LID HINGES LH	0.00	75.20	-20.00	60.16
12	1	BOOT LID HINGES RH	0.00	75.20	-20.00	60.16
13	1	BOOT LID RUBBER	0.00	78.68	-20.00	62.94
14	1	BOOT LID LOCK	0.00	90.30	-20.00	72.24
15	1	BOOT LID LOCK CATCH	0.00	35.89	-20.00	28.71
16	1	BOOT LID LOGO	0.00	68.65	-20.00	54.92
17	1	BOOT LID CITY EMBLEM	0.00	71.25	-20.00	57.00
18	1	BOOT LID IVTEC EMBLEM	0.00	74.50	-20.00	59.60
19	1	BOOT LID REFLECTOR LH	0.00	36.88	-20.00	29.50
20	1	BOOT LID REFLECTOR RH	0.00	36.88	-20.00	29.50
21	1	BOOT LID INNER TRIM BOARD	0.00	110.25	-20.00	88.20
22	1	REAR TAILLAMP LH	0.00	238.47	-20.00	190.78
23	1	REAR TAILLAMP RH	0.00	238.47	-20.00	190.78
24	1	REAR TAILLAMP PANEL LH	0.00	95.77	-20.00	76.62
25	1	REAR TAILLAMP PANEL RH	0.00	95.77	-20.00	76.62
26	1	REAR TAILLAMP LOWER BRACKET LH	0.00	68.25	-20.00	54.60
27	1	REAR TAILLAMP LOWER BRACKET RH	0.00	68.25	-20.00	54.60
28	1	REAR END PANEL	0.00	398.11	-20.00	318.49
29	1	REAR END PANEL TOP GARNISH	0.00	398.11	-20.00	318.49
30	1	REAR SPARE TYRE BOARD	0.00	114.78	-20.00	91.82
31	1	REAR SPARE TYRE PANEL	0.00	489.52	-20.00	391.62
32	1	REAR BUMPER STAY LH	0.00	80.28	-20.00	64.22
33	1	REAR BUMPER STAY RH	0.00	80.28	-20.00	64.22
34	1	REAR CHASSIS MEMBER LH	0.00	398.14	-20.00	318.51
35	1	REAR CHASSIS MEMBER RH	0.00	398.14	-20.00	318.51

P-2240.01

Total Parts (\$\$)

4,714.64

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER REVERSE SENSOR	0.00	380.00	0.00	380.00
2	1	REAR BUMPER CLIP	0.00	45.00	0.00	45.00
3	1	REAR CAR PLATE	0.00	45.00	0.00	45.00
4	1	BOOT LID INNER TRIM BOARD CLIPS	0.00	30.00	0.00	30.00

Sub Total (\$\$)

500.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The	100.00	100.00	0.00	100.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Rear Section To Give Way To The Repair on The Rear Section.				
2	1	To Remove and Refit Rear Cushion Fittings.	80.00	80.00	0.00 <i>Reyoth</i>	80.00 X
3	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 50
4	1	To Transfer Rear Tailgate. <i>Rept. d. mechanism</i>	80.00	80.00	0.00	80.00 60
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	50.00	0.00	50.00 30
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,600.00	1,600.00	0.00	1,600.00 700

Gross Labour Cost (S\$) 1,990.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	50.00	0.00	50.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00 <i>me</i>	45.00 30
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	0.00	800.00 ✓

Gross Labour Cost (S\$) 895.00

< END OF ESTIMATES >

3 1160
3086.

8099.64

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011414/UQD3N2

Date: 09/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN17626918011
Claimant Vehicle No :	SDH7886A	Insured Vehicle No :	SJA6649R
Date of Loss:	25/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202968C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH7886A	Engine No:	L15Z12702731
Make & Model:	HONDA CITY, 1.5 (A)	Chassis No:	MRHGM6660GP000073
Reg. Date:	30/07/2015 (Man. Year: 2015)	Odometer:	46354 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,214.64	2,078.61	3,136.03	60.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,885.00	1,780.00	1,105.00	38.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,099.64	3,858.61	4,241.03	52.36
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	8,099.64	3,050.00	5,049.64	62.34
+ GST 7.00/7.00% (S\$)	566.97	213.50	353.47	62.34
Nett Amount (S\$)	8,666.61	3,263.50	5,403.11	62.34

INSPECTION

Date of Assignment: 02/07/2019

Date Inspected: 27/06/2019 Inspected At:

Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)
Blk 25 Kaki Bukit Road 4, #01-61
SYNERGY @ KAKI BUKIT
Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2019)
Parts: 143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDH7886A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	463.20 FL	*463.20 FL
2	1		*REAR BUMPER REFLECTOR LH	Not Necessary	34.20 FL	*- FL
3	1		*REAR BUMPER REFLECTOR RH	Not Necessary	34.20 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Bent	23.28 FL	*23.28 FL
5	1		*REAR BUMPER SIDE RETAINER RH	Bent	23.28 FL	*23.28 FL
6	1		*REAR BUMPER BRACKET LH	Not Necessary	36.33 FL	*- FL
7	1		*REAR BUMPER BRACKET RH	Not Necessary	36.33 FL	*- FL
8	1		*REAR BUMPER INNER SPONGE	No such part	452.10 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	No such part	386.15 FL	*- FL
10	1		*BOOT LID	Bent/Buckled	488.21 FL	*488.21 FL
11	1		*BOOT LID HINGES LH	Not Necessary	75.20 FL	*- FL
12	1		*BOOT LID HINGES RH	Not Necessary	75.20 FL	*- FL
13	1		*BOOT LID RUBBER	Twisted	78.68 FL	*78.68 FL
14	1		*BOOT LID LOCK	Twisted	90.30 FL	*90.30 FL
15	1		*BOOT LID LOCK CATCH	Not Necessary	35.89 FL	*- FL
16	1		*BOOT LID LOGO	Necessary	68.65 FL	*68.65 FL
17	1		*BOOT LID CITY EMBLEM	Necessary	71.25 FL	*71.25 FL
18	1		*BOOT LID IVTEC EMBLEM	Necessary	74.50 FL	*74.50 FL
19	1		*BOOT LID REFLECTOR LH	Not Necessary	36.88 FL	*- FL
20	1		*BOOT LID REFLECTOR RH	Not Necessary	36.88 FL	*- FL
21	1		*BOOT LID INNER TRIM BOARD	Not Necessary	110.25 FL	*- FL
22	1		*REAR TAILLAMP LH	Not Necessary	238.47 FL	*- FL
23	1		*REAR TAILLAMP RH	Cut	238.47 FL	*238.47 FL
24	1		*REAR TAILLAMP PANEL LH	Repair	95.77 FL	*- FL
25	1		*REAR TAILLAMP PANEL RH	Repair	95.77 FL	*- FL
26	1		*REAR TAILLAMP LOWER BRACKET LH	Not Necessary	68.25 FL	*- FL
27	1		*REAR TAILLAMP LOWER BRACKET RH	Not Necessary	68.25 FL	*- FL
28	1		*REAR END PANEL	Badly Dented	398.11 FL	*398.11 FL
29	1		*REAR END PANEL TOP GARNISH	Twisted	398.11 FL	*109.30 FL
30	1		*REAR SPARE TYRE BOARD	Torn	114.78 FL	*114.78 FL
31	1		*REAR SPARE TYRE PANEL	Repair	489.52 FL	*- FL
32	1		*REAR BUMPER STAY LH	Not Necessary	80.28 FL	*- FL
33	1		*REAR BUMPER STAY RH	Not Necessary	80.28 FL	*- FL
34	1		*REAR CHASSIS MEMBER LH	Repair	398.14 FL	*- FL
35	1		*REAR CHASSIS MEMBER RH	Repair	398.14 FL	*- FL
36	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	380.00 FS	*250.00 FS
37	1		*REAR BUMPER CLIP	Necessary	45.00 FS	*35.00 FS
38	1		*REAR CAR PLATE	Not Necessary	45.00 FS	*- FS
39	1		*BOOT LID INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,393.30	2,527.01
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,178.66	448.40
Total Parts (\$\$)	5,214.64	2,078.61

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	100.00	60.00
2	TO REMOVE AND REFIT REAR CUSHION FITTINGS	New	80.00	0.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	50.00
4	TO TRANSFER REAR BOOTLID MECHANISM	New	80.00	60.00
5	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS	New	50.00	30.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,600.00	700.00
7	TO CARRY-OUT BODY CAVITY PRESERVATION	New	50.00	50.00
8	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTUNG AREAS	New	45.00	30.00
9	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF EURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	800.00	800.00
Gross Labour Cost (\$\$)			2,885.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >