

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLQ 1250G
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 09/06/2019

TP Veh Reg No: SLN5052B

Estimate No: ES1991806/YISHUN

Date: 29 Jul 2019

Policy No: MS000834

Veh Reg No: SLQ1250G

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053ZEE106116284

Engine No: 3ZZ4790106

Reg. Date: 22/12/2008

Estimate Repair Cost to Vehicle No :SLQ1250G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	459.75	1 PC	459.75	—
2 REAR BUMPER SIDE RETAINERS	66.78	2 PCS	133.56	—
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	—
4 REAR BOOT LOGO	52.15	1 PC	52.15	—
5 REAR BOOT EMBLEM (1.6)	32.13	1 PC	32.13	—
6 REAR BOOT EMBLEM (COROLLA)	42.35	1 PC	42.35	—
7 REAR BOOT EMBLEM (ALTIS)	54.23	1 PC	54.23	—
8 REAR BOOT INNER LOCK	96.53	1 PC	96.53	7
			891.70	
		Less 25%	222.93	668.78
Special Net				
9 REVERSE SENSOR	200.00	1 SET	200.00	7
			200.00	200.00
Labour				
10 PANEL BEATING	500.00	1 LA	500.00	3600
11 PUTTY & RESPRAY	500.00	1 LA	500.00	400
			1,000.00	1,000.00
Total				S\$ 1,868.78
Add GST @ 7%				130.81
Total Amount Payable				S\$ 1,999.59

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE