

Survivor: Chua Kang Seng

REF: CS/LAW19011417/ Uy d362

Special Instruction:

As: \$ 10,900.00

From (Person): Julia Ong of Comlaw Date/Time: 25/6/19

Estimated Bill to:

Third Parties:

Claimant:

Surveyor: Automobile Assessment

Workshop: Best Auto

OD/TP Res/ation/ Evaluation

To Inspect V No: GBG 2087B

Insured: CB 6516T

at Workshop Best Auto

Tel: 6604 9883

of 2 Kaki Bukit Ave 2 # 01-11

Policy No:

Claim No: DV-CG-2019-218875

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21/08/2018

(Client's Record)

06/02/2020 @ 9 am - 10 am

H.O.D. Enforcement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 10 days)

Date/Time: 4/3/20 Submit Final Fig \$5200/-, 5 days (Red \$ 11406-10 68%; Original 5 days)

Date/Time	Action/Instruction
	GBG 2087B - NA/INC 18021620/24
	CB 6516T - NA/INC 18021620/24
31/01/2020	call back to (6604 9883) check with Admin about this case
	then just got back to julia.
4/3/20	1/5 @ \$5200 5% (Red \$11406-10, 68%)
RECEIVED 05 MAR 2020	
Do Not Finalise	

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1000

1000

1) Date/Time 4/3/20 File Pass to Typist

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time

4) Date/Time

6) Date/Time

File Return to

File Return to

File Return to

Nivitha (LKK Auto)

From: Julia Ong <julia@comlaw.com.sg>
Sent: Tuesday, 25 June 2019 9:47 AM
To: Admin-D (LKKAuto)
Cc: Crystal Goh; anjallim@visionlawllc.com; ct-admin@visionlawllc.com
Subject: Appointment of SJE - MC/MC 2814/2019 (Vision Law Ref: AM1-jt-Ins-825-107767-18 (sj) ; ComLaw Ref: DV.CG.2019.218875)
Attachments: Letter to LKK Auto Consultants Pte Ltd dd 25.06.2019 (appoint SJE + provide docs).pdf

Dear Sirs,

Please find enclosed our self-explanatory letter dated 25 June 2019 for your attention and necessary action.

As the file size of the attachments is too large, please download it via the link below instead:

<https://www.dropbox.com/s/ugj3z86m8rxnba4l/AAA6850SmPDseztMWFqEuHQ-a?dl=0>

Thank you and Best regards,

Ms Julia Ong
Secretary

For and on behalf of **Ms Crystal Goh**
Associate

ComLaw LLC

64 Cecil Street | #06-01 IOB Building | Singapore 049711

Direct: +65 6506 9139 | General: +65 6538 1221 | Fax: +65 6538 7890 | Email: julia@comlaw.com.sg

This email is intended solely for the person named. The contents are confidential and may be privileged solicitor-client communication. If you are not the intended recipient, kindly notify us, delete this email, and do not disclose this email. Thank you.

ComLaw LLC

Advocates & Solicitors, Notaries Public & Commissioners for Oaths
64 Cecil Street #06-01 / #03-02, IOB Building, Singapore 049711

COMLAW LLC is a law corporation with limited liability (Regn. No. 200105172H)
(Incorporating Piah, Tan & Partners)

Directors
Gertrude Chan
Chua Li Suan
Yeo Piah Chuan
Tan Siah Yong
Charles Phua

Associate Directors
D. Vivekananda
Felicia Ng
Charlene Chee

Associates
Crystal Goh
Herman Lee
Sancia Ng
Douglas Pang

Telephone : (65) 6538 1221
Fax : (65) 6538 7890
E-Mail : email@comlaw.com.sg

Our Ref : DV.CG.2019.218875.jo

Direct Line : 6506 9154
6506 9134

Your Ref : To be advised.

Secretary : 6506 9139

25 June 2019

LKK Auto Consultants Pte Ltd
Blk 51 Ubi Avenue 1
#02-25, Paya Ubi Industrial Park
Singapore 408933

BY EMAIL ONLY

Attention: Mr Chua Kang Seng Marcus

Dear Sirs

CLAIMANT : WU ZHENCHENG t/a CHECK-MATE EXPRESS SOLUTIONS
INSURED : STEADFAST TRANSPORT SERVICE

MC/MC 2814/2019

**ACCIDENT 21 AUGUST 2018 INVOLVING CB 6516T AND GBG 2087B ALONG
JALAN EUNOS TOWARDS HOUGANG**

1. We refer to the above matter.
2. We act for Steadfast Transport Service and M/s Vision Law LLC act for Wu Zhencheng t/a Check-Mate Express Solutions.
3. The claim is in respect of damage to motor vehicle no. GBG 2087B which was damaged in a road traffic accident on 21 August 2018 involving motor vehicle no. CB 6516T.
4. Pursuant to Order 108 of the Rules of Court, parties has agreed to appoint you as the Single Joint Expert.
5. Kindly note that as the Single Joint Expert appointed in the above matter, your duty is to the Court and you are required to give a fair and reasonable opinion as regards the issue of repair costs and duration for the repair of motor vehicle no. GBG 2087B.
6. We enclose herewith a copy of the following documents for your attention and review:
 - a) Traffic Police reports of CB 6516T and GBG 2087B;
 - b) Survey report by Aeon Auto Consultants LLP (with coloured photographs) (Claimant's surveyor);

- c) Survey report by FormTeam Consultancy Pte Ltd (with coloured photographs) (Defendant's surveyor); and
- d) Repair invoice by Best Auto K Pte Ltd.
7. Kindly conduct a physical re-inspection of motor vehicle no. GBG 2087B and let us have your views on the issue of repair costs and duration for the repair of motor vehicle no. GBG 2087B.
8. Please also let us have your fee for the report as well as your Court attendance fee (if required).
9. Please let us know when re-inspection has been completed and we look forward to receiving your re-inspection report.
10. Please let us have your report by **25 July 2019**.
11. Given your appointment as a Single Joint Expert, kindly copy M/s Vision Law LLC (file ref: AM1-jt-Ins-B25-107767-18 (sj)) in all your correspondence.

Yours faithfully




D.VIVEKNANDA / CRYSTAL GOH

Enc.

cc. M/s Vision Law LLC
Ref: AM1-jt-Ins-B25-107767-18 (sj)

BY EMAIL ONLY



INVOICE

TO : CHECK-MATE EXPRESS SOLUTIONS
C/O: BEST AUTO K PTE LTD
2 KAKI BUKIT AVE 2 #01-11 AUTO HUB
SINGAPORE 417921

Invoice No.: 818/BA781
Date: 20-Sep-2018

PARTICULARS

Vehicle Registration No.: GBG 2087 B
Date of Loss: 21-Aug-2018
Date of Assessment: 29-Aug-2018

SERVICES

FEES

1. Assessment with report Photographs -
Including films, developing, storage and Transport. \$600.00

TOTAL \$600.00

SINGAPORE DOLLARS SIX HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169674
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com

AUTOMOBILE ASSESSMENT REPORT

TO: CHECK-MATE EXPRESS SOLUTIONS
C/O: BEST AUTO K PTE LTD
2 KAKI BUKIT AVE 2 #01-11 AUTO HUB
SINGAPORE 417921

Our Reference: 818/BA781
Date: 20-Sep-2018

ASSESSMENT OF VEHICLE NO. GBG 2087 B
DATE OF LOSS: 21-Aug-2018

We have carried out a physical assessment at **BEST AUTO K PTE LTD**,
2 Kaki Bukit Ave 2 #01-11 AUTO HUB, Singapore 417921, according to your instruction
on **29-Aug-2018** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: GBG 2087 B
Make & Model: MERCEDES BENZ VITO 115 EU4
Year of Registration: 2006
Engine Capacity: 2148
Chassis No.: WDF63970523242818
Engine No.: 64698250233664
Colour: BLACK
Mileage (km): 829296

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: KUMHO 225/60 R16 – 70%
LH Make/Size/Thread: KUMHO 225/60 R16 – 70%


Rear
RH Make/Size/Thread: KUMHO 225/60 R16 – 70%
LH Make/Size/Thread: KUMHO 225/60 R16 – 70%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$16,606.10
Adjusted Amount:	\$13,629.50
Lump Sum:	\$10,900.00
Estimated Repair Days:	10 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. GBG 2087 B

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR TAILGATE ASSY	Bent	1,913.00	1,913.00 ✓
1	REAR TAILGATE 'LOGO' EMBLEM	Necessary	48.00	48.00 ✓
1	REAR TAILGATE 3RD BRAKE LAMP	Cracked	136.00	136.00 ✓
2	REAR TAILGATE DAMPER L/R	Bent	246.00	246.00 ✓
2	REAR TAILGATE HINGES L/R	Bent	274.00	274.00 ✓
1	REAR TAILGATE HINGES SUPPORT PANEL	Bent	278.00	278.00 ✓
1	REAR TAILGATE INNER OPENER HANDLE	Bent	94.00	94.00 ✓
1	REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	Cracked	138.00	138.00 ✓
1	REAR TAILGATE MECHANISM LOCK	Bent	170.00	170.00 ✓
1	REAR TAILGATE MECHANISM LOCK STRIKER	Bent	26.00	26.00 ✓
1	REAR TAILGATE OUTER GARNISH	Cracked	83.00	83.00 ✓
1	REAR TAILGATE OUTER HANDLE	Cracked	155.00	155.00 ✓
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R	Bent	72.00	72.00 ✓
1	REAR TAILGATE UPPER UPHOLSTERY TRIM GARNISH	Repair	50.00	✓
1	REAR TAILGATE WEATHER STRIP	Cut	205.00	205.00 ✓
1	REAR TAILGATE WINDSCREEN	Shattered	558.00	558.00 ✓
1	REAR TAILGATE WIPER ARM	Bent	95.00	95.00 ✓
1	REAR TAILGATE WIPER ARM COVER	Bent	15.00	15.00 ✓
1	REAR TAILGATE WIPER BLADE	Bent	60.00	60.00 ✓
1	REAR TAILGATE WIPER MOTOR	Faulty	356.00	356.00 ✓
1	REAR TAILGATE WIRE HARNESS	Repair	128.00	✓
2	REAR TAILGATE NUMBER PLATE LAMP L/R	Cracked	220.00	220.00 ✓
2	REAR TAILLAMP L/R	Cracked	728.00	728.00 ✓
2	REAR TAILLAMP OUTER PANEL L/R	Repair	425.00	✓
2	REAR TAILLAMP BACK RUBBER SEAL L/R	Necessary	54.00	54.00 ✓
2	REAR TAILLAMP LOWER GARNISH L/R	Bent	170.00	170.00 ✓
2	REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	Cut	968.00	968.00 ✓
1	REAR BUMPER ASSY	Cracked	735.00	735.00 ✓
2	REAR BUMPER BRACKET L/R	Bent	438.00	438.00 ✓
1	REAR BUMPER INNER FRAME GARNISH	Cracked	85.00	85.00 ✓
1	REAR BUMPER INNER SPONGE	Cracked	125.00	125.00 ✓
2	REAR BUMPER REFLECTOR L/R	Necessary	56.00	56.00 ✓
2	REAR BUMPER SIDE RETAINER L/R	Bent	82.00	82.00 ✓
2	REAR SIDE BUMPER L/R	Cracked	438.00	438.00 ✓
1	REAR END PANEL INNER TOP GARNISH	Cracked	134.00	134.00 ✓
1	REAR END INNER PANEL	Repair	529.00	✓
1	REAR END OUTER PANEL	Repair	212.00	✓
1	REAR FLOOR PANEL	Repair	980.00	✓
1	REAR EXHAUST SILENCER BOX	Repair	450.00	✓
			11,929.00	9,155.00
Less 10% discount			1,192.90	915.50
Parts Total:			10,736.10	8,239.50

4923
 4430.70

ASSESSMENT REPORT FOR VEHICLE NO. GBG 2087 B

SPECIAL NETT ITEMS

1	REAR TAILGATE NUMBER PLATE	Cracked	Coat Seal Dye	25.00	25.00
1	REAR TAILGATE NUMBER PLATE HOLDER	Cracked	Coat Seal Dye	50.00	50.00
1	REAR TAILGATE '70KM/H' STICKER	Necessary		15.00	10 15.00
1	REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	Necessary		80.00	80.00
1	REAR TAILGATE OUTER GARNISH CLIPS - SET	Necessary	NN	30.00	30.00
1	REAR TAILGATE REVERSE CAMERA	Faulty	NT	800.00	800.00
1	REAR TAILGATE WINDSCREEN SEALANT	Necessary		100.00	40 100.00
1	REAR TAILGATE WINDSCREEN CURTAIN	Bent	NF	300.00	300.00
2	REAR TAILLAMP CLIPS L/R - SET	Necessary	NN	60.00	60.00
2	REAR TAILLAMP LOWER GARNISH CLIPS L/R - SET	Necessary	NN	20.00	20.00
2	REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	Necessary	NN	60.00	60.00
1	REAR BUMPER CLIPS - SET	Necessary		50.00	50.00
1	REAR BUMPER REVERSE SENSOR	Cracked		350.00	200 350.00
1	REAR END PANEL INNER TOP GARNISH CLIPS - SET	Necessary	NN	30.00	30.00

Special Nett Total : 1,970.00 1,970.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	160.00	80 140.00
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	140.00	120.00
3	To remove, reinstall tailgate windscreen.	180.00	120 160.00
4	To reset system after repair works.	400.00	NNX 350.00
5	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,400.00	800 1,200.00
6	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,500.00	600 1,350.00
7	To apply anti-rust chemical on repaired and replaced panel.	120.00	30 100.00
Labour Total :		3,900.00	3,420.00
TOTAL (PARTS & LABOUR) \$		16,606.10	13,629.50

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$10,900.00

(SINGAPORE DOLLARS TEN THOUSAND NINE HUNDRED ONLY)



Amas Ong
Automobile Assessor

h 560.7
5200

2 KAKI BUKIT AVE 2 #01-11 AUTO HUB
SINGAPORE 417921
TEL : 6604 9883 FAX : 6604 9823
CO-GST REG.NO.:201211041G

Our Reference:	VITO115E/GBG2087B
Date:	20-Sep-2018
Vehicle Num:	GBG 2087 B
Make/Model:	MERCEDES BENZ VITO 115 EU4
Chassis No.:	WDF63970523242818
Engine No.:	64698250233664
Accident Date:	21-Aug-2018

[illegible]

GST Reg No. 2008192900

Attn: Ms. Juliana Lee

Invoice No :	13037371
Date :	19/11/2018
Page :	1
Your Ref :	MT/1008330-002
Our Ref :	NTUC18-085966/PRS/CY/ADJ/CY,

Description	Amount (S\$)
/ GBG 2087B - Balance bill for repair cost above 10K	S\$50.00

We would appreciate your cheque crossed and make payable to
FormTeam Consultancy Pte Ltd

E & O E

Total	S\$50.00
Add: 7% GST	S\$3.50
Total Inc GST	S\$53.50
Less: Deposit	S\$0.00
Balance Due	S\$53.50

FormTeam Consultancy Pte Ltd

RECEIVED BY	DATE	COMPANY STAMP



FormTeam Consultancy Pte Ltd

No. 33, Ubi Ave 3
#02-13, Vertex
Singapore 408668

Tel: (65) 6309 1788
Fax: (65) 6309 6221

Email: monosurvey@fta.com.sg

C=Reg No: 200819280D

LST Reg No: 200819280D

Our Reference: NTUC 18 085966 PRS / CY / AD / / CY / gh

Your Reference: MT 1008330-002

Date: 17 Nov 2018

Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Attention: Ms. Juliana Lee

Dear Sir/Mdm,

SURVEY OF VEHICLE NO. GBG 2087B

Pursuant to your instruction on **15 Nov 2018**

We recommend a repair cost of **\$4,850.00** (see report) based on lump sum repair and
the estimated duration of repairs would take **05 days**.

We also enclosed our note of charges for your consideration

Thank you for this assignment

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)


Ong Chung Yang
Automobile Appraiser

(Email: yang@fta.com.sg)

Encl: Survey Report

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference : NTUC18-085966/PRS/CY/ADJ/CY/gh

Your Reference: MT/1008330-002

Date : 17-Nov-18

Attention : Ms Juliana Lee

TO : Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Assessment of Vehicle No : **GBG 2087B**
Date of Accident : **21-August-2018**
Date of Inspection : **29-August-2018**
Address of Inspection : **25 Kaki Bukit Ave 2 #01-11 S'417921**

We have carried out a physical assessment of **GBG 2087B** at **M/S Best K Auto Pte Ltd** according to your instructions on **23-Aug-2018**, dismantled items on **30-Aug-2018**, post repair survey on **04-Sep-2018** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No. : GBG 2087B
Make & Model : Mercedes Benz Vito
Year of Registration : 2006
Engine Capacity : 2148 cc
Chassis No. : WDF63970523242818
Engine No. : 64698250233664
Colour : Black
Mileage (km) : 829296

2. VEHICLE CONDITION

Body Paint : Fair
Steering : Serviceable
Foot Brake : Serviceable
Parking Brake : Serviceable

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size : Habilead 225/60R16 - 40%
LH Make/Size : Habilead 225/60R16 - 40%

Rear

RH Make/Size : Kumho 225/60R16 - 80%
LH Make/Size : Kumho 225/60R16 - 80%


Note : % denotes the remaining percentage of the tyre

Our Reference VTUC 18-085966/PRS/CY/ADJ/CY/gh
Your Reference MT/1008330-002
Vehicle Number GBG 2087H

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Rear** portion. Please see attached scheduled for details.



5. REMARKS

Market Value -
Salvage Value -
Repair Limit (Nett Loss) -
Repairer's estimate Not Provided
Nett Saving -
Excess -
Sum Insured -
Our adjusted amount \$ 4,850.00
Estimated Repair Days 05 days ←

Additional photographs will be submitted upon request by our principal.

Pursuant to your instructions, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by

FormTeam Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

FormTeam Consultancy Pte Ltd

Our Reference : NTUC18-085966/PRS/CY/ADJ/CY/gh
 Your Reference : MT/1008330-002
 Vehicle Number : GBG 2087B

Page No. 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	PARTS (LIST ITEMS)			
1	Rear Tailgate Assy	Bent	-	1,913.00
1	Rear Tailgate Logo Emblem	Necessary	-	48.00
1	Rear Tailgate 3rd Brake Lamp	No Damage	-	- x
2	Rear Tailgate Damper L/R	No Damage	-	- x
2	Rear Tailgate Hinges L/R	No Damage	-	- x
1	Rear Tailgate Hinges Support Panel	No Damage	-	- x
1	Rear Tailgate Inner Opener Handle	Bent	-	94.00
1	Rear Tailgate Inner Upholstery Trim Garnish	Cracked	-	138.00
1	Rear Tailgate Mechanism Lock	Bent	-	170.00
1	Rear Tailgate Mechanism Lock Striker	No Damage	-	-
1	Rear Tailgate Outer Garnish	Cracked	-	83.00
1	Rear Tailgate Outer Handle	Cracked	-	155.00
2	Rear Tailgate Rubber Guide Stopper R/L	No Damage	-	-
1	Rear Tailgate Upper Upholstery Trim Garnish	Repair	-	-
1	Rear Tailgate Weatherstrip	Not Consistent	-	-
1	Rear Windscreen	Shattered	-	558.00
1	Rear Tailgate Wiper Arm	Bent	-	95.00
1	Rear Tailgate Wiper Arm Cover	Bent	-	15.00
1	Rear Tailgate Wiper Blade	Bent	-	60.00
1	Rear Tailgate Wiper Motor	Faulty	-	356.00
1	Rear Tailgate Wire Harness	Repair	-	-
2	Rear Tailgate Number Plate Lamp L/R	No Damage	-	-
2	Rear Taillamp L/R	N/S Cracked, N/S No Damage	-	364.00
2	Rear Taillamp Outer Panel L/R	No Damage	-	-
2	Rear Taillamp Back Rubber Seal L/R	Necessary	-	54.00
2	Rear Taillamp Lower Garnish L/R	Repairable	-	-
2	Rear Fender Inner Upholstery Trim Garnish L/R	Serviceable	-	-
1	Rear Bumper Assy	Cracked	-	735.00

FormTeam Consultancy Pte Ltd

Our Reference : NTUC18-085966/PRS/CY/ADJ/CY/gh
 Your Reference : MT/1008330-002
 Vehicle Number : GHG 2087B

Page No. 4

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)		OUR ASSESSMENT (S\$)	
2	Rear Bumper Bracket L/R	Not Consistent/Serviceable	-	-	-	-
1	Rear Bumper Inner Frame Garnish	Cracked	-	-	85.00	-
1	Rear Bumper Inner Sponge	Not In Use	-	-	-	-
2	Rear Bumper Reflector L/R	No Damage/Not Necessary	-	-	-	-
2	Rear Bumper Side Retainer L/R	Not Necessary	-	-	-	-
2	Rear Side Bumper L/R	Repairable	-	-	-	-
1	Rear End Panel Inner Top Garnish	Not Consistent/Reuse	-	-	-	-
1	Rear End Inner Panel	No Damage	-	-	-	-
1	Rear End Outer Panel	No Damage	-	-	-	-
1	Rear Floor Panel	No Damage	-	-	-	-
1	Rear Exhaust Silencer Box	No Damage	-	-	-	-
			-	-	4,923.00	-
Less Discount :			0%	-	10%	492.30
Parts Total :			-	-	4,430.70	-
SPECIAL NETT ITEMS						
1	Rear Tailgate Number Plate	No Damage	-	-	-	-
1	Rear Tailgate Number Plate Holder	No Damage	-	-	-	-
1	Rear Tailgate 70km/h Sticker	Necessary	-	-	10.00	-
1	Rear Tailgate Inner Upholstery Trim Garnish Clips - Set	Necessary	-	-	20.00	-
1	Rear Tailgate Outer Garnish Clips - Set	Not Necessary	-	-	-	-
1	Rear Tailgate Reverse Sensor	Reuse	-	-	-	-
1	Rear Tailgate Windscreen Sealant	Necessary	-	-	40.00	-
1	Rear Tailgate Windscreen Curtain	Serviceable	-	-	-	-
2	Rear Taillamp Clips L/R - Set	Not Necessary	-	-	-	-
2	Rear Taillamp Lower Garnish Clips L/R - Set	Not Necessary	-	-	-	-
1	Rear Bumper Clips - Set	Necessary	-	-	20.00	-
1	Rear Bumper Reverse Sensor - Set	Cracked	-	-	200.00	-
1	Rear End Panel Inner Top Garnish Clips Set	Not Necessary	-	-	-	-
Special Nett Total :			-	-	290.00	-
Parts Total :			-	-	4,720.70	-


FormTeam Consultancy Pte Ltd

Our Reference : NTUC18 085966 / PRS / CY / ADJ / CY / gh
 Your Reference : MT / 1008330-002
 Vehicle Number : GBG 2087B

Page No. 5

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To rewire rear portion, remove and refix reverse sensor.	-	80.00
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet	-	-
3	To remove, reinstall tailgate windscreen.	-	100.00
4	To reset system after repair works.	-	-
5	To putty and respray painting on the affected areas.	-	700.00
6	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts	-	450.00
7	To apply undersending	-	30.00
	Labour Total :	-	1,360.00
	TOTAL (PARTS & LABOUR) :	-	6,080.70

The final adjusted Lump Sum contract amount is **\$4,850.00**
(SINGAPORE DOLLARS FOUR THOUSAND EIGHT HUNDRED AND FIFTY ONLY)


 Frankie Pang
 AMSAE(AUST), AMIRTE, AMSOE,
 MASPACI, MSAAA
 Licensed Appraiser


 Ong Chung Yang
 Automobile Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the costs and to copies of the report being made available as stated.

ACCIDENT STATEMENT

Date Of Report 21/08/2018 17:12
Date Of Accident 21/08/2018 14:50
Exact Location Of Accident JUNCTION ROAD OF JALAN EUNOS
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBG2087B
Insured/Policyholder
Name Of Registered Owner CHECK-MATE EXPRESS SOLUTIONS
Co Reg No 5332050BE
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-90696675
Vehicle Particulars
Manufacturer MERCEDES-BENZ
Model VITO 115 2.1 D (A)
Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE
Insurance Company
Name of Insurance Company EQ INSURANCE COMPANY LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number DMCPHQ18-003681
Cover Note Number
Driver
Name of Driver MUHAMMAD HADI BIN MD TAHIR
NRIC No S8207245D
Date Of Birth 02/03/1982
Occupation OUTDOOR
Date Of Driving Pass 21/04/2017
Driving Experience 1 YEAR AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-87518410
Fax Number
Contact Number
Email Address ADVIER F@GMAIL.COM

Address BLK 1 EUNOS CRESCENT
#04-2535
Postcode 400001
Was driver an employee of the Insured's Company? YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims and/or other
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

STATEMENT RECORDED BY SOU - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number CB851BT
Vehicle Make/Model/Colour
Details Of Property
Vehicle Category COMMERCIAL VEHICLE
Name of Driver YUEN KWEK MUN
NRIC/Passport Number S742699J
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMMAD HADI BIN MD TAHIR

SKETCH PLAN

VEHICLE NO.
A-05670876

B. 65 67

A diagram showing a square with a triangle on top and a circle inside.

[illegible]

1. The undersigned hereby certifies that the above information is true and correct to the best of his knowledge and belief.

Reporting Center Personnel's Signature _____
 Date: _____
 Page 2 of 2

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please read carefully the following instructions, send us the signed form and the documents requested as the **Forwarder** and/or the **Authorized Driver**.
2. We will be able to accept the form only if it is **truthful and accurate** as possible. The data must be consistent with the knowledge of material facts that show no intent to commit fraud or to evade policy liability.
3. Payment of a premium of insurance is made on the basis of the information provided by you. If you provide false information on the part of the insurance contract.
4. Any false reporting must be referred to the Police for investigation.
5. The form is to be filled out by the **Forwarder** or the **Authorized Driver** who is requested by the General Insurance Company. It is not to be filled out by the **Insured** or the **Beneficiary**. It is not to be filled out by the **Insured** or the **Beneficiary** if they are not the **Forwarder** or the **Authorized Driver**.
6. Current under the Personal Data Protection Act (NEN 2).
7. **Insured** is the **Insured** or the **Authorized Driver**.
8. **Insured** is the **Insured** or the **Authorized Driver**.
9. **Insured** is the **Insured** or the **Authorized Driver**.
10. **Insured** is the **Insured** or the **Authorized Driver**.
11. **Insured** is the **Insured** or the **Authorized Driver**.
12. **Insured** is the **Insured** or the **Authorized Driver**.
13. **Insured** is the **Insured** or the **Authorized Driver**.
14. **Insured** is the **Insured** or the **Authorized Driver**.
15. **Insured** is the **Insured** or the **Authorized Driver**.
16. **Insured** is the **Insured** or the **Authorized Driver**.
17. **Insured** is the **Insured** or the **Authorized Driver**.
18. **Insured** is the **Insured** or the **Authorized Driver**.
19. **Insured** is the **Insured** or the **Authorized Driver**.
20. **Insured** is the **Insured** or the **Authorized Driver**.
21. **Insured** is the **Insured** or the **Authorized Driver**.
22. **Insured** is the **Insured** or the **Authorized Driver**.
23. **Insured** is the **Insured** or the **Authorized Driver**.
24. **Insured** is the **Insured** or the **Authorized Driver**.
25. **Insured** is the **Insured** or the **Authorized Driver**.
26. **Insured** is the **Insured** or the **Authorized Driver**.
27. **Insured** is the **Insured** or the **Authorized Driver**.
28. **Insured** is the **Insured** or the **Authorized Driver**.
29. **Insured** is the **Insured** or the **Authorized Driver**.
30. **Insured** is the **Insured** or the **Authorized Driver**.
31. **Insured** is the **Insured** or the **Authorized Driver**.
32. **Insured** is the **Insured** or the **Authorized Driver**.
33. **Insured** is the **Insured** or the **Authorized Driver**.
34. **Insured** is the **Insured** or the **Authorized Driver**.
35. **Insured** is the **Insured** or the **Authorized Driver**.
36. **Insured** is the **Insured** or the **Authorized Driver**.
37. **Insured** is the **Insured** or the **Authorized Driver**.
38. **Insured** is the **Insured** or the **Authorized Driver**.
39. **Insured** is the **Insured** or the **Authorized Driver**.
40. **Insured** is the **Insured** or the **Authorized Driver**.
41. **Insured** is the **Insured** or the **Authorized Driver**.
42. **Insured** is the **Insured** or the **Authorized Driver**.
43. **Insured** is the **Insured** or the **Authorized Driver**.
44. **Insured** is the **Insured** or the **Authorized Driver**.
45. **Insured** is the **Insured** or the **Authorized Driver**.
46. **Insured** is the **Insured** or the **Authorized Driver**.
47. **Insured** is the **Insured** or the **Authorized Driver**.
48. **Insured** is the **Insured** or the **Authorized Driver**.
49. **Insured** is the **Insured** or the **Authorized Driver**.
50. **Insured** is the **Insured** or the **Authorized Driver**.
51. **Insured** is the **Insured** or the **Authorized Driver**.
52. **Insured** is the **Insured** or the **Authorized Driver**.
53. **Insured** is the **Insured** or the **Authorized Driver**.
54. **Insured** is the **Insured** or the **Authorized Driver**.
55. **Insured** is the **Insured** or the **Authorized Driver**.
56. **Insured** is the **Insured** or the **Authorized Driver**.
57. **Insured** is the **Insured** or the **Authorized Driver**.
58. **Insured** is the **Insured** or the **Authorized Driver**.
59. **Insured** is the **Insured** or the **Authorized Driver**.
60. **Insured** is the **Insured** or the **Authorized Driver**.
61. **Insured** is the **Insured** or the **Authorized Driver**.
62. **Insured** is the **Insured** or the **Authorized Driver**.
63. **Insured** is the **Insured** or the **Authorized Driver**.
64. **Insured** is the **Insured** or the **Authorized Driver**.
65. **Insured** is the **Insured** or the **Authorized Driver**.
66. **Insured** is the **Insured** or the **Authorized Driver**.
67. **Insured** is the **Insured** or the **Authorized Driver**.
68. **Insured** is the **Insured** or the **Authorized Driver**.
69. **Insured** is the **Insured** or the **Authorized Driver**.
70. **Insured** is the **Insured** or the **Authorized Driver**.
71. **Insured** is the **Insured** or the **Authorized Driver**.
72. **Insured** is the **Insured** or the **Authorized Driver**.
73. **Insured** is the **Insured** or the **Authorized Driver**.
74. **Insured** is the **Insured** or the **Authorized Driver**.
75. **Insured** is the **Insured** or the **Authorized Driver**.
76. **Insured** is the **Insured** or the **Authorized Driver**.
77. **Insured** is the **Insured** or the **Authorized Driver**.
78. **Insured** is the **Insured** or the **Authorized Driver**.
79. **Insured** is the **Insured** or the **Authorized Driver**.
80. **Insured** is the **Insured** or the **Authorized Driver**.
81. **Insured** is the **Insured** or the **Authorized Driver**.
82. **Insured** is the **Insured** or the **Authorized Driver**.
83. **Insured** is the **Insured** or the **Authorized Driver**.
84. **Insured** is the **Insured** or the **Authorized Driver**.
85. **Insured** is the **Insured** or the **Authorized Driver**.
86. **Insured** is the **Insured** or the **Authorized Driver**.
87. **Insured** is the **Insured** or the **Authorized Driver**.
88. **Insured** is the **Insured** or the **Authorized Driver**.
89. **Insured** is the **Insured** or the **Authorized Driver**.
90. **Insured** is the **Insured** or the **Authorized Driver**.
91. **Insured** is the **Insured** or the **Authorized Driver**.
92. **Insured** is the **Insured** or the **Authorized Driver**.
93. **Insured** is the **Insured** or the **Authorized Driver**.
94. **Insured** is the **Insured** or the **Authorized Driver**.
95. **Insured** is the **Insured** or the **Authorized Driver**.
96. **Insured** is the **Insured** or the **Authorized Driver**.
97. **Insured** is the **Insured** or the **Authorized Driver**.
98. **Insured** is the **Insured** or the **Authorized Driver**.
99. **Insured** is the **Insured** or the **Authorized Driver**.
100. **Insured** is the **Insured** or the **Authorized Driver**.

Signature of the Insured or the Authorized Driver

Signature of the Insured or the Authorized Driver

Signature of the Insured or the Authorized Driver

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/08/2018 10:06
Date Of Accident	21/08/2018 15:10
Exact Location Of Accident	JALAN EUNOS TOWARDS HOUGANG
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	CB6516T
Insured/Policyholder	
Name Of Registered Owner	STEADFAST TRANSPORT SERVI
Co Reg No	53004741A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67478424
Vehicle Particulars	
Manufacturer	HIGER
Model	KLQ6728-3.8 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102047893
Cover Note Number	24/07/2018 - 23/07/2019
Driver	
Name of Driver	YUEN KWOK MUN
NRIC No	S7426999J
Date Of Birth	19/08/1974
Occupation	INDOOR
Date Of Driving Pass	15/10/1996
Driving Experience	21 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97718324
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 406C FERNVALE ROAD #12-57
Postcode	793406
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	11
Passenger 1	NAME: : PASSENGER GENDER: : MALE
Passenger 2	NAME: : PASSENGER GENDER: : MALE
Passenger 3	NAME: : PASSENGER GENDER: : MALE
Passenger 4	NAME: : PASSENGER GENDER: : MALE
Passenger 5	NAME: : PASSENGER GENDER: : MALE
Passenger 6	NAME: : PASSENGER GENDER: : FEMALE
Passenger 7	NAME: : PASSENGER GENDER: : FEMALE
Passenger 8	NAME: : PASSENGER GENDER: : FEMALE
Passenger 9	NAME: : PASSENGER GENDER: : FEMALE
Passenger 10	NAME: : PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

TRAFFIC TURNED GREEN. VEHICLE B MOVED OFF AND I FOLLOWED SUIT. SUDDENLY, VEHICLE B JAMMED BRAKE CAUSING ME NOT ABLE TO BRAKE IN TIME AND HIT INTO THE REAR PORTION OF HIS VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG2087B
Vehicle Make/Model/Colour	MERCEDES VITO
Details Of Properties	REAR PORTION
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	S8207245D
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan Pg. 1

NFIC Inshore Motor Service Centre

Vehicle No.

CRC516T

Report Date: 8/23/2018 Start Time: 10:22 AM

Report No: MI

D.O.A. 2/8/18

Make / Model

Reporting Type: RD

End Time:

Pending company stamp

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.



8/23/2018 10:22


Policyholder's Signature
Date & Time:

Driver's Signature (if driver is not the policyholder)
Date & Time:

8/23/2018 10:22

Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

TRAFFIC TURNED GREEN. VEHICLE B MOVED OFF AND I FOLLOWED SUIT. SUDDENLY, VEHICLE B JAMMED BRAKE CAUSING ME NOT ABLE TO BRAKE IN TIME AND HIT INTO THE REAR PORTION OF HIS VEHICLE.

DECLARATION

We declare the foregoing particulars are true in every respect



8/23/2018 10:22

Policyholder's Signature
Date & Time:

8/23/2018 10:22

Driver's Signature (if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
COMLAW LLC*		Ref : CS/LAW19011417/Uyd3e2		
64 CECIL ST #06-01 IOB BLDG SINGAPORE 049711		Date : 05-03-2020		
		Code : L050		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	CB 6516T	Veh. Inspected	GBG 2087B	
Policy No.		Coverage (\$)	0.00	
Claim No.	DV.CG.201.218875	Excess (\$)	0.00	
Assign From	JULIA ONG	Assign Date	25/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ VITO	c.c	2148	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	WDF63970523242818	Colour	BLACK	
Odometer	876342	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R16	HABILEAD	5 mm	
L/H Front Tyre	225/60 R16	HABILEAD	5 mm	
R/H Rear Tyre	225/60 R16	HABILEAD	5 mm	
L/H Rear Tyre	225/60 R16	HABILEAD	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	21/08/2018	Inspection Date	06/02/2020	
Survey held at	2 KAKI BUKIT AVE 2 #01-11			
Repairer	BEST AUTO K PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2087B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE ASSY	REPLACED	1,913.00	1,913.00
1	REAR TAILGATE 'LOGO' EMBLEM	REPLACED	48.00	48.00
1	REAR TAILGATE 3RD BRAKE LAMP	CAN'T SEE DAMAGE	136.00	-
2	REAR TAILGATE DAMPER L/R	CAN'T SEE DAMAGE	246.00	-
2	REAR TAILGATE HINGES L/R	CAN'T SEE DAMAGE	274.00	-
1	REAR TAILGATE HINGES SUPPORT PANEL	CAN'T SEE DAMAGE	278.00	-
1	REAR TAILGATE INNER OPENER HANDLE	REPLACED	94.00	94.00
1	REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	REPLACED	138.00	138.00
1	REAR TAILGATE MECHANISM LOCK	REPLACED	170.00	170.00
1	REAR TAILGATE MECHANISM LOCK STRIKER	CAN'T SEE DAMAGE	26.00	-
1	REAR TAILGATE OUTER GARNISH	REPLACED	83.00	83.00
1	REAR TAILGATE OUTER HANDLE	REPLACED	155.00	155.00
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R	CAN'T SEE DAMAGE	72.00	-
1	REAR TAILGATE UPPER UPHOLSTERY TRIM GARNISH	REPAIRED SEE LABOUR	50.00	-
1	REAR TAILGATE WEATHER STRIP	NOT CHANGED	205.00	-
1	REAR TAILGATE WINDSCREEN	REPLACED	558.00	558.00
1	REAR TAILGATE WIPER ARM	REPLACED	95.00	95.00
1	REAR TAILGATE WIPER ARM COVER	REPLACED	15.00	15.00
1	REAR TAILGATE WIPER BLADE	REPLACED	60.00	60.00
1	REAR TAILGATE WIPER MOTOR	REPLACED	356.00	356.00
1	REAR TAILGATE WIRE HARNESS	REPAIRED SEE LABOUR	128.00	-
2	REAR TAILGATE NUMBER PLATE LAMP L/R	CAN'T SEE DAMAGE	220.00	-
2	REAR TAILLAMP L/R	N/S REPLACED / O/S CAN'T SEE DAMAGE	728.00	364.00

Report Ref No. CS/LAW19011417/Uyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILLAMP OUTER PANEL L/R	REPAIRED SEE LABOUR	425.00	-
2	REAR TAILLAMP BACK RUBBER SEAL L/R	REPLACED	54.00	54.00
2	REAR TAILLAMP LOWER GARNISH L/R	CAN'T SEE DAMAGE	170.00	-
2	REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	CAN'T SEE DAMAGE	968.00	-
1	REAR BUMPER ASSY	REPLACED	735.00	735.00
2	REAR BUMPER BRACKET L/R	CAN'T SEE DAMAGE	438.00	-
1	REAR BUMPER INNER FRAME GARNISH	REPLACED	85.00	85.00
1	REAR BUMPER INNER SPONGE	NOT FITTED	125.00	-
2	REAR BUMPER REFLECTOR L/R	CAN'T SEE DAMAGE	56.00	-
2	REAR BUMPER SIDE RETAINER L/R	CAN'T SEE DAMAGE	82.00	-
2	REAR SIDE BUMPER L/R	CAN'T SEE DAMAGE	438.00	-
1	REAR END PANEL INNER TOP GARNISH	NOT CHANGED	134.00	-
1	REAR END INNER PANEL	REPAIRED SEE LABOUR	529.00	-
1	REAR END OUTER PANEL	REPAIRED SEE LABOUR	212.00	-
1	REAR FLOOR PANEL	NOT DAMAGED	980.00	-
1	REAR EXHAUST SILENCER BOX	NOT DAMAGED	450.00	-
	LESS 10% DISCOUNT		-1,192.90	-492.30
			10,736.10	4,430.70
SPECIAL NETT ITEMS				
1	REAR TAILGATE NUMBER PLATE (SN)	CAN'T SEE DAMAGE	25.00	-
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	CAN'T SEE DAMAGE	50.00	-
1	REAR TAILGATE '70KM/H' STICKER (SN)	REPLACED	15.00	10.00
1	SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	REPLACED	80.00	80.00
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/LAW19011417/Uyd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE REVERSE CAMERA (SN)	CAN'T SEE DAMAGE	800.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	REPLACED	100.00	40.00
1	REAR TAILGATE WINDSCREEN CURTAIN (SN)	CAN'T SEE DAMAGE	300.00	-
2	SET REAR TAILLAMP CLIPS L/R (SN)	NOT NECESSARY	60.00	-
2	SET REAR TAILLAMP LOWER GARNISH CLIPS L/R (SN)	NOT NECESSARY	20.00	-
2	SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIPS (SN)	REPLACED	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	REPLACED	350.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
			1,970.00	380.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		160.00	80.00
	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET.		140.00	120.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		180.00	120.00
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	400.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,400.00	800.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR TAILGATE UPPER UPHOLSTERY TRIM GARNISH, REAR TAILGATE WIRE HARNESS, REAR TAILLAMP OUTER PANEL L/R, REAR END INNER PANEL AND REAR END OUTER PANEL.		1,500.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	30.00
			3,900.00	1,750.00
GRAND TOTAL			16,606.10	6,560.70

Report Ref No. CS/LAW19011417/Uyd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00
---	--	--	----------

Report Ref No. CS/LAW19011417/Uyd3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.