



SMRT AUTOMOTIVE SERVICES PTE LTD
60 Woodlands Industrial Park E4, SINGAPORE 757705

To: PUB

Vehicle No: GBD3944L

Model: Nissan NV200

Date: 24/06/2019

Quotation

S/No.	Description	Qty	Price
1	Rear tailgate RH — 30%	1	\$ 1,320.00
2	Rear tailgate LH — 30%	1	\$ 1,350.00
3	Rear tailgate rubber RH X	1	\$ 185.00
4	Rear tailgate rubber LH X	1	\$ 185.00
5	Rear tailgate lock X	1	\$ 188.00
6	Rear tailgate hinge top RH X	1	\$ 147.00
7	Rear tailgate hinge bottem RH X	1	\$ 147.00
8	Rear tailgate hinge top LH X	1	\$ 147.00
9	Rear tailgate hinge top LH X	1	\$ 147.00
10	Rear end panel X	1	\$ 285.00
11	Rear end panel inner X	1	\$ 472.00
12	Rear tail lamp RH X	1	\$ 325.00
13	Rear tail lamp LH X	1	\$ 325.00
14	Rear bumper assy — -30%	1	\$ 1,026.00
15	Rear bumper retainer RH X	1	\$ 68.00
16	Rear bumper retainer LH X	1	\$ 68.00
17	Rear bumper reflector RH X	1	\$ 90.00
18	Rear bumper reflector LH X	1	\$ 90.00
19	Rear fender RH X	1	\$ 1,650.00
20	Rear fender LH X	1	\$ 1,650.00
21	Rear reverse camera X	1	\$ 380.00
22	Rear reverse sensor — SW	1	\$ 300.00

20

Rear tail gate stickers

SN — \$200 —

23	Rear number plate lamp x 2 pcs	X	1	\$	226.00
24	Rear emblem logo wording (Nissan/NV200)	— SN	1	\$	95.00
25	Rear sticker (70/km) - PUB red and white logo	— SN	1	\$	200.00
26	Rear number plate 1 set	X	1	\$	80.00
To supply labour cost				\$	-
1	Rust proofing		1	\$	200.00 50
2	To check wiring system rear reverse camera and rear reverse sensor		1	\$	400.00 100
3	To remove and refix rear wind screen RH & LH		1	\$	400.00 150
4	Rear wind screen sealant - 2 pcs (1 pc @ \$50)		2	\$	100.00 60
5	To knock and welding, straightening accident rear tailgate RH& LH, end panel, end panel inner, fender RH & LH, bumper		1	\$	2,500.00 600
6	To respray paint on accident rear tailgate RH & LH, end panel, end panel inner fender RH & LH, bumper (two colour, blue & white)		1	\$	2,000.00 600
Estimated 14 working days upon quotation approval.				\$	-
Remarks: Any additional parts or pricing will be informed after dismantle parts for further check (if needed)				Total Charges:	\$ 16,746.00
				GST	\$ 1,172.22
				Amount Payable:	\$ 17,918.22

Tan Yuwei
Workshop Manager
Fleet Maintenance

SMRT Automotive Pte Ltd



Kalvin 10/10/19

27/6/19

3 Pys

4s

After Repair photo

11/30

LKK Auto Consultants hence notify the Rep after of the following:

- To respray paint after repair painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Win-Lose" basis
- No illegal modification is allowed
- Supplemental damages or insurance claim is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date: