

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A**AAD1906-230***Not Authored
6/6/2014*

26 JUN 2019

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHF 615A

VF1ABL15AUC278494

RENAULT

LATITUDE

25.6.19

III

27/6/2014

		PART	LIST	
1	1	BUMPER COVER REAR	\$ <i>Part 1</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$ <i>not in</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$ <i>SL</i> 113.47	X
4	1	BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 135.97	X
5	1	BUMPER RETAINER RH REAR	\$ <i>SL</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$ <i>SL</i> 43.61	X
7	1	BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 135.97	X
8	1	BUMPER RETAINER LH REAR	\$ <i>SL</i> 44.99	✓
9	1	BUMPER REFLECTOR LH	\$ <i>SL</i> 43.61	✓
10	1	BUMPER BEAM REAR	\$ <i>R</i> 777.52	X
11	1	BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 225.95	X
13	1	OUTER PANEL REAR (End Panel)	\$ <i>R</i> 1,471.77	✓
14	1	OUTER PANEL REAR (End Panel)TRIM	\$ <i>SL</i> 404.56	} X
15	1	TAILLAMP RH	\$ <i>SL</i> 552.55	
16	1	TAILLAMP PANEL RH	\$ <i>R</i> 986.70	
17	1	TAILLAMP LH	\$ <i>SL</i> 552.55	
18	1	TAILLAMP PANEL LH	\$ <i>R</i> 986.70	
19	1	BOOT REAR	\$ <i>R</i> 2,872.68	
20	1	BOOT FINISHER	\$ <i>SL</i> 470.06	
21	1	BOOT WHEATERSTRIP	\$ <i>SL</i> 323.05	
22	1	BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 493.35	
23	1	BOOT REFLECTOR LAMP RH	\$ <i>SL</i> 493.35	
24	1	BOOT BADGE 'RENAULT'	\$ <i>na</i> 225.36	
25	1	BOOT BADGE	\$ <i>na</i> 225.36	
26	1	BOOT STRUT LH	\$ <i>SL</i> 276.08	
27	1	BOOT STRUT RH	\$ <i>SL</i> 276.08	
28	1	BOOT HINGE LH	\$ <i>R</i> 367.84	
29	1	BOOT HINGE RH	\$ <i>R</i> 367.84	
30	1	BOOT INNER TRIM	\$ <i>SL</i> 586.45	

Trans-cab Auto Services Pte Ltd**AAD1906-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

31	1	BOOT SWITCH	\$	<i>PL</i>	168.13	X
32	1	BOOT LOCK	\$	<i>PL</i>	202.67	X
33	1	BOOT LOCK CATCH	\$	<i>PL</i>	74.40	X
34	1	EXHAUST REAR	\$	<i>PL</i>	7,489.05	X
35	1	EXHAUST CAP REAR	\$	<i>PL</i>	230.49	X
TOTAL			\$		23,766.42	
10%			\$		2,376.64	
			\$		21,389.78	

Special Nett

1	1SET	PARKING AID	\$	<i>PL</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	✓
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	
12	1	EXHAUST MOUNTING REAR	\$	<i>na</i>	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	
14	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	
16	1	BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	
17	1SET	BOOT FINISHER CLIP	\$	<i>na</i>	24.20	
18	1	TAILLAMP CLIP LH	\$	<i>na</i>	5.00	
19	1	TAILLAMP CLIP RH	\$	<i>na</i>	5.00	
TOTAL			\$		1,384.02	

TOTAL PARTS \$ 22,773.80**LABOUR**

To Check Electrical Lighting Concerned.	\$	<i>na</i>	170.00	<i>1d</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i>	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1906-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 <i>20d</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>22d</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>5</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>5</i> 170.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>5</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>5</i> 220.00 <i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>5</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair	\$	<i>5</i> 380.00 <i>X</i>

TOTAL \$ 11,890.00**Over All Total \$ 34,663.80****LUMP SUM (REPAIR DAY)****15 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: