

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0650/06/19
M/s : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD, #04-01
SUNTEC TOWER FIVE
SINGAPORE 038985
Attn :

Page: 1
Date: 26/06/2019

Tan Jiah 97495749
WP
11/7/19 @ 2pm
Lumpsum
Resurvey after repair
4-5 days
suve@hwa.com

Dear Sir/Madam,

ACCIDENT REPAIR ON : SGT6839U - TEANA-2.0 (A) 0
INSURED : CHEN YAW TIONG
DATE OF ACCIDENT : 21/06/2019
YOUR INSURED VEH NO: GBF5122T

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
REPLACEMENT OF PARTS				
	*NETT PRICE			
1	REAR RH DOOR	1 @ 1,098.00	1,098.00	Rx
2	REAR RH DOOR WEATHERSTRIP	1 @ 151.40	151.40	x
3	REAR RH DOOR STICKERS	3 @ 33.10	99.30	x
4	REAR RH FENDER	1 @ 1,288.20	1,288.20	Rx
5	REAR RH FENDER SPLASH SHIELD	1 @ 186.40	186.40	x
6	SPLASH SHIELD RIVETS	6 @ 4.40	26.40	x
	SUB-TOTAL			2,849.70
	*SPECIAL NETT			
7	REAR RH SPORT RIM	1 @ 1,366.00	1,366.00	cut ✓
8	REAR RH TYRE	1 @ 350.00	350.00	x

LABOUR CHARGES

1	REPLACE NEW PARTS, REMOVE/REFIT ALL	400.00	✓
1	ATTACHMENT PARTS TO FACILITATE REPAIR		
1			
2	DISMANTLE AND TRANSFER DOOR FITTINGS	400.00	x
2	AND MECHANISM TO NEW DOOR/FACILITATE		
2	REPAIR.		
2			
3	CHECK WIRING AND PROPER FUNCTIONING	80.00	30.
3			
4	SPRAY PAINT ON THE EFFECTED AREAS	1,200.00	800
4	WITH 2K PAINT.		
4			
5	CHECK AND RE-ADJUST 4 WHEEL ALIGNMENT	120.00	80.

Nett Total Before GST

6,765.70

Yours faithfully,

[Signature]
[Stamp: HIN LUNG WORKSHOP]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: