

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 7129G

DATE : 26.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

India 1 CRPL

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 2,265.90
	Bonnet Insulator Clips	HH		\$ 8.40
	Radiator Grille	broken		\$ 1,110.10
	Radiator Grille H Emblem	dislodged		\$ 120.30
	Front Bumper Cover	broken		\$ 1,052.20
	Front Bumper Sponge	broken		\$ 99.20
	Front Bumper Reinforcement	Decker		\$ 402.10
	Front Bumper Grille (LH)	dislodged		\$ 93.60
	Front Bumper Grille Airduct (LH)	dislodged		\$ 26.20
	Front Bumper Lip	SVC		\$ 54.90
	Front Bumper Bracket Top (LH)	HH		\$ 22.40
	Front Bumper Bracket (LH)	broken		\$ 24.60
	Headlamp Support Panel Assy	broken		\$ 907.40
	Headlamp (LH/RH)	broken / mostly broken	\$ 1,388.00	\$ 2,776.00
	Headlamp Halogen Bulb (LH)	HH		\$ 14.40
	Radiator	BT / punctured		\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy	HH		\$ 792.95
	Radiator Bracket (RH/LH)	HH	\$ 6.50	\$ 13.00
	Radiator Guard, LH	HH		\$ 20.00
	Horn Unit (LH)	broken		\$ 73.80
	Horn Wire	HH		\$ 156.50
	Front Fender (LH)	Decker		\$ 663.00
	Front Fender Apron Panel (LH)	Decker		\$ 637.00
	Front Fender Shield (LH)	dislodged		\$ 174.90
	Aircon Condenser	BT		\$ 927.50
	Front Door Mirror Assy (LH)	HH		\$ 670.00
	Rocker Panel Outer Garnish, LH	HH		\$ 341.40
	Front Windscreen Moulding	HH		\$ 113.30
	Front Windscreen Pillar Outer (LH)	BT		\$ 1,745.50
	Front Wheel Rim (LH)	HH		\$ 325.30
	Front Wheel Hub Cap (LH)	cut		\$ 107.10
	Front Wheel Bearing	BT / Dam		\$ 540.50
	Front Shock Absorber (Assy) (LH)	distorted		\$ 342.20
	Front Shock Absorber Mounting (LH)	HH		\$ 108.80
	Front Drive Shaft (LH)	HH		\$ 1,030.80
	Rack & Pinion Assy	HH / Dam		\$ 1,191.30
	STG Tie End	distorted		\$ 62.60
	Stabilizer Bar	HH		\$ 252.30
	Stabilizer Bar Bush (LH)	HH		\$ 16.40
	Stabilizer Bar Link	HH		\$ 61.10
	Stabilizer Bracket	HH		\$ 24.00
	Front Suspension Lower Arm (LH)	distorted		\$ 529.30
	Front Chassis Member	BT / LH		\$ 1,060.70
	Knuckle Arm (LH)	distorted		\$ 552.00
	Engine Under Cover	HH / torn		\$ 334.60
	Engine Crossmember	distorted		\$ 2,094.40

SHC 7129G

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Inter Cooler <i>ST</i>			\$ 1,032.50
	Wiring-Engine <i>⇒ heavily broken</i>			\$ 3,326.00
	Wiring-Front <i>NH</i>			\$ 1,960.80
	Electric Power Steering <i>NH</i>			\$ 3,641.00