

23/03/2019

A.S. REC. BY:

REF: CS/CT219011456 IRGd302

Special Instruction:

SUNVAJOY RASUL

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CT2 Date/Time: 27.6.19 17:27 PM

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLQ 2M Insured: SLB 6166 M

at Workshop m/s CYL & Carriage Tel: 91265109

of 188 Pandan Loop

Policy No: DMPCSN3040101901 Claim No: SVM19123029 FOC02

Sum Insured: Excess:

Make of Veh: D.O.A 24.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS "up"

Date/Time: 28.6.2019 9:59am Person Contacted: Chai Hoe H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 6166M - X
	SLQ 2M - X
22/8/19	RASUL finalised final fig & 28783.43
	(Red & 5568.71, 16%)

ASSIGNMENT

From:

Date:

28.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLQ 2M

at Workshop n/s cycle & carriage

of 188 Pandan Loop

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ 2M

Yr Regn:

2014 / SEP

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz 25400 (AM)

c.c 2496

Colour:

Black

A/G:

Insured / Std / NI / NA

Sp. Reading:

85222

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W00 222165 2A105 723

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45RF19

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/6/19

D.O.I.

28/06/19

Survey held at

CYCLE & CARRIAGE (PL)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rasul

P/s SEE my remarks.

RECEIVED 28 AUG 2019

27/8/2019

Date/Time, File Pass to?

☐

Preli. Report

1) 28/8/2019

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 16

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

220

Transportation:

5 + RS, 50

Photos

Others

TOTAL

220

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

28783.43

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2019		27 Jun 2019 17:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All				
CLAIM SUBFOLDER DETAILS [Created by insurer]								
Insured:								
Main Claimant:	WANG LIYUN , ID: S71673181							
Vehicle Reg. No.:	SLQ2M	Date of Loss:	24/06/2019 19:00 - :59					
Claim type:	TP / SNM19D202970C02	Policy/Cover Note No.:	DMPCSN3040101901					
Vehicle Reg. No. (Insured):	SLB6166M	Policy No. (Claimant):	S101114322					
		Excess:	S\$2,000.00					
Repaired:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]							
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Appover:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/07/2019]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail								
There are no mail for this case.								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete								
Task Group	Priority	Type	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.								

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 22 August, 2019 12:11 PM
To: 'Yik Chan Hoe'; Tony Lim
Subject: RE: SLQ2M damaged photos and B4 paint photos

Hi Yik,

Finalised amount confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Yik Chan Hoe [<mailto:chanhoe.yik@cyclecarriage.com.sg>]
Sent: Friday, 16 August, 2019 3:45 PM
To: Tony Lim; Rasul (LKKAUTO)
Subject: RE: SLQ2M damaged photos and B4 paint photos

Hi Rasul,

Please take out these 2 items, LH and RH rear fender liner. Final repair cost \$28783.43 before GST.

Thanks & Regards,

Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

From: Tony Lim
Sent: Friday, 16 August, 2019 3:35 PM
To: Yik Chan Hoe; Rasul (LKKAUTO)
Subject: RE: SLQ2M damaged photos and B4 paint photos

Hi Yik,

As attached.

Thank you.

Warmest Regards,

Tony Lim

From: Yik Chan Hoe
Sent: Friday, 16 August 2019 9:09 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Tony Lim <tony.lim@cyclecarriage.com.sg>
Subject: RE: SLQ2M damaged photos and B4 paint photos

Hi Tony,

Kindly assist on the photos.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Friday, 16 August, 2019 9:00 AM
To: Yik Chan Hoe
Subject: RE: SLQ2M damaged photos and B4 paint photos

This email was sent from outside of your organisation

Bro,

Under supplementary parts, do you have damage photos for LH and RH rear fender liner?
Kindy forward to me

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: Yik Chan Hoe [<mailto:chanhoe.yik@cyclecarriage.com.sg>]
Sent: Wednesday, 3 July, 2019 9:47 AM
To: Rasul (LKKAuto)
Cc: SUR
Subject: RE: SLQ2M damaged photos and B4 paint photos

Hi Rasul,

Attached fyn.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

From: Yik Chan Hoe
Sent: Monday, 1 July, 2019 10:58 AM
To: 'Rasul@lkkauto.com'
Cc: 'sur@lkkauto.com'
Subject: SLQ2M damaged photos

Hi Rasul,

Attached fyna.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/06/2019 14:21
Date Of Accident	24/06/2019 19:50
Exact Location Of Accident	MCE TWD CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ2M
Insured/Policyholder	
Name Of Registered Owner	WANG LIYUN
NRIC No	S7167318I
Email Address	ETWOIRENE@ME.COM
Mobile Phone No	(LOCAL) +65-96627433
Alternative Phone No	OFFICE-96627433

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	S400L-3.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101114322
Cover Note Number	

Driver

Name of Driver	WANG LIYUN
NRIC No	S7167318I
Date Of Birth	05/01/1971
Occupation	INDOOR
Date Of Driving Pass	13/04/2007
Driving Experience	12 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96627433
Fax Number	
Contact Number	OFFICE-96627433
EMail Address	ETWOIRENE@ME.COM

Address	BLK 232 YISHUN ST 21 #11-538
Postcode	780232
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : FRIEND GENDER: : MALE
Passenger 2	NAME: : FRIEND GENDER: : MALE
Passenger 3	NAME: : FRIEND GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLANS

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB6166M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on Lane 1 along MCE toward Changi. I applied emergency brake when a car cut in to my lane and jammed brake.

Suddenly vehicle No SLB 6166 M travelling behind me collided on to the rear of my vehicle

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:







Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLQ2M

Wang Li Yun

Blk 232 Yishun Street 21
#11-538
Singapore 760232

Mobile: 92349349

Vehicle & Document Information

WIP No 34567
Reg No/Reg Date SLQ2M / 16/09/2014
Date In/Mileage / 0
Chassis No WDD2221652A105723
Engine No 27682430100628
Make/Model MB/S 400 L BlueEFFICIENCY SE
Colour/Trim 021 197 Obsidian Bl/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	25/06/2019/ 19:24	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request

M BPN50N

POLICY NO/ACC DATE : 5101114322 // 24/06/2019

DRIVE IN/TP VEHICLE NO. : 24/06/2019 // SLB6166M CHINA TAIPING

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH

A BPIRES

RESPRAY BOOT LID, REAR BUMPER AND REAR END PANEL

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE

A BPILAB

REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS

A BPILAB

PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMENT

A BPILAB

REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS

A BPILAB

INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT

M REAR BUMPER

1.00 2139.83 00.00

2139.83

M REAR BUMPER LOWER

1.00 518.33 00.00

518.33

M LEFT REAR BUMPER REFLECTOR

1.00 28.52 00.00

28.52

M RIGHT REAR BUMPER REFLECTOR

1.00 28.52 00.00

28.52

M REAR BUMPER FOG LAMP

1.00 274.59 00.00

274.59

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 16 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal mod. collection is allowed

* Supplementary work(s) must be a record work
Signature: _____
Date: _____

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLQ2M

Wang Li Yun

Blk 232 Yishun Street 21
#11-538
Singapore 760232

Mobile: 92349349

WIP No

34567

Reg No/Reg Date

SLQ2M / 16/09/2014

Date In/Mileage

/ 0

Chassis No

WDD2221652A105723

Engine No

27682430100628

Make/Model

MB/S 400 L BlueEFFICIENCY SE

Colour/Trim

021 197 Obsidian Bl/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	25/06/2019/ 19:24	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR DISTANCE SENSOR ? Aw	6.00	176.11	00.00	1056.66
M REAR PTS SPACER RING	6.00	6.35	00.00	38.10
M CLIP-TYPE NUT	2.00	3.80	00.00	7.60
M LEFT REAR BUMPER MOUNTING RAIL	1.00	48.97	00.00	48.97
M RIGHT REAR BUMPER MOUNTING RAIL	1.00	48.97	00.00	48.97
M REAR BASIC MOUNTING FOR BUMPER	1.00	125.09	00.00	125.09
M LEFT REAR BUMPER MOUNTING RAIL	1.00	82.46	00.00	82.46
M RIGHT REAR BUMPER MOUNTING RAIL	1.00	82.78	00.00	82.78
M REAR SWITCHING MODULE BRACKET	1.00	25.13	00.00	25.13
M LEFT EXHAUST CHROME COVER	1.00	785.22	00.00	785.22
M RIGHT EXHAUST CHROME COVER	1.00	785.22	00.00	785.22
M REAR SWITCH MODULE	1.00	121.95	00.00	121.95
M RIGHT EXHAUST CHROME COVER BRACKET	1.00	78.94	00.00	78.94
M LEFT EXHAUST CHROME COVER BRACKET	1.00	78.94	00.00	78.94
M REAR SWITCH MODULE CODE B	1.00	122.99	00.00	122.99
M REAR SWITCHING MODULE CODE A	1.00	307.73	00.00	307.73
M REAR BUMPER ELECTRICAL WIRING HARNESS	1.00	411.27	00.00	411.27
M BOOT LID CHROME MOULDING	1.00	176.08	00.00	176.08
M BOOT LID MERCEDES STAR	1.00	47.69	00.00	47.69
M MB STAR GROMMET	3.00	2.51	00.00	7.53
M BOOT LID S400 MODEL PLATE	1.00	83.72	00.00	83.72
M BOOT LID LOCK	1.00	813.78	00.00	813.78
M LEFT REAR LAMP COMBINATION	1.00	1048.20	00.00	1048.20
M RIGHT REAR LAMP COMBINATION	1.00	1048.20	00.00	1048.20
M REAR CROSS MEMBER	1.00	1140.89	00.00	1140.89
M REAR END PANEL	1.00	727.93	00.00	727.93
M REAR END PANEL INNER	1.00	372.57	00.00	372.57
M SPARE WHEEL RECESS	1.00	1117.74	00.00	1117.74
M COVER, REAR-END FLOOR	1.00	331.39	00.00	331.39
M RIGHT REAR FENDER COVERING	1.00	37.16	00.00	37.16
M LEFT REAR FENDER COVERING	1.00	37.16	00.00	37.16
M REAR END PANEL GARNISH	1.00	250.62	00.00	250.62
M TS TWO-COMPONENT ADHESIVE	1.00	776.81	00.00	776.81

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

(DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chenhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Nett 29,115.28
7% GST on 29115.28 2038.07
Total Payable 31,153.35

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLQ2M

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 34567
Reg No/Reg Date SLQ2M / 16/09/2014
Date In/Mileage 28/06/2019 / 86500
Chassis No WDD221652A105723
Engine No 27682430100628
Make/Model MB/S 400 L BlueEFFICIENCY SE
Colour/Trim 021 197 Obsidian Bl/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WC000668	Credit	15/08/2019/ 09:47	YK	395 / Yik Chan Hoe					
7 REQUEST Customer Request M.BPNSON POLICY NO/ACC DATE : 5101114322 // 24/06/2019 DRIVE IN/TP VEHICLE NO. : 24/06/2019 // SLB6166M CHINA TAIPING DATE IN/DATE SURVEY: 28/06/2019 @ 1230 // RASUL LKK BY/AUTHORIZED ON : DIRECT SETTLEMENT // ALFRED TOH CHINA TAIPING A BPILAB 4800.00 PANEL BEATING TO REPAIR AFFECTED AREAS. REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH A BPIRES 1800.00 RESPRAY BOOT LID, REAR BUMPER AND REAR END PANEL A BPILAB 480.00 USING XENTRY SYSTEM TO CHECK CONTROL UNITS. RESET SYSTEM TO STANDARD SETTINGS A BPILAB 120.00 CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE A BPILAB 960.00 REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS A BPILAB 1000.00 PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMEN A BPILAB 1920.00 REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS A BPILAB 540.00 INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT A BPILAB 420.00 REMOVE & REPLACE EXHAUST SYSTEM / MUFFLER X REAR BUMPER FOG LAMP 1.00 274.59 00.00 274.59 X REAR PTS SPACER RING 6.00 6.35 00.00 38.10 X CLIP-TYPE NUT 2.00 3.80 00.00 7.60									
THIS IS NOT AN OFFICIAL TAX INVOICE Attn: <u>16</u> Working Days ESTIMATE									

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe-yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLQ2M

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 34567
Reg No/Reg Date SLQ2M / 16/09/2014
Date in/Mileage 28/06/2019/ 86500
Chassis No WDD221652A10572V
Engine No 27682430100628
Make/Model MB/S 400 L BlueEFFICIENCY SE
Colour/Trim 021 197 Obsidian B1/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	15/08/2019/ 09:47	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BOOT LID CHROME Moulding	1.00	176.08	00.00	176.08
X BOOT LID MERCEDES STAR	1.00	47.69	00.00	47.69
X MB STAR GRONNET	3.00	2.63	00.00	7.68
X BOOT LID S400 MODEL PLATE	1.00	83.72	00.00	83.72
X BOOT LID LOCK	1.00	813.78	00.00	813.78
X LEFT REAR LAMP COMBINATION	1.00	1048.20	00.00	1048.20
X RIGHT REAR LAMP COMBINATION	1.00	1048.20	00.00	1048.20
X REAR CROSS MEMBER	1.00	1140.89	00.00	1140.89
X REAR END PANEL	1.00	727.93	00.00	727.93
X TS TWO-COMPONENT ADHESIVE	1.00	776.81	00.00	776.81
X REAR BUMPER	1.00	2649.27	00.00	2649.27
X REAR BUMPER LOWER	1.00	666.54	00.00	666.54
X REAR SWITCH MODULE	1.00	121.95	00.00	121.95
X REAR SWITCH MODULE CODE B	1.00	122.99	00.00	122.99
X REAR BASIC MOUNTING FOR BUMPER	1.00	125.09	00.00	125.09
X LEFT REAR BUMPER MOUNTING RAIL	1.00	82.46	00.00	82.46
X RIGHT REAR BUMPER MOUNTING RAIL	1.00	82.78	00.00	82.78
X REAR DISTANCE SENSOR	3.00	176.11	00.00	528.33
X LEFT EXHAUST CHROME COVER BRACKET	1.00	78.85	00.00	78.85
X LEFT EXHAUST CHROME COVER	1.00	933.72	00.00	933.72
X REAR BUMPER ELECTRICAL WIRING HARNESS	1.00	411.27	00.00	411.27
X LEFT REAR BUMPER MOUNTING RAIL	1.00	21.80	00.00	21.80
X REAR SWITCHING MODULE CODE A	1.00	307.73	00.00	307.73
X LEFT REAR BUMPER REFLECTOR	1.00	47.75	00.00	47.75
X REAR BUMPER UNDER BRACKET	1.00	182.04	00.00	182.04
X [STR] RIVET	6.00	3.17	00.00	19.02
X RIVET	48.00	2.51	00.00	120.48
X RIVET	9.00	5.69	00.00	51.21
X BLIND RIVET	36.00	1.29	00.00	46.44
X SEAM SEAL	2.00	104.99	00.00	209.98
X REAR BUMPER LOWER DISFUSER	1.00	624.73	00.00	624.73
X LEFT REAR EXHAUST MUFFLER	1.00	2909.48	00.00	2909.48
X REAR BUMPER LOWER CHROME TRIM STRIP	1.00	208.40	00.00	208.40

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe-yik@cyclocarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SLQ2M

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
6222368

Vehicle & Document Information

WIP No 34567
Reg No/Reg Date SLQ2M / 16/09/2014
Date In/Mileage 28/06/2019/ 86500
Chassis No WDD2221652A10572V
Engine No 27682430100628
Make/Model MB/S 400 L BlueEFFICIENCY SE
Colour/Trim 021 197 Obsidian B1/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	15/08/2019/ 09:47	YK	395 / Yik Chan Hoe
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount
X LEFT REAR FENDER LINER	1.00	222.54	00.00	222.54
X RIGHT REAR FENDER LINER	1.00	222.54	00.00	222.54

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclocarriage.com.sg

Confirmed & accepted by

Nett 29,228.51
7% GST on 29228.51 2046.00
Total Payable 31,274.51

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SLQ2M

SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 34567
Reg No/Reg Date SLQ2M / 16/09/2014
Date In/Mileage 28/06/2019/ 86500
Chassis No WDD2221652A105723
Engine No 27682430100628
Make/Model MB/S 400 L BlueEFFICIENCY SE
Colour/Trim 021 197 Obsidian Bl/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	15/08/2019/ 09:48		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A BPTLAB				420.00
REAR BUMPER LOWER CHROME TRIM STRIP	1.00	182.04	00.00	182.04
X [STR] RIVET	6.00	3.17	00.00	19.02
X RIVET	48.00	2.51	00.00	120.48
X RIVET	9.00	5.69	00.00	51.21
X BLIND RIVET	36.00	1.29	00.00	46.44
X SEAM SEAL	2.00	104.99	00.00	209.98
X REAR BUMPER LOWER DISFUSER	1.00	624.73	00.00	624.73
X LEFT REAR EXHAUST MUFFLER	1.00	2909.48	00.00	2909.48
X REAR BUMPER LOWER CHROME TRIM STRIP	1.00	208.40	00.00	208.40
X LEFT REAR FENDER LINER	1.00	222.54	00.00	222.54
X RIGHT REAR FENDER LINER	1.00	222.54	00.00	222.54

ESTIMATE

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett	5,236.86
7% GST on	366.58
Total Payable	5,603.44

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2019		27 Jun 2019 17:27 Edit Adj Rpt	\$528,783.43 Edit Estimates	\$528,783.43 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	WANG LIYUN , ID: 571673181								
Vehicle Reg. No.:	SLQ2M	Date of Loss:	24/06/2019 19:00 - :59 [57 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202970C02	Policy/Cover Note No.:	DMPCSN3040101901						
Vehicle Reg. No. (Insured):	SLB6166M	Policy No. (Claimant):	5101114322						
		Excess:	S\$2,000.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ2M (SNM19D202970C02)
[SLB6166M]

TP

WANG LIYUN

Jun 24 2019 7:00PM

[-]

Cycle & Carriage Industries Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
1	25/06/19 14:30	Accident Statement	 Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
1	25/06/19 14:28	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	25/06/19 14:28	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	25/06/19 14:28	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	25/06/19 14:28	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	25/06/19 14:28	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	25/06/19 14:28	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/19 12:12	Odometer Reading	 Load JPG	☒
2	27/08/19 12:12	Chassis Number	 Load JPG	☒
3	27/08/19 12:12	General View	 Load JPG	☒
4	27/08/19 12:12	General View	 Load JPG	☒
5	27/08/19 12:12	General View	 Load JPG	☒
6	27/08/19 12:12	General View	 Load JPG	☒
7	27/08/19 12:12	General View	 Load JPG	☒
8	27/08/19 12:12	General View	 Load JPG	☒
9	27/08/19 12:12	General View	 Load JPG	☒
10	27/08/19 12:12	General View	 Load JPG	☒
11	27/08/19 12:12	General View	 Load JPG	☒
12	27/08/19 12:12	General View	 Load JPG	☒
13	27/08/19 12:12	General View	 Load JPG	☒
14	27/08/19 12:12	General View	 Load JPG	☒
15	27/08/19 12:12	General View	 Load JPG	☒
16	27/08/19 12:12	General View	 Load JPG	☒
17	27/08/19 12:12	General View	 Load JPG	☒
18	27/08/19 12:12	General View	 Load JPG	☒
19	27/08/19 12:12	General View	 Load JPG	☒
20	27/08/19 12:12	General View	 Load JPG	☒
21	27/08/19 12:12	General View	 Load JPG	☒
22	27/08/19 12:12	General View	 Load JPG	☒
23	27/08/19 12:12	General View	 Load JPG	☒
24	27/08/19 12:12	General View	 Load JPG	☒
25	27/08/19 12:12	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
26	27/08/19 12:12	General View	 Load JPG	☒
27	27/08/19 12:12	General View	 Load JPG	☒
28	27/08/19 12:12	General View	 Load JPG	☒
29	27/08/19 12:12	General View	 Load JPG	☒
30	27/08/19 12:12	General View	 Load JPG	☒
31	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
32	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
33	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
34	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
35	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
36	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
37	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
38	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
39	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
40	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
41	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
42	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
43	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
44	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
45	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
46	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
47	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
48	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
49	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
50	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
51	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
52	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
53	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
54	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
55	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
56	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
57	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
58	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
59	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
60	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
61	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
62	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
63	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
64	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
65	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
66	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
67	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
68	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
69	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
70	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
71	27/08/19 12:12	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/06/19 17:30	TP REPAIR ESTIMATE - SLQ2M	 Load PDF	
2	27/06/19 17:30	PRS - SLQ2M	 Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
1	25/06/19 14:28	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	25/06/19 14:28	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/08/19 14:08	Supplementary	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
1	25/06/19 14:30	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
1	25/06/19 14:28	Accident Photo	Load JPG ☒	
2	25/06/19 14:28	Accident Photo	Load JPG ☒	
3	25/06/19 14:28	Accident Photo	Load JPG ☒	
4	25/06/19 14:28	Accident Photo	Load JPG ☒	
5	25/06/19 14:28	Accident Photo	Load JPG ☒	
6	25/06/19 14:28	Accident Photo	Load JPG ☒	
Documentation			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Pandan)	Thumbnail	Print
1	25/06/19 14:28	Sketch Plan	Load TIF	
2	25/06/19 14:28	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011456/R1QD3E2

Date: 28/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3040101901

Claimant Vehicle
No: SLQ2MInsured Vehicle
No: SLB6166M

Date of Loss: 24/06/2019

Nature of Claim: TP

Claim
No: SNM19D202970C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ2M

Make & Model: MERCEDES-BENZ S400L, 3.0 (A)

Reg. Date: 16/09/2014 (Man. Year: 2014)

Colour: Black

Engine Capacity: 2996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 27682430100628

Chassis No: WDD2221652A105723

Odometer: 85222 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45RF19

Rear Tyre Size: 245/45RF19

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,857.52	16,743.43	4,114.09	19.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,320.00	12,040.00	2,280.00	15.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,177.52	28,783.43	6,394.09	18.18
+ GST 7.00/7.00% (S\$)	2,462.43	2,014.84	447.59	18.18
Nett Amount (S\$)	37,639.95	30,798.27	6,841.68	18.18

INSPECTION

Date of Assignment: 27/06/2019

Date Inspected: 28/06/2019 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 16.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2019)
Parts:	143	MERCEDES-BENZ S400L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ2M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	2,649.27 FS	*2,649.27 FS
2	1	*REAR BUMPER LOWER	Missing	666.54 FS	*666.54 FS
3	1	*LEFT REAR BUMPER REFLECTOR	Missing	47.75 FS	*47.75 FS
4	1	*RIGHT REAR BUMPER REFLECTOR	Serviceable	28.52 FS	*- FS
5	1	*REAR BUMPER FOG LAMP	Missing	274.59 FS	*274.59 FS
6	1	*REAR DISTANCE SENSOR (6PCS)	Not Working-3pc only	1,056.66 FS	*528.33 FS
7	6	*REAR PTS SPACER RING	Necessary	38.10 FS	*38.10 FS
8	2	*CLIP-TYPE NUT	Necessary	7.60 FS	*7.60 FS
9	1	*LEFT REAR BUMPER MOUNTING RAIL	Bent	48.97 FS	*21.80 FS
10	1	*RIGHT REAR BUMPER MOUNTING RAIL	Serviceable	48.97 FS	*- FS
11	1	*REAR BASIC MOUNTING FOR BUMPER	Bent	125.09 FS	*125.09 FS
12	1	*LEFT REAR BUMPER MOUNTING RAIL	Bent	82.46 FS	*82.46 FS
13	1	*RIGHT REAR BUMPER MOUNTING RAIL	Bent	82.78 FS	*82.78 FS
14	1	*REAR SWITCHING MODULE BRACKET	Serviceable	25.13 FS	*- FS
15	1	*LEFT EXHAUST CHROME COVER	Bent	933.72 FS	*933.72 FS
16	1	*RIGHT EXHAUST CHROME COVER	Serviceable	785.22 FS	*- FS
17	1	*REAR SWITCH MODULE	Not Working	121.95 FS	*121.95 FS
18	1	*RIGHT EXHAUST CHROME COVER BRACKET	Serviceable	78.94 FS	*- FS
19	1	*LEFT EXHAUST CHROME COVER BRACKET	Necessary	78.94 FS	*78.85 FS
20	1	*REAR SWITCH MODULE CODE B	Not Working	122.99 FS	*122.99 FS
21	1	*REAR SWITCHING MODULE CODE A	Not Working	307.73 FS	*307.73 FS
22	1	*REAR BUMPER ELECTRICAL WIRING HARNESS	Cut	411.27 FS	*411.27 FS
23	1	*BOOT LID CHROME MOULDING	Necessary	176.08 FS	*176.08 FS
24	1	*BOOT LID MERCEDES STAR	Necessary	47.69 FS	*47.69 FS
25	3	*MB STAR GROMMET	Necessary	7.53 FS	*7.53 FS
26	1	*BOOT LID S400 MODEL PLATE	Necessary	83.72 FS	*83.72 FS
27	1	*BOOT LID LOCK	Cut	813.78 FS	*813.78 FS
28	1	*LEFT REAR LAMP COMBINATION	Cut	1,048.20 FS	*1,048.20 FS
29	1	*RIGHT REAR LAMP COMBINATION	Cracked	1,048.20 FS	*1,048.20 FS
30	1	*REAR CROSS MEMBER	Bent	1,140.89 FS	*1,140.89 FS
31	1	*REAR END PANEL	Bent	727.93 FS	*727.93 FS
32	1	*REAR END PANEL INNER	Serviceable	372.57 FS	*- FS
33	1	*SPARE WHEEL RECESS	Serviceable	1,117.74 FS	*- FS
34	1	*COVER, REAR-END FLOOR	Serviceable	331.39 FS	*- FS
35	1	*RIGHT REAR FENDER COVERING	Serviceable	37.16 FS	*- FS
36	1	*LEFT REAR FENDER COVERING	Serviceable	37.16 FS	*- FS
37	1	*REAR END PANEL GARNISH	Serviceable	250.62 FS	*- FS
38	1	*TS TWO-COMPONENT ADHESIVE	Necessary	776.81 FS	*776.81 FS
39	1	*REAR BUMPER UNDER BRACKET	Necessary	182.04 FS	*182.04 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	6		*[STR] RIVET	Necessary	19.02 FS	*19.02 FS
41	1		*RIVET (48PCS)	Necessary	120.48 FS	*120.48 FS
42	9		*RIVET	Necessary	51.21 FS	*51.21 FS
43	1		*BLIND RIVET (36PCS)	Necessary	46.44 FS	*46.44 FS
44	2		*SEAM SEAL	Necessary	209.98 FS	*209.98 FS
45	1		*REAR BUMPER LOWER DISFUSER	Cracked	624.73 FS	*624.73 FS
46	1		*LEFT REAR EXHAUST MUFFLER	Bent	2,909.48 FS	*2,909.48 FS
47	1		*REAR BUMPER LOWER CHROME TRIM STRIP	Scratched	208.40 FS	*208.40 FS
48	1		*LEFT REAR FENDER LINER	Serviceable	222.54 FS	*- FS
49	1		*RIGHT REAR FENDER LINER	Serviceable	222.54 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 20,857.52 16,743.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	5,760.00	4,800.00
2	RESPRAY BOOT LID, REAR BUMPER AND REAR END PANEL	New	2,400.00	1,800.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS	New	480.00	480.00
4	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
5	PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMEN	New	1,000.00	1,000.00
6	REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS	New	2,400.00	1,920.00
7	INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT	New	540.00	540.00
8	REMOVE & REPLACE EXHAUST SYSTEM / MUFFLER	New	420.00	420.00
9	REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS	New	1,200.00	960.00
Gross Labour Cost (S\$)			14,320.00	12,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >