

ASS. REC. BY:

REF: CS/SMO/01463/ Etd3n2

Special Instruction:

Survivor: Steve

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi of SMD Date/Time: 28.6.19 11.129.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGS 2717U Insured: SMD 1297D

at Workshop in/s Sun Tex Auto Tel: 67556210

of BK 1019 # 01-388 Yishun

Policy No: DIGMTPV 01013915 Claim No: CM171902868

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 28.6.19 11.199.m Person Contacted: Dev H.O.D. Endorsement: _____
Vehicle IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>SMD 1297D : X</u>
	<u>SGS 2717U : NS/INC13011521/H1+J2</u>
<u>12/7-</u>	<u>Revised via merimen preli advise</u>

ASS. REC. BY: Steve

REF SMO

ASSIGNMENT

From:

Date: 11.7.2019Veh No: SGS 27174Yr Regn: 03 07

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SGS 27174Make: Toyota Rush c.c. 1495at Workshop m/s San Tre AutoColour: Black A/C: Insured / Std / NI / NAof Blk 1019 # 01-388 Uishun Industrial ParkSp. Reading: 169255 T/Radio: Insured / Std / NI / NAInsured: A

Eng/No:

Policy No.

C/No: J290E-0011135

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)


Brake: Inorder / Jammed / Leaked / Burnt orMake of Veh: 10:00am - 11:00am owner waitingModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/65R16R: "

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 5 mmR/Bal. 5 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 5 mmL/Bal. 5 mm

Est. Repairs: days Res.: Yes or No

D.O.A. 12/6/19D.O.I. 11/7/19

Lum Sum: % 3 Val.: Yes or No

Survey held at San Tre Auto

CA / REV / REP. / 24 HRS

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/7/19 PARF value cannot print out
Finalise confr- \$900, 2 days (Red: 2479.80: 73%)

RECEIVED 30 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report1) 29/7 Typist☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: -

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format : TPLump Sum / I.B.I. (\$) 90025011261

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 12 Jul 2019

Preliminary Advice

Insured Vehicle No	: SMD1297D	Accident Date	: 12/06/2019
TP Vehicle No	: SGS2717U	Assignment Date	: 28/06/2019
Make	: TOYOTA RUSH	Est. Duration of Repair	: 2.00
Date of Inspection	: 11/07/2019		
Inspection At	: SAN TEE AUTO PTE LTD (HQ) BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,379.80
Revised Amount	:S\$	1,503.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,503.90

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2019		28 Jun 2019 11:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

Main Claimant:

Vehicle Reg. No.:

Claim Type:

Vehicle Reg. No. (Insured):

Repairer:

Handling Insurer:

Adjuster:

Driver/Custodian (Insured):

Adj Asg. Remarks:

WONG WENG FATT, ID: S1527270H

THE TITULAR ROMAN CATHOLIC ARCHBISHOP OF SINGAPORE,

SGS2717U

TP / CMTD1902868

SMD1297D

San Tee Auto Pte Ltd (HQ) BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A, 768761 Yishun - Tel: 67538276

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/07/2019]

RACHAEL WONG KA LI (), NRIC: S9445302Z, Tel: +6581800792 Email:

WS: MS DEVI 67556210/ 67538276

[Created by insurer]

Co. Reg. No.: S1360564E

Date of Loss: 12/06/2019 20:00 - :59

Policy/Cover Note No.: D18MTPV01013915 (Comprehensive)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Steve Chen (LKK Auto)

From: santeeauto@singnet.com.sg
Sent: Thursday, July 25, 2019 11:10 AM
To: Steve Chen (LKK Auto)
Subject: Re: SGS2717U Finalize

Dear Steve

Ok , we are agreeable to the above offer. Please advise where shall I send the invoice to.

Regards

Devi

SAN TEE AUTO PTE LTD BLK 1019, YISHUN INDUSTRIAL PARK A #01-388 SINGAPORE 768761 Tel : 67556210/67538276 Fax : 67592034

On Tue Jul 23 2019 10:57:32 GMT+0800 (Malay Peninsula Standard Time) Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

----- Original Message -----

Hi Devi,

1)

Tow hook cover no I don't have photo.

2)

Bumper retainer LH and RH u no put in the estimate, I cannot recommend.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com

| fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

santeeauto@singnet.com.sg [<mailto:santeeauto@singnet.com.sg>]

Sent: Tuesday, July 23, 2019 10:04 AM

To: Steve Chen (LKK Auto)

Subject: Re: SGS2717U Finalize

Dear Steve

Your finalize repair cost is too low. As we have some more items changed which was not included in the quotation.

1) Tow hook cover

2) Bumper retainer 2 pcs

Please update us with details.

Regards

Devi

SAN TEE AUTO PTE LTD BLK 1019, YISHUN INDUSTRIAL PARK A #01-388
SINGAPORE 768761 Tel : 67556210/67538276 Fax : 67592034

On Tue Jul 23 2019 08:57:26 GMT+0800 (Malay Peninsula Standard Time)
Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

----- Original Message -----

Dear Devi,

We have come out with the finalize \$900 (L/S, before GST). 2 repair days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen| Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561| Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Club/Association/Organisation
Owner ID:	4023D
Vehicle Details	
Vehicle No.:	SGS2717U
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	RUSH 1.5 A
Primary Colour:	Green
Manufacturing Year:	2007
Engine No.:	3SZ1750941
Chassis No.:	J200E0011135
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,331.00
Original Registration Date:	09 Mar 2007
First Registration Date:	09 Mar 2007
Transfer Count:	2
Actual ARF Paid:	\$16,865.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$50,394.00
COE Rebate Amount:	\$38,455.00
Total Rebate Amount:	\$38,455.00

The information contained herein is correct as at 12 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/06/2019 16:50
Date Of Accident	12/06/2019 08:30
Exact Location Of Accident	SPC PETROL STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGS2717U
Insured/Policyholder	
Name Of Registered Owner	THE TITULAR ROMAN CATHOLIC ARCHBISHOP OF SINGAPORE
Co Reg No	0
Email Address	FRAUGUSTINE1005@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-92489790

Vehicle Particulars

Manufacturer	TOYOTA
Model	RUSH-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29113229 MCY
Cover Note Number	

Driver

Name of Driver	AUGUSTINE JOSEPH
NRIC No	S1360564E
Date Of Birth	27/08/1959
Occupation	OUTDOOR
Date Of Driving Pass	27/09/1999
Driving Experience	19 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92489790
Fax Number	
Contact Number	
Email Address	SHARON.TAN@CATHOLIC.ORG.SG

Address	BLK 123 YISHUN STREET 11 #03-509
Postcode	760123
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD1297D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


1. Police would certainly be called to the incident (3 weeks to the court process)
2. The form will be completed by the Policyholder and/or the Authorized Driver
3. Information provided must be truthful and accurate as possible. Any willful misstatements or omissions may constitute insurance fraud and may be considered to constitute policy violation
4. The vehicle is expected to bring a full and complete disclosure of all accidents, claims, and violations of traffic laws, including any violations of traffic laws, during the entire policy term.
5. Any false statements may be referred to the Police for investigation.
6. The vehicle will be taken to the Police at the Police Station and the driver will be taken to the Police Station and the driver will be taken to the Police Station and the driver will be taken to the Police Station.
7. The vehicle will be taken to the Police at the Police Station and the driver will be taken to the Police Station and the driver will be taken to the Police Station.
8. Content under the Personal Data Protection Act (PDPA)

Driver's signature _____
 Driver's name (please print) _____
 Date & Time _____



姓名：_____
 学号：_____
 班级：_____

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

After pumping petrol, I drove to exit the petrol station, then there was a vehicle parked in front, as such I parked and waited + then suddenly she reversed her car and hit the front part of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)

Date & Time: 13-06-19, 1.58pm



[Signature]

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:



THE TITULAR ROMAN
CATHOLIC ARCHBISHOP
OF SINGAPORE

Archdiocesan House
31 Victoria Street
Singapore 188067

Tel: +65 6350 1512
Fax: +65 6350 1501
www.sga.org.sg

14 June 2019

To Whom It May Concern

Dear Sir/Mdm,

Rev Fr Augustine Joseph
Vehicle Reg No: SGS 2717U
Period of Insurance: 1 January 2019 to 31 December 2019

Kindly be advised that our priest Rev Fr Augustine Joseph is our Authorized Driver for our vehicle- Vehicle Registration No **SGS 2717U**

This is also to confirm that our Motor Insurance Company is MSIG Insurance (Singapore) Pte Ltd.

Yours in Christ,

Sharon Tan
Archdiocesan Office for Human Resource
Manager- Insurance

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel: +65 6827 7868, Fax: +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.4
 Company Ownership

MOTORMAX PLUS-COMMERCIAL
 Comprehensive

Certificate No. B 29113229 MCY

Excess : SGD500
 Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SGS2717U
2. Name of Policyholder
The Titular Roman Catholic Archbishop of Singapore
3. Effective Date of the Commencement of Insurance for the purposes of the Act
01/01/2019
4. Date of Expiry of Insurance
31/12/2019
5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the policyholder's business.
 The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers

for Chief Executive Officer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

SAN TEE AUTO PTE LTD

BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A SINGAPORE 768761

TEL: (65)67538276 FAX: (65)67592034 H/P: (65)97232449

EMAIL: santeeauto@singnet.com.sg

TO: SOMPO INSURANCE

DATE :

10-Jul-19

ATTN : 3RD PARTY CLAIM / DIRECT SETTLEMENT

RE: 3RD PARTY CLAIM VEHICLE NO. SGS2717U AND SMD1297D AT SPC PETROL STATION

S/NO	DESCRIPTION	AMOUNT
		\$
1	FRONT BUMPER ✓ DD	1077.90 995.45 ✓
2	FRONT GRILLE ✗ NAI	695.90 ✗
3	FRONT NO. PLATE ✓ CR4	26.00 ✓
	LABOUR TO REPLACE FRONT BUMPER AND RETAINERS, CLIPS ETC ALIGNMENT,	680.00 200
	LABOUR TO SPRAY PAINT FRONT BUMPER AND AFFECTED AREA	900.00 200
		400
		995.45 - 25% 746.58
		\$3,379.80

Steve CLKK)
83228813
Steve Chen @ lkkauto.com

WHL 11/7/19
2 days
L/S
Rin AF spy

11/7/19
11:30am

O - 746.58
L - 400
1,146.58

L/S - 917.26
= 900

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19011463/ETD3N2

Date: 01/08/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01013915
Claimant Vehicle No :	SGS2717U	Insured Vehicle No :	SMD1297D
Date of Loss:	12/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1902868

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS2717U	Engine No:	3SZ1750941
Make & Model:	TOYOTA RUSH, 1.5 (A)	Chassis No:	J200E0011135
Reg. Date:	09/03/2007 (Man. Year: 2007)	Odometer:	169255 km
Colour:	Black		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R16	Rear Tyre Size:	215/65R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,799.80	766.09	1,033.71	57.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	400.00	1,180.00	74.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,379.80	1,166.09	2,213.71	65.50
Approved Total (Overridden) (\$\$)		900.00		
Nett Amount (\$\$)	3,379.80	900.00	2,479.80	73.37

INSPECTION

Date of Assignment:	28/06/2019	
Date Inspected:	11/07/2019	Inspected At: San Tee Auto Pte Ltd (HQ) BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2019)
Parts:	M1-SUV	TOYOTA RUSH 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGS2717U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,077.90 F	*995.45 FL
2	1		*FRONT GRILLE	Not Necessary	695.90 F	*- FL
3	1		*FRONT NO PLATE	Crushed	26.00 F	*26.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	1,799.80
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00
					Total Parts (\$\$)	1,799.80
						766.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REPLACE FRONT BUMPER AND RETAINERS,CLIPS ETC ALIGNMENT	New	680.00	200.00
2	LABOUR TO SPRAY PAINT FRONT BUMPER AND AFFECTED AREA	New	900.00	200.00
Gross Labour Cost (S\$)			1,580.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >