

INSURER

INS. CASE OWNER

CC 4/AIG1901 1467, A 1467, A 1467

LKK

IDAC

Surveyor:

Adrian

DOI:

ASSIGNMENT

17/6/19

Date / Time:

24/6/19

Registered in Merimen:

28/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJA 3629T

Name of Insured:

APEX CAR LEASING

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

24/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LAW ZHONG WEI

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

59827474159

Policy No.:

999994110

Make / Model:

Honda

Place of Accident:

SEKANGSON RD.

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJK 739AD

SJA 3629T

SUB 1725H

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

28/11/19
Khuncho

File pass to Sun Pei to close

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OE:

After call 1st to OE: 21/10/19

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45 SS 4,400

(7 days) Reduction:

28

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

0/00

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

(4487)

SS

4,308

Loss of Rental (LOR):

SS

4,149

(7 days) v \$ 100

Loss of Use (LOU):

SS

-

(5 - 7 days)

Loss of Income (LOI):

SS

-

(5 - 7 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

SS

10

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost:

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320

Total:

SS

5,467

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5,467

Name 1:

KANG CAR REPAIRERS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Accident

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLB1725H Yr Regn: 2016 March
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime-Mover /
 Truck / Trailer or

Make: Hyundai Accent cc 1368
 Colour: Black A/C: Insured / Std / Nil / NA
 Sp. Reading 80840 T/Radio: Insured / Std / Nil / NA

Eng/No: _____
 C/No: KMHCTS1BL64251140

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R16

R: 205/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>27/06/19</u>

Survey held at Kany

Des. of Damages: Frt / Rear / S / N / S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG

CL / S\$4,400 / Red \$1,718.40 / 28/1)

MV :

PV :

Nett :

Date/Time, File Pass to?

Date/Time, File Return to?

1)	2)
3)	4)
5)	6)
Pre Report:	
Final Report:	

Part Prices Check:

IN OUT

Survey Fee:

Date:

Basic & Add.
 S + RS, SI
 Photos
 Others
 TOTAL

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900192
Date: 26 Jun 2019
Veh Reg No: SLB1725H
Make/Model: HYUNDAI ACCENT
(RB) 5DR 1.4MT
Chasis No: KMHCT51BLGU251140
Reg. Date: 30/03/2016
Your Ref No: SJA3629T

Claim Type: Third Party
Accident Date: 24/06/2019
TP Veh Reg No: SJA3629T

Estimate Repair Cost to Vehicle No :SLB1725H

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC BOOT LID <i>Dented</i>	1,303.20 ✓	
2	1 PC BOOT LID LOGO <i>Ne</i>	23.30 ✓	
3	1 PC BOOTLID "ACCENT" EMBLEM <i>nee</i>	31.20 ✓	
4	1 PC BOOT LID LOCK <i>Dented</i>	166.80 ✓	
5	1 PC BOOT LID LOCK CHECKER <i>nee</i>	12.00 ✓	
6	1 PC BOOT LID RUBBER <i>ut</i>	82.60 ✓	
7	1 PC BOOT LID TRIM <i>at 2miled</i>	58.20 ✓	
8	1 PC TAIL LAMP LH <i>ut</i>	326.30 ✓	
9	1 PC TAIL LAMP - RH <i>2miled</i>	326.30 ✓	
10	1 PC REAR PANEL <i>Dented</i>	499.30 ✓	
11	1 PC REAR PANEL TRIM <i>Deformed</i>	115.10 ✓	
12	1 PC REAR BUMPER <i>Dented</i>	466.40 ✓	
13	1 PC REAR BUMPER REINFORCEMENT <i>2miled</i>	365.40 ✓	
14	2 PCS REAR BUMPER LOWER BRACKET <i>2miled</i>	33.40 ✓	
15	2 PCS REAR BUMPER SIDE RETAINER <i>ne</i>	48.60 ✓	
16	1 PC REAR BUMPER REFLECTOR - LH <i>ut</i>	53.40 ✓	
17	1 PC REAR BUMPER REFLECTOR - RH <i>2miled</i>	53.40 ✓	
18	2 PCS REAR NUMBER PLATE LAMP <i>2miled</i>	70.60 ✓	
	<i>2pc in bumper bracket 98.70 x 2</i>	4,035.50	
	<i>Less 20%</i>	807.10	3,228.40
Special Net			
19	1 SET BOOTLID TRIM CLIPS <i>nee</i>	40.00 ✓	
20	1 PC REAR WINDSCREEN SEAL <i>2miled</i>	60.00 ✓	
21	1 PC REAR WINDSCREEN SEALANT <i>2miled</i>	60.00 ✓	
22	1 SET REAR PANEL TRIM CLIPS <i>nee</i>	30.00 ✓	
23	1 SET REVERSE SENSORS <i>Dented</i>	250.00 ✓	
24	1 PC REAR NUMBER PLATE <i>Bent</i>	50.00 ✓	
		490.00	490.00
		380	
Labour			

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 24/06/2019
TP Veh Reg No: SJA3629T

Estimate No: EST1900192
Date: 26 Jun 2019
Veh Reg No: SLB1725H
Make/Model: HYUNDAI ACCENT
(RB) 5DR 1.4MT
Chassis No: KMHCT51BLGU251140
Reg. Date: 30/03/2016
Your Ref No: SJA3629T

Estimate Repair Cost to Vehicle No :SLB1725H

Quantity	Description	List Price	Amount
		SS	SS
25	1 TO CHECK WIRING	50.00 30	
26	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
27	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 40	
28	1 TO SPRAY UNDERSEAL	150.00 60	
29	1 (REAR) TO SPRAY PAINTING	1,000.00 820	
30	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 820	
		2,400.00	2,400.00
	Total		S\$ 6,118.40
	Add GST @ 7%		428.29
	Total Amount Payable		S\$ 6,546.69

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED FORTY SIX AND CENTS SIXTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian Limy total: S\$ 6,546.69
L/S 27/06/19 L/S: 4 HIC.
of Rep.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

19/06/2019

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 11 November 2019 5:23 PM
To: kangcar@singnet.com.sg
Cc: Admin A
Subject: RE: LOD : ACCDT INVLG SLB1725H & SJA3629T9AIG) ON 24.06.2019

Tracking:	Recipient	Delivery
	kangcar@singnet.com.sg	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 11/11/2019 5:24 PM
	shupei@lkkauto.com	Delivered: 11/11/2019 5:24 PM
	olivialau@lkkauto.com	Delivered: 11/11/2019 5:24 PM

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

For amicable settlement on a without prejudice basis, we propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 4,708.00
2. Loss of Rental (7 days x \$100)(w/GST)	\$ 749.00
3. LTA Search Fee	\$ 10.00
Total	\$ 5,467.00

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Suwanna (LKK Auto) <Suwanna@lkkauto.com>
Sent: Wednesday, 11 September 2019 4:30 PM
To: kangcar@singnet.com.sg
Cc: Khanchna (LKK Auto) <khanchna@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: LOD : ACCDT INVLG SLB1725H & SJA3629T9AIG) ON 24.06.2019

PRE-REPAIR INSPECTION REQUEST – SLB1725H vs SJA3629T (OI) on D.O.A.: 24/06/2019

From: Hor, Yinnul
 To: 'wsgmments@kkauto.com', Admin A (admin-a@kkauto.com)
 Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Ton
 Date: Thursday, 27 June 2019 3:52:09 PM
 Attachments: [SLB1725H vs SJA3629T.PDF](#)

Hi,

Please refer to the enclosed request from **Kang Car Repairers Pte Ltd**.

Claim no : 5982942741SG005
 Case Owner : Wan Nur Saliha Binte Syed Yusoff

If you have any queries/concerns, please let us know.
 Kindly assist to assign **Adrian Ling** as **Single Joint Expert** as requested.

Thanks & Regards,

Yinnul Hor (Vivante)

Senior Manager - Singapore PTD, Claims Operations – Auto
yinnul.hor@kkauto.com www.kkauto.com

From: kangcar@singnet.com.sg [mailto:kangcar@singnet.com.sg]

Sent: Thursday, June 27, 2019 3:38 PM

To: Hor, Yinnul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; kangcar@singnet.com.sg

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJA3629T AND SLB1725H ON 24/06/2019

Without Prejudice

Dear Vivante,

We refer to the email below.

Please appoint Adrian Ling from LKK Auto Consultants Pte Ltd to conduct the pre repair survey on our client's vehicle.

Thank you & Regards,

Sharon

Kang Car Repairers Pte Ltd

From: Hor, Yinnul

Sent: Thu, 27 Jun 2019 00:43:51 +0000

To: kangcar@singnet.com.sg

Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Wahxin

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJA3629T AND SLB1725H ON 24/06/2019

Without Prejudice

Your Reference : KCR0620191725AIG

Our Reference : SJA3629T

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

P. Sharon

T: 428 p.m

V: 11

E: ✓

We intend to conduct a pre-repair survey of the damage to your client's/customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Long Kun	Priority Services
Sammy Lee	Priority Services
EC Lee	Automobile Inspection Services Pte Ltd
Ping Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng Yau Han	Formteam Adjusters Pte Ltd
Norm YunXin (Gary)	Formteam Adjusters Pte Ltd
Chow Ho Xiong	Formteam Adjusters Pte Ltd
Chun Hoo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Nathan Ang	LKK Auto Consultants Pte Ltd
Ang Guo Qiang	LKK Auto Consultants Pte Ltd
Yusuf Chua	LKK Auto Consultants Pte Ltd
Mohammad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasid	LKK Auto Consultants Pte Ltd
Kamath Nong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & regards,

Yee Hui (Winnie)

2019/06/27 09:00 AM Singapore PMOL Claims Operations v 3.00

YeeHui@sea.com www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref: KCR0620191725AIG
Your Ref: SJA3629T

26 June 2019

WITHOUT PREJUDICE
BY FAX: 6415 3727

AIG Asia Pacific Insurance Pte Ltd
Claims Department
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Dear Sirs,

Notice to inspect our client's damaged motor-vehicle SLB1725H.
Accident involving SLB1725H / SJA3629T & others on 24/06/2019 along Serangoon Rd.

Our client's motor vehicle no: SLB1725H which was damaged as a result of negligence of your driver, is now lying at our premises/workshop awaiting for repairs to be carried out.

As you are the insurer of the motor-vehicle no: SJA3629T, we hereby give you NOTICE TO INSPECT OUR CLIENT'S DAMAGED MOTOR VEHICLE at our premises/workshop. If your representative/surveyor does not inspect our client's damaged motor vehicle within the next two(2) days, we shall proceed to repair our client's damaged motor vehicle without any further notice and our client will thereafter look to you/your insured for the repair costs. This is without prejudice to our client's claim for damages, loss of use and incidental loss.

Please let us have your list of your panel surveyors for our consideration.

We enclosed herewith our estimate cost of repairs and our clients' accident report for your reference.

Thank you.

Yours faithfully,
KANG CAR REPAIRERS PTE LTD

.....

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singtel.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 24/06/2019
TP Veh Reg No: SJA3629T

Estimate No: EST1900192
Date: 26 Jun 2019
Veh Reg No: SLB1725H
Make/Model: HYUNDAI ACCENT
(RB) SDR 1.4MT
Chasis No: KMHCT51BLGU251140
Reg. Date: 30/03/2016
Your Ref No: SJA3629T

Estimate Repair Cost to Vehicle No :SLB1725H

Quantity	Description	List Price	Amount
		S\$	S\$
	List Price		
1	1 PC BOOT LID	1,303.20	
2	1 PC BOOT LID LOGO	23.30	
3	1 PC BOOTLID "ACCENT" EMBLEM	31.20	
4	1 PC BOOT LID LOCK	166.80	
5	1 PC BOOT LID LOCK CHECKER	12.00	
6	1 PC BOOT LID RUBBER	82.60	
7	1 PC BOOT LID TRIM	58.20	
8	1 PC TAIL LAMP LH	326.30	
9	1 PC TAIL LAMP - RH	326.30	
10	1 PC REAR PANEL	499.30	
11	1 PC REAR PANEL TRIM	115.10	
12	1 PC REAR BUMPER	466.40	
13	1 PC REAR BUMPER REINFORCEMENT	365.40	
14	2 PCS REAR BUMPER LOWER BRACKET	33.40	
15	2 PCS REAR BUMPER SIDE RETAINER	48.60	
16	1 PC REAR BUMPER REFLECTOR - LH	53.40	
17	1 PC REAR BUMPER REFLECTOR - RH	53.40	
18	2 PCS REAR NUMBER PLATE LAMP	70.60	
		4,035.50	
	Less 20%	807.10	3,228.40
	Special Net		
19	1 SET BOOTLID TRIM CLIPS	40.00	
20	1 PC REAR WINDSCREEN SEAL	60.00	
21	1 PC REAR WINDSCREEN SEALANT	60.00	
22	1 SET REAR PANEL TRIM CLIPS	30.00	
23	1 SET REVERSE SENSORS	250.00	
24	1 PC REAR NUMBER PLATE	50.00	
		490.00	490.00
	Labour		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL.: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 24/06/2019
TP Veh Reg No: SJA3629T

Estimate No: EST1900192
Date: 26 Jun 2019
Veh Reg No: SLB1725H
Make/Model: HYUNDAI ACCENT
(RB) 5DR 1.4MT
Chasis No: KMHCT51BLGU251140
Reg. Date: 30/03/2016
Your Ref No: SJA3629T

Estimate Repair Cost to Vehicle No :SLB1725H

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
25	1 TO CHECK WIRING	50.00	
26	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
27	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
28	1 TO SPRAY UNDERSEAL	150.00	
29	1 (REAR) TO SPRAY PAINTING	1,000.00	
30	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	
		<u>2,400.00</u>	<u>2,400.00</u>
	Total		S\$ 6,118.40
	Add GST @ 7%		428.29
	Total Amount Payable		<u>S\$ 6,546.69</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED FORTY SIX AND CENTS SIXTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2019 Edit Reg		27 Jun 2019 00:00 Edit Adj Rpt	S\$4,400.00 Edit Estimates	S\$4,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	APEX CAR LEASING , Co. Reg. No.: 53337283J								
Main Claimant:	GOLDBN , Co. Reg. No.: 53367993A								
Vehicle Reg. No.:	SLB1725H	Date of Loss:	24/06/2019 20:00 - :59 [38 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5982942741SG	Policy/Cover Note No.:	0999994092 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJA3629T	Policy No. (Claimant):	5093335815-01						
		Excess:							
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB1725H (5982942741SG)
[SJA3629T]
TP
GOLD8N
Jun 24 2019 8:00PM
[APEX CAR LEASING]
Kang Car Repairers Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page 1	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1		Edit	
Assessment Reports										1 per page 1	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	01/07/19 15:47	Accident Statement From: SC - Reg. No: SJA3629T, Claimant: APEX CAR LEASING						1		Load HTM	
Photos/Images										3 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	31/07/19 17:59	General View						1		Load JPG	
2	31/07/19 17:59	General View						1		Load JPG	
3	31/07/19 17:59	General View						1		Load JPG	
4	31/07/19 17:59	General View						1		Load JPG	
5	31/07/19 17:59	General View						1		Load JPG	
6	31/07/19 17:59	General View						1		Load JPG	
7	31/07/19 17:59	General View						1		Load JPG	
8	31/07/19 17:59	General View						1		Load JPG	
9	31/07/19 17:59	General View						1		Load JPG	
10	31/07/19 17:59	General View						1		Load JPG	
11	31/07/19 17:59	General View						1		Load JPG	
12	31/07/19 17:59	General View						1		Load JPG	
13	31/07/19 17:59	General View						1		Load JPG	
14	31/07/19 17:59	General View						1		Load JPG	
15	31/07/19 17:59	General View						1		Load JPG	
16	31/07/19 17:59	General View						1		Load JPG	
17	31/07/19 17:59	General View						1		Load JPG	
18	31/07/19 17:59	General View						1		Load JPG	
19	31/07/19 17:59	General View						1		Load JPG	
20	31/07/19 17:59	General View						1		Load JPG	
21	31/07/19 17:59	General View						1		Load JPG	
22	31/07/19 17:59	General View						1		Load JPG	
23	31/07/19 17:59	Reinspection Photo						1		Load JPG	
24	31/07/19 17:59	Reinspection Photo						1		Load JPG	
25	31/07/19 17:59	Reinspection Photo						1		Load JPG	
26	31/07/19 17:59	Reinspection Photo						1		Load JPG	
27	31/07/19 17:59	Reinspection Photo						1		Load JPG	
28	31/07/19 17:59	Reinspection Photo						1		Load JPG	
29	31/07/19 17:59	Reinspection Photo						1		Load JPG	
30	31/07/19 17:59	Reinspection Photo						1		Load JPG	
31	31/07/19 17:59	Reinspection Photo						1		Load JPG	
32	31/07/19 17:59	Reinspection Photo						1		Load JPG	
33	31/07/19 17:59	Reinspection Photo						1		Load JPG	
34	31/07/19 17:59	Reinspection Photo						1		Load JPG	
35	31/07/19 17:59	Reinspection Photo						1		Load JPG	
36	31/07/19 17:59	Reinspection Photo						1		Load JPG	

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
37	31/07/19 17:59	Reinspection Photo		Load JPG	☒
38	31/07/19 17:59	Reinspection Photo		Load JPG	☒
39	31/07/19 17:59	Reinspection Photo		Load JPG	☒
40	31/07/19 17:59	Reinspection Photo		Load JPG	☒
41	31/07/19 17:59	Reinspection Photo		Load JPG	☒
42	31/07/19 17:59	Reinspection Photo		Load JPG	☒
43	31/07/19 17:59	Reinspection Photo		Load JPG	☒
44	31/07/19 17:59	Reinspection Photo		Load JPG	☒
45	31/07/19 17:59	Reinspection Photo		Load JPG	☒
46	31/07/19 17:59	Reinspection Photo		Load JPG	☒
47	31/07/19 17:59	Reinspection Photo		Load JPG	☒
48	31/07/19 17:59	Reinspection Photo		Load JPG	☒
49	31/07/19 17:59	Reinspection Photo		Load JPG	☒
50	31/07/19 17:59	Reinspection Photo		Load JPG	☒
51	31/07/19 17:59	Reinspection Photo		Load JPG	☒
52	31/07/19 17:59	Reinspection Photo		Load JPG	☒
53	31/07/19 17:59	Reinspection Photo		Load JPG	☒
54	31/07/19 17:59	Reinspection Photo		Load JPG	☒
55	31/07/19 17:59	Reinspection Photo		Load JPG	☒
56	31/07/19 17:59	Reinspection Photo		Load JPG	☒
57	31/07/19 17:59	Reinspection Photo		Load JPG	☒
58	31/07/19 17:59	Reinspection Photo		Load JPG	☒
59	31/07/19 17:59	Reinspection Photo		Load JPG	☒
60	31/07/19 17:59	Reinspection Photo		Load JPG	☒
61	31/07/19 17:59	Reinspection Photo		Load JPG	☒
62	31/07/19 17:59	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/06/19 12:13	EMAIL FROM AIG DD 27062019		Load PDF	
2	28/06/19 12:13	TP EST & GIA REPORT		Load PDF	
3	21/10/19 18:50	LETTER TO OI		Load PDF	
4	10/12/19 10:27	WORKSHOP INVOICE		Load PDF	
5	10/12/19 10:27	AUTHORISATION TO ACT FORM		Load PDF	
6	10/12/19 10:27	Release Voucher		Load PDF	
7	10/12/19 10:27	RENTAL RECEIPT		Load PDF	
8	10/12/19 10:27	LTA SEARCH		Load PDF	
9	10/12/19 10:27	LOD		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJA3629T (Insd veh)	Model:	HYUNDAI ACCENT 1.3 5DR
	SLB1725H (TP veh)		
Date of Accident:	24/06/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	6,714.81
Final Repair Cost	:	\$	4,708.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	749.00 7 days
LTA / GIA Search Fee	:	\$	10.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,467.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability ____ 100 ____ (%)			
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: ____			
BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Kang Car Repairers Pte Ltd	:	\$ 5,467.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011467/AKB3Q2

Date: 10/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994092
Claimant		
Vehicle No : SLB1725H	Insured Vehicle No :	SJA3629T
Date of Loss: 24/06/2019	Nature of Claim: TP	Claim No: 5982942741SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB1725H	Engine No:	G4LCFU473772
Make & Model:	HYUNDAI ACCENT, 1.3 5DR	Chassis No:	KMHCT51BLGU251140
Reg. Date:	30/03/2016 (Man. Year: 2015)	Odometer:	80840 km
Colour:	Black		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,875.52	3,672.72	202.80	5.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,890.00	510.00	21.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,275.52	5,562.72	712.80	11.36
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	6,275.52	4,400.00	1,875.52	29.89
+ GST 7.00/7.00% (S\$)	439.29	308.00	131.29	29.89
Nett Amount (S\$)	6,714.81	4,708.00	2,006.81	29.89
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		10.00		
Nett Liability (S\$)		5,467.00		

INSPECTION

Date of Assignment: 27/06/2019
Date Inspected: 27/06/2019 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,303.20 FL	*1,303.20 FL
2	1		*BOOT LID LOGO	Necessary	23.30 FL	*23.30 FL
3	1		*BOOTLID ACCENT EMBLEM	Necessary	31.20 FL	*31.20 FL
4	1		*BOOT LID LOCK	Damaged	166.80 FL	*166.80 FL
5	1		*BOOT LID LOCK CHECKER	Not Necessary	12.00 FL	*- FL
6	1		*BOOT LID RUBBER	Cut	82.60 FL	*82.60 FL
7	1		*BOOT LID TRIM	Cracked	58.20 FL	*58.20 FL
8	1		*TAIL LAMP LH	Cut	326.30 FL	*326.30 FL
9	1		*TAIL LAMP RH	Cracked	326.30 FL	*326.30 FL
10	1		*REAR PANEL	Dented	499.30 FL	*499.30 FL
11	1		*REAR PANEL TRIM	Deformed	115.10 FL	*115.10 FL
12	1		*REAR BUMPER	Deformed	466.40 FL	*466.40 FL
13	1		*REAR BUMPER REINFORCEMENT	Cracked	365.40 FL	*365.40 FL
14	2		*REAR BUMPER LOWER BRACKET	Not Necessary	33.40 FL	*- FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	48.60 FL	*48.60 FL
16	1		*REAR BUMPER REFLECTOR -LH	Cut	53.40 FL	*53.40 FL
17	1		*REAR BUMPER REFLECTOR -RH	Cracked	53.40 FL	*53.40 FL
18	2		*REAR NUMBER PLATE LAMP	Not Necessary	70.60 FL	*- FL
19	2		*REAR BUMPER BRACKET	Bent	196.40 FL	*196.40 FL
20	1		*SET BOOTLID TRIM CLIPS	Necessary	40.00 FS	*30.00 FS
21	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
23	1		*SET REAR PANEL TRIM CLIPS	Necessary	30.00 FS	*20.00 FS
24	1		*SET REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
25	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,721.90	4,495.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	846.38	823.18
Total Parts (\$\$)	3,875.52	3,672.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	40.00
4	TO SPRAY UNDERSEAL	New	150.00	60.00
5	(REAR) TO SPRAY PAINTING	New	1,000.00	820.00
6	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS,AND FOR CUTTING /WELDING WORKS	New	1,000.00	820.00
Gross Labour Cost (S\$)			2,400.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >