Name 2:

Name 3:

Payce 1:

Payce 2: (Strike if N.A.)

Payee 3: (Strike if N.A.)

SS

	T'
08/11/13 wef REF:	
ASS. REC. BY: Marcus REF:	AXA/
ASS. REC. VIII	ASSIGNMENT
From: Date: Estimated Cost: OD ATR / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: at Workshop m/s K M Church Church	Veh No: SLK3984Ryr Regn: // /7 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
of	30.11
Insured:	Eng/No: SJNFEAJIIU1724035
Policy No.	Gen. Cond: Good Fair / Poor / Burnt
Claims No.	
Sum Insured: Excess:	Steering: Ingraer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or Tyre Size: F: 215-80-21
Date: Person Contacted:	R: BS/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front R/Bal. mm R/Bal. mm L/Bal. D.O.A. 26/6/8 Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time, File Pass to? : Preli. Report : Final Report Date/Time, File Return to?	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)_S+RS,_SI
7	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$
, Lump dam / non (4	TOTAL

Not Albertus Lle 28/6/19 2/5 \$ 17.100? 9 dy.

KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 SINGAPORE 417883

SINGAPORE 4	1863	7.
VEHICLE NO: 5	K3984R	8
QTY	PARTICULAR (NETT ITEM)	
1 PCS	REAR WINDSCREEN 11 \$1,855.3	30 🗙
1 PCS	REAR WINDSCREEN MOULDING 17 \$195.3	The second secon
2 PCS	REAR WINDSCREEN INNER SIDE GARNISH @\$165.00 \$330.0	∞ oc
1 PCS	TAILGATE \$3,066.2	20 ×
1 PCS	TAILGATE OUTER GARNISH 11 \$450.0	00 ×
1 PCS		50 X
1 PCS	TAILGATE 'Qashqai' EMBLEM \$78.5	50 /
2 PCS	TAILGATE REFLECTORS @\$650.00 \$1,300.0	00 X
1 PCS	TAILGATE REAR WIPER MOTOR 17 \$966.0	00 ×
1 PCS	TAILGATE REAR WIPER ARM 1/7 \$315.0	
1 PCS		00 X
1 PCS	TAILGATE INNER LOCK 17 \$292.0	00 >
1 PCS	TAILGATE INNER TRIM BOARD 17 \$595.3	
1 SET		00 X
1 PCS		20 🗡
1 PCS	TAILGATE REVERSE CAMERA 11 \$485.0	X 00
1 PCS	TAILGATE INNER TOP BOARD 17 \$492.3	30 1
2 PCS	TAILGATE LICENCE PLATE LAMPS @\$53.00 \$106.0	00 ×
1 PCS	REAR BUMPER 7/7.00 (796.00) 75 \$891.0	00 —
1 PCS	REAR BUMPER TOW COVER 71-7 \$22.0	00 —
2 PCS	REAR BUMPER REFLECTORS @\$68.00 \$136.0	00 ×
2 PCS	REAR BUMPER SIDE RETAINERS @\$25.00 A 1 \$50.0	00 X
1 PCS	REAR BUMPER REINFORCEMENT 6/9.20 But \$721.	00
2 PCS	TAILLAMPS @\$580.00 \$1,160.0	∞
2 PCS		00 💢
2 PCS	REAR FENDERS @\$1150.00 \$2,300.0	00 X
2 PCS		00 راکار
2 PCS	REAR FENDER INNER TRIMS @\$481.00	
1 PCS	REAR FENDER UNDER SHIELD N/S 11 \$266.	
1 PCS	REAR FENDER INNER AIR VENT N/S 4 1 \$68.0	∞, ∞
1 PCS	REAR FENDER INNER AIR VENT N/S REAR FENDER GLASS W/MOULDING N/S REAR END PANEL \$68.0 1 \$820.0 \$720.0	00 🗡
1 PCS	REAR END PANEL \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	00 💢
1 PCS	REAR END PANEL TOP GARNISH 17 \$408.	000
1 PCS	REAR END PANEL LOCK SENSOR	00 a
1 PCS	REAR FLOOR PANEL 1 1,288.	1
1 PCS	REAR FLOOR PANEL TOP BOARD A 7 \$622.	
2 PCS	REAR FLOOR PANEL TOOLS SPONGES @\$305.00	
1 PCS	REAR FLOOR PANEL TOOLS SPONGE CENTRE 17 \$308.	
1 PCS	REAR FLOOR PANEL SPARE TYRE NUT A 4 \$62.	20 🗡

	MIN		/
1 PCS	find funder outer protectors @ 281.15	Torn 5	1,122.30
2 PCS Sel	fund feder outer protector cl.75	11	\$60.00 X
1 PCS	front fender inversible it of	-	\$188.00
1 PCS	front funder OLS , 622.70	But/346	\$810.50
1 SET	front fender innershed cl-25	nu-	\$30.00
PCS	10000		1,844.00
1 PCS	FRONT BUMPER - 61460 (639.00)	Dis	\$801.00
1 PCS	FRONT BUMPER REINFORCEMENT 674-40	25	\$665.00
1 PCS	FRONT BUMPER SPONGE 145.70	10-1.	\$302.00
2 PCS	FRONT BUMPER SIDE RETAINERS @\$35.00	Bert	\$70.00
1 SET	FRONT BUMPER CLIPS	M	\$30.00
1 PCS		11	\$28.00 X
2 PCS	(1996.00)		5,700.00
1 PCS	FRONT GRILLE 46/·20 (535.00)	3R0	\$803.30
1 PCS	FRONT GRILLE LOGO	MIS	\$65.00
1 PCS	BONNET	Buc	\$923.30
1 PCS	FRONT SUPPORT PANEL 6/7:50	ser	\$792.50
1 PCS	EDON'T CURRORY DANIEL TOR CARNICU	Ton	\$368.40
1 PCS	AIR CON CONDENSER	Buflem.	\$911.00
2 PCS	AIR CON CONDENSER SIDE GARNISH @\$208.00	Din.	\$416.00
1 PCS	AIR CON SUCTION HOSE	11	\$150.00 ×
1 PCS	AIR CON DISCHARGE HOSE	Best	\$166.00
1 PCS		cra	\$105.00
	HUCA UNIT FRONT BUMPER REINFORCEMENT BRACKETS @\$205.00	Bed	\$410.00
2 PCS		7117	\$620.00
1 PCS	OIL COOLER OIL COOLER HOSE		\$30.00 x
1 PCS	RADIATOR (716.00)	2-3	\$885.00
1 PCS	/24.20	crefon	\$820.00
1 PCS	FRONT FOG LAMP COVERS @\$95.00	121	\$190.00
2 PCS (۱)	from for lamps 0 258x2 = \$16 cre	100	3,424.70
-(1.)	S.NETT	44	3,424.70
1 SET	REAR BUMPER REVERSE SENSOR (4 PCS)	shotel	\$380.00 200
1 PCS	REAR END PANEL SEALANT	11	\$50.00 ×
	REAR FLOOR PANEL INSULATOR	11	\$300.00 X
1 SET	REAR PLOOR FANEL INSULATOR REAR WINDSCREEN SEALANT	11	\$50.00 ×
1 PCS	REAR WINDSCREEN SEALANT N/S	11	\$50.00 🗶
1 PCS 1 SET	REAR VIEW CAMERA CAM	11	\$500.00 ×
1 PCS	REAR WINDSCREEN SOLAR FILM	11	\$300.00 ×
		11	\$50.00 ×
1 PCS	REAR LICENCE PLATE WHOLDER	sel	
1 PCS	FRONT LICENCE PLATE W/HOLDER	sei	\$50.00 70
1 BOT	RADIATOR COOLANT	in	\$30.00 50
	LABOUR CHRAGES:		
	TO CHECK WIRING		\$80.00 30
	TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00 (~)
	TO DISMANTLE & REPLACING REAR WINDSCREEN		\$150.00 ×
	TO DISMANTLE & REPLACING REAR EXHAUST	1,1	\$150.00 60
	TO DISMANTLE & REPLACING REAR EXHAUST		\$100.00 BU

P-19882:70 172 17897:13 TO DISMANTLE & REPLACING REAR FENDER GLASS N/S
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO DISMANTLE & REFIX PETROL TANK
TO DISMANTLE & REFIX REAR UNDERCARRIAGE
TO CONDUCT WHEEL ALIGNMENT
TO SPRAY RUSIT PROOFING
TO REFILL AIR CON GAS
TO MOUNT VEHICLE ON CAR O-LINER
TO TRNASFER TAILGATE COMPONENTS
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN
& REPLACING PARTS
TO PUTTY & SPRAY PAINTING

3490 21387:13 17/09.

\$150.00 X

\$150.00 fo

\$180.00 |00

\$150.00 (00

\$3,000.00 / 200

\$3,000.00 1600

11 \$100.00 ×

11 \$120.00 X

N 1 \$380.00 ×

11 \$100.00 X

\$53,494.70

53890-704

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8906D
Vehicle Details	
Vehicle No.:	SLK3984R
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	HRA2310472A
Chassis No.:	SJNFEAJ11U1724035
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,689.00
Original Registration Date:	16 Jan 2017
First Registration Date:	16 Jan 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$13,689.00 (PU 4
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jan 2027
PARF Rebate Amount: Intended COE Rebate Details	\$10,266.00
COE Expiry Date:	15 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$37,818.00
Total Rebate Amount:	\$48,084.00

The information contained herein is correct as at 28 Jun 2019

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Login Sign up

Resources

Advanced Search

BUILD YOUR OWN PLAN SAMSUNG WITH GALAXY S10 SERIES Depreciation Y 2017 Vehicle Type Submit (Price Range Qashqai

Home » Used Cars » Universe Motoring » Nissan Qashqai 1.2A DIG-T Premium

Nissan Qashqai 1.2A DIG-T Premium

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Мар

Price

\$77,800

Depreciation

\$9,390 /yr

View models with similar depre

Reg Date

16-Jan-2017

(7yrs 6mths 18days COE left)

Mileage

N.A.

Manufactured

2016

Road Tax

\$508 /yr

Transmission

Auto

Dereg Value

\$48,151 as of today (change)

OMV

\$18,725

COE

\$50,101

ARF

\$13,725

Engine Cap

1,197 cc

Power

85.0 kW (113 bhp)

Curb Weight

1,285 kg

No. of Owners

Type of Vehicle

SUV

Price Chart

Summary

1.2L DIG Turbocharged Engine, 7 Speeds Xtronic CVT Transmission. 6 Airbags, Traction/Cruise Control, Audio Steering Control, ABS, Keyless Entry/Start. View specs of the Nissan Qashqai (2014)

Accessories

Factory Fitted Audio Player, Bluetooth, GPS, Leather Seats, Reverse Camera/Sensors, Electronic Parking Brake, Solar Film.

Description

1 Owner, Full Agent Maintained, (5Yrs Warranty + 1 Time Free Service), Blue In Colour, Beautiful Condition, Please Kindly Call For More Information.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Vehicle Evaluation











Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Universe Motoring

dealer's pricelist

» 52 vehs sold | 32 vehs available

Address

210 Turf Club Road Lot A19/A20 Search cars nearby this location

SGCARMART.COM

New Cars Used Cars

Cars Sell My Car

Directory

Products

Depreciation V

Similar

Insurance

Photos

Vehicle Type

Articles

Мар

Forum

Submit (

Sign up

Login

Resources

Search

PREMIUM AD



Overview

BIAVIVA

18% off now, promo code: CAR18

Research

2017

Get a quote

Home » Used Cars » CarChope » Nissan Qashqai 1.2A DIG-T

Nissan Qashqai 1.2A DIG-T

Financial

SUV

Qashqai

Price	\$78,888		
Depreciation	\$9,390 /yr View models with similar depre	Reg Date	28-Feb-2017 (7yrs 7mths 30days COE left)
Mileage	36,000 km (15.5k /yr)	Manufactured	2016
Road Tax	\$508 /yr	Transmission	Auto
Dereg Value	\$47,332 as of today (change)	ому	\$18,585
COE	\$48,401	ARF	\$13,585
Engine Cap	1,197 cc	Power	85.0 kW (113 bhp)
Curb Weight	1,285 kg	No. of Owners	1

Price Range

Accessories



Features

Type of Vehicle

1.2L DIG Turbocharged Engine, 7 Speeds Xtronic CVT Transmission. 6 Airbags, Traction/Cruise Control, Audio Steering Control, ABS, Keyless Entry/Start. View specs of the Nissan Qashqai (2014)

Accessories

Factory Fitted Audio Player, Bluetooth, GPS, Leather Seats, Reverse Camera/Sensors, Electronic Parking Brake, Solar Film, Fog Lights, Recording Camera

Description

Beautiful Red. Accident Free! 3 + 2 Years Warranty With Tan Chong Motors Until Feb 2022. High Loan At Low Interest Rate! Trade In Welcome. Consignment Unit. Call Now To Book An Appointment To View

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 27-May-2019 | Last Updated on: 05-Jun-2019

Upfront Payment

more Financial info













Summary

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

CarChope

· dealer's pricelist

▶ 40 vehs sold | 17 vehs available

Address

316 Tanglin Road #02-01 Search cars nearby this location

P: Nancy T. 4.56 p.m V: In



Service Request Details

591401RYP

None &

June 26, 2019

Report Date

Jun 27, 2019 4:04:00 PM

8 Hest Date

June 27, 2019

July 4, 2019

LICE AUTO CONSULTANTS PTE LTD (TP)

Third Party Vehicle Damage

Pending verification - Direct Settlement

Actions

Agree to perform service

Accept Work

Vehicle Information

Whit Vehicle Registration #

SL153984R

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu

QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Service Address

Primary Contact/Insured

GOH SEOW CHUAN
27 PASIR RIS STREET 72, WHITEWATER, #11-16, 518767. Singapore 82180633

Claim Handler

65/68804833

while ho@axa.com.sg

a limit instructions

Invoices History Documents Assessment Metrics Notes

Catherine Chong (LKK Auto)

From:

Nancy Lam <nancy.lam@fastechauto.com.sg>

Sent:

Thursday, 27 June, 2019 2:34 PM

To:

SG AXA Insurance SM AXA SGP - Motor Survey

Subject:

Request for PRS SLK 3984R

Categories:

Raghav

Without Prejudice

Hi Sir

My client claiming your insured SLJ 891A.

Please kindly arrange PRS for SLK 3984R.

Date of accident 26.06.2019.

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards Namey Lam KIM CHWEE Auto Pte Ltd

Tel. 67 6 5405 Fax: 6745 8520

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	906D	
Vehicle No.:	SLK3984R	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	08 Aug 2019	
Vehicle Make:	NISSAN	
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR	
Primary Colour:	Black	
Manufacturing Year:	2016	
Engine No.:	HRA2310472A	
Chassis No.:	SJNFEAJ11U1724035	
Maximum Power Output:	85.0 kW (113 bhp)	
Open Market Value:	\$18,689.00	
Original Registration Date:	16 Jan 2017	
First Registration Date:	16 Jan 2017	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$13,689.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	15 Jan 2027	
PARF Rebate Amount: Intended COE Rebate Details	\$10,266.00	
COE Expiry Date:	15 Jan 2027	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$50,101.00	
COE Rebate Amount:	\$37,252.00	
Total Rebate Amount:	\$47.518.00	

The information contained herein is correct as at 08 Aug 2019

OK



<TP - Mandate IA> - S9M01RYP [ACCIDENT INVOLVING SLJ 891A(OI) / SLK 3984R(TP) / OTHERS ON 26/06/2019]

Type

Q Question

Message

Liability: 100%. 5 vehicles chain collision whereby OID was the 4th vehicle. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$18,899.00(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong -12-Nov-19

Reply



Auto Consultants

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 12/11/2019

Survey Details:

Date of loss	26-Jun-19	
Date of appointment	28-Jun-19	
Date of survey	28-Jun-19	
Location of survey	KIM CHWEE AUTO PTE LTD	

Vehicle Details:

Claim Type:	Third party	
Vehicle number	SLK 3984R	
Make and Model	NISSAN QASHQAI 1.2 DIG	
Date of registration	16/1/2017	
Excess		
Market Value	\$75,000	
Parf Rebate	\$48,084	
Nett Loss	\$26,916	

Repair details:

Initial Estimate	\$ 53,494.70

Proposed/Revised repair cost:

Parts	\$ 18,167.13
Check items (estimate)	\$
Labour	\$ 3,220.00
Total	\$ 21,387.13
Lump Sum(if applicable)	\$ 17,100.00
	\$
Number of days for repair	9



51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Remarks:

5 vehicles chain collision whereby OID wss the 4th vehicle.	

Mandate:

Liability(TP)	100%	1
Proposed repair cost (w/GST)	\$ 18,297.00	
Loss of use	\$	(10days x\$60.00)
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees	\$ 2.00	7
Others	NIL	
Proposed Total	\$ 18,899.00	



<TP - Mandate IA> - S9M01RYP [ACCIDENT INVOLVING SLJ 891A(OI) / SLK 3984R(TP) / OTHERS ON 26/06/2019]

Type

Question

Message

Hi Hsiao Tong, understand currently Tan Chong is giving 15% discount on body parts and 10% on non body parts . pls reduce further discount for these items, amend and re-submit your mandate IA for approval. FRONT BUMPER \$629, FRONT GRILLE \$525, RADIATOR \$716, A/C CONDENSER \$696, REAR BUMPER \$796, REAR EXHAUST \$544, FRONT HEADLAMP \$613. Tks

Reply



RE: <TP - Mandate IA> - S9M01RYP [ACCIDENT INVOLVING SLJ 891A(OI) / SLK 3984R(TP) / OTHERS ON 26/06/2019]

Type

Q Question

Message

Hi according to surveyor, since Nov 2017, all Nissan Model spare parts is under Nett Items with 10% discount. We have amend the parts price and re-submit mandate for your review. Kindly refer to TP-MANDATE IA dd 141119 for your easy reference. Kindly let us have your mandate after review the matter. Thank you. Hsiao Tong - 14 Nov 2019

Reply



51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 14/11/2019

Survey Details:

	26-Jun-19
Date of appointment	28-Jun-19
Date of survey	28-Jun-19
Location of survey	KIM CHWEE AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLK 3984R
Make and Model	NISSAN QASHQAI 1.2 DIG
Date of registration	16/1/2017
Excess	,-,,
Market Value	\$75,000
Parf Rebate	\$48,084
Nett Loss	\$26,916

Repair details:

Initial Estimate	\$ 53,494.70
7), I	

Proposed/Revised repair cost:

Parts	\$ 14,341.77
Check items (estimate)	\$
Labour	\$ 3,220.00
Total	\$ 17,561.77
Lump Sum(if applicable)	\$ 14,000.00
	\$
Number of days for repair	9



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Remarks:

5 vehicles chain collision whereby OID was the 4th car.	

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 14,980.00	
Loss of use	\$ 600.00	(10days x \$60)
Loss of rental	NIL	no. of days
Loss of income	NIL	no. of days
LTA search fees	\$ 2.00	
Others	NIL	
Proposed Total	\$ 15,582.00	

Menu



<TP - Mandate IA> - S9M01RYP [ACCIDENT INVOLVING SLJ 891A(OI) / SLK 3984R(TP) / OTHERS ON 26/06/2019]

Type

Q Question

Message

Hi Hsiao Tong, pls proceed. tks

Reply



RE: <TP - Mandate IA> - \$9M01RYP [ACCIDENT INVOLVING SLJ 891A(OI) / SLK 3984R(TP) / OTHERS ON 26/06/2019]

Type

Q Question

Message

Hi third party counter proposed g/s \$16,800.00(all-in). Kindly advise further mandate after review the matter. Thanks. Hsiao Tong - 05 Dec 2019

Reply

Hsiao Tong (LKKAuto)

From:

Shu Pei (LKKAuto)

Sent:

Friday, 6 December 2019 9:01 AM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: New message for service request 124140, vehicle number SLK3984R

10.0	-	4014410040
15/11/19 9:32 AM HO Winnie**MessageHi Hsiao Tong, pls proceed. tks	CHT	16/11/2019 11:05:47 AM
**PENDING TP AMENDED LOD & DOCS	СНТ	18/11/2019 7:52:35 AM
Offered TP at g/s \$15,500.00	СНТ	18/11/2019 11:58:00 AM
MessageAXA: Hi third party counter proposed g/s \$16,800.00(all-in). Kindly advise further mandate after review the matter. Thanks. Hsiao Tong - 05 Dec 2019	CHT	5/12/2019 3:37:40 PM
5/12/19 3:54 PM HO WinnieHi Hsiao Tong, pls maintained as per mandate IA dated 14.11.2019. Tks	LSP	6/12/2019 8:47:30 AM

Best Regards,

Shu Peil Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Thursday, 5 December 2019 4:05 PM To: Admin A <admin-a@lkkauto.com>

Subject: FW: New message for service request 124140, vehicle number SLK3984R

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue

1, #02-25 | S(408933)

----Original Message-----

From: winnie.ho@axa.com.sg <winnie.ho@axa.com.sg>

Sent: Thursday, 5 December, 2019 3:55 PM

To: admin-d@lkkauto.com

Subject: New message for service request 124140, vehicle number SLK3984R

AXA Insurance has sent you a message for claim number S9M01RYP.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal.

Hsiao Tong (LKKAuto)

From:

Jason <Jason@fastechauto.com.sg>

Sent:

Monday, 9 December 2019 3:26 PM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: YOUR REF: SLJ891A MY REF:SLK3984R DOA: 26/06/2019 // LKK REF:

CC4/ASM19011472/Upb3

Without Prejudice

Dear Hsiao Tong,

Without admission of liability, we are agreeable with your offer of global sum of \$15,580.00(all-in) for my client's vehicle property claim.

Thank you.

Best Regards

Jason Tang Kim Chwee Auto Pte Ltd 1 Kaki Bukit Ave 6 #01-46/48/50 AutoBay Singapore 417883

Tel: 67465405 Hp: 98218445

jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, December 9, 2019 8:25 AM To: Jason < Jason@fastechauto.com.sg>

Subject: RE: YOUR REF: SLJ891A MY REF:SLK3984R DOA: 26/06/2019 // LKK REF: CC4/ASM19011472/Upb3

Without Prejudice (save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to revise offer at a global sum of \$15,580.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice

engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason < <u>Jason@fastechauto.com.sg</u>> Sent: Monday, 18 November 2019 2:49 PM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com

Subject: RE: YOUR REF: SLJ891A MY REF:SLK3984R DOA: 26/06/2019 // LKK REF: CC4/ASM19011472/Upb3

Without Prejudice

Dear Hsiao Tong,

We counter propose at global sum \$16800.00 all in.

Thank you.

Best Regards

Jason Tang Kim Chwee Auto Pte Ltd 1 Kaki Bukit Ave 6 #01-46/48/50 AutoBay Singapore 417883 Tel: 67465405

Hp: 98218445

jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, November 18, 2019 12:11 PM

To: Jason < Jason@fastechauto.com.sg>

Subject: RE: YOUR REF: SLI891A MY REF:SLK3984R DOA: 26/06/2019 // LKK REF: CC4/ASM19011472/Upb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of \$15,500.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason < Jason@fastechauto.com.sg> Sent: Thursday, 7 November 2019 10:49 AM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Subject: YOUR REF: SLI891A MY REF:SLK3984R DOA: 26/06/2019

Without Prejudice

Dear Hsiao Tong,

We await your offer.

Thank you.

Best Regards

Jason Tang Kim Chwee Auto Pte Ltd 1 Kaki Bukit Ave 6 #01-46/48/50 AutoBay Singapore 417883 Tel: 67465405

Hp: 98218445

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date:14.08.2019

AXA Insurance Pte Ltd 8 Shenton Way #27-01 AXA Tower Singapore 068811

Attn: Motor Claim Department

SLK 3984R AND SLJ 891A ON 26.06.2019 ACCIDENT INVOLVING VEHICLE:

SLK 3984R, which was involved in We are the authorized repair workshop for the owner of motor vehicle no: SLJ 891A . The vehicle owner has requested and authorized the captioned accident with your insured vehicle no: us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

	2) Loss Of Use (9 Days + Isun 7 7 3 2 3) GIA Search Fee	5	19,499.00
2)	Loss Of Use (9 Days + 1sun + X \$120)	\$	1,200.00
1) G C Papair (inclusive of	Cost of Repair (inclusive of GST)	\$	18,297.00

We enclosed herewith the following documents to support the claims:

- a) Final Repair Invoice
- c) GIA Report
- e) Insurance Certificate
- g) Letter of Authorisation, etc ...
- b) Vehicle Registration Log Card
- d) I/C & Driving Licence
- f) GIA Search Result

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Kim Chwee Auto Pte Ltd

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01 AXA Tower Singapore 068811

Attn: Motor Claim Department

Tax Invoice:21201

Date:

14.08.2019

Vehicle No:

SLK 3984R

Make/Model: NISSAN QASHQAI

Chassis/Eng#

Accident Date: 26.06.2019

Claim No:

0619-21201

Amount

To proceed on lump sum repair

SS

17,100.00

17,100.00 Total: S\$ E. & O. E. 1,197.00 GST @ 7% : S\$ 18,297.00

Amount Due 'S\$

for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	nationale Des Experts En Autor	mobile
AXA	A INSURANCE PT	E LTD	Ref : CC4/ASM1901	11472/Upa3s2
AXA	HENTON WAY #24 A TOWERSINGAPO TN: WINNIE HO		Date: 23-01-2020 Code: ASM	
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.	SLJ 891A	Veh. Inspected	SLK 3984R
	Policy No.	GA294406	Coverage (\$)	0.00
	Claim No.	S9M01RYP	Excess (\$)	0.00
	Assign From	WINNIE HO	Assign Date	28/06/2019
2.		Vehicle P	articulars & Condition	
	Make & Model	NISSAN QASHQAI (A)	c.c	1197
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	SJNFEAJ11U1724035	Colour	BLACK
	Odometer	32779	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Cor	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm
4.			iption of Damages	EST LIGHT STORY
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR AND FRONT PORTIO	N.
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	E SERVICE OF SERVICE
	Accident Date	26/06/2019	Inspection Date	28/06/2019
	Survey held at	KIM CHWEE AUTO PTE LT	D	
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a.			Remarks	APPENDICTOR STATE
	A)THE INSPECTION	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	IS.
5b.			ate Days of Repair	ED NEFAING.
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	9 Working Day	/e



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3984R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN (CONSISTENT)	NOT NECESSARY	1,855.30	
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	195.30	
2	REAR WINDSCREEN INNER SIDE GARNISH @ \$165.00 (CONSISTENT)	NOT NECESSARY	330.00	
1	TAILGATE (CONSISTENT)	TO REPAIR SEE LABOUR	3,066.20	
1	TAILGATE OUTER GARNISH (CONSISTENT)	NOT NECESSARY	450.00	
1	TAILGATE REAR LOGO (CONSISTENT)	NOT NECESSARY	38.50	
1	TAILGATE 'QASHQAI' EMBLEM (CONSISTENT)	NECESSARY	78.50	78.50
2	TAILGATE REFLECTOR @ \$650.00 (CONSISTENT)	NOT NECESSARY	1,300.00	
1	TAILGATE REAR WIPER MOTOR (CONSISTENT)	NOT NECESSARY	966.00	
1	TAILGATE REAR WIPER ARM (CONSISTENT)	NOT NECESSARY	315.00	62
1	TAILGATE REAR WIPER BLADE (CONSISTENT)	NOT NECESSARY	65.00	10-
1	TAILGATE INNER LOCK (CONSISTENT)	NOT NECESSARY	292.00	77
1	TAILGATE INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	595.30	29
1	SET TAILGATE INNER TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	30.00	5.2
1	TAILGATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	166.20	
1	TAILGATE REVERSE CAMERA (CONSISTENT)	NOT NECESSARY	485.00	-
1	TAILGATE INNER TOP BOARD (CONSISTENT)	NOT NECESSARY	492.30	
2	TAILGATE LICENCE PLATE LAMPS @ \$53.00 (CONSISTENT)	NOT NECESSARY	106.00	
1	REAR BUMPER (CONSISTENT)	DISTORTED	891.00	796.00
1	REAR BUMPER TOW COVER (CONSISTENT)	TORN	22.00	22.00
2	REAR BUMPER REFLECTORS @ \$68.00 (CONSISTENT)	NOT NECESSARY	136.00	12
2	REAR BUMPER SIDE RETAINERS @ \$25.00 (CONSISTENT)	NOT NECESSARY	50.00	85
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	721.00	619.20
2	TAILLAMPS @ \$580.00 (CONSISTENT)	NOT NECESSARY	1,160.00	82
2	TAILLAMP HOUSING PANELS @ \$265.00 (CONSISTENT)	NOT NECESSARY	530.00	
2	REAR FENDERS @ \$1150.00 (CONSISTENT)	NOT NECESSARY	2,300.00	19-
2	REAR FENDER OUTER PROTECTORS @ \$541.00 (CONSISTENT)	O/S TORN	1,082.00	541.00

Report Ref No. CC4/ASM19011472/Upa3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
160000	REAR FENDER INNER TRIMS @ \$481.00 (CONSISTENT)	NOT NECESSARY	962.00	-
2	REAR FENDER UNDER SHIELD N/S (CONSISTENT)	NOT NECESSARY	266.00	-
	REAR FENDER INNER AIR VENT N/S (CONSISTENT)	NOT NECESSARY	68.00	-
1	REAR FENDER GLASS W/MOULDING N/S (CONSISTENT)	NOT NECESSARY	820.00	3
	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	720.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	408.00	-
1	REAR END PANEL LOCK SENSOR (CONSISTENT)	NOT NECESSARY	265.00	-
,	REAR FLOOR PANEL (CONSISTENT)	NOT NECESSARY	1,288.30	1
3	REAR FLOOR PANEL TOP BOARD (CONSISTENT)	NOT NECESSARY	622.00	
2	REAR FLOOR PANEL TOOLS SPONGES @ \$305.00 (CONSISTENT)	NOT NECESSARY	610.00	
1	REAR FLOOR PANEL TOOLS SPONGE CENTRE (CONSISTENT)	NOT NECESSARY	308.30	
31	REAR FLOOR PANEL SPARE TYRE NUT (CONSISTENT)	NOT NECESSARY	62.20	The second of
2	FRONT FENDER OUTER PROTECTORS @ \$561.15 (CONSISTENT)	TORN	1,122.30	
	SET FRONT FENDER OUTER PROTECTOR CLIPS (CONSISTENT)	NOT NECESSARY	60.00	
1	FRONT FENDER INNER SHIELD O/S (CONSISTENT)	TORN	188.00	
8	1 FRONT FENDER O/S (CONSISTENT)	BENT / BUCKLED	810.50	
	1 SET FRONT FENDER INNER SHIELD CLIPS (CONSISTENT)	NECESSARY	30.00	
	1 INTER COOLER (CONSISTENT)	DISTORTED	1,844.0	
	1 FRONT BUMPER (CONSISTENT)	DISTORTED	801.0	
	1 FRONT BUMPER REINFORCEMENT (CONSISTENT)	DISTORTED	665.0	
	1 FRONT BUMPER SPONGE (CONSISTENT)	TORN	302.0	
	2 FRONT BUMPER SIDE RETAINERS @ \$35.00 (CONSISTENT)	BENT	70.0	
	1 SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	30.0	3
	1 FRONT BUMPER TOW COVER (CONSISTENT)	NOT NECESSARY	28.0	
	2 HEADLAMPS @ \$2850.00 (CONSISTENT)	CRACKED	5,700.0	
	1 FRONT GRILLE (CONSISTENT)	BROKEN	803.3	
	1 FRONT GRILLE LOGO (CONSISTENT)	MISSING	65.0	
	1 BONNET (CONSISTENT)	BUCKLED	923.3	923.3

Report Ref No. CC4/ASM19011472/Upa3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT SUPPORT PANEL (CONSISTENT)	BENT	792.50	617.50
1	FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	TORN	368.40	368.40
1	AIR CON CONDENSER (CONSISTENT)	BENT / PUNCTURE	911.00	696.00
2	AIR CON CONDENSER SIDE GARNISH @ \$208.00 (CONSISTENT)	TORN	416.00	416.00
1	AIR CON SUCTION HOSE (CONSISTENT)	NOT NECESSARY	150.00	
1	AIR CON DISCHARGE HOSE (CONSISTENT)	BENT	166.00	166.00
1	HORN UNIT (CONSISTENT)	CRACKED	105.00	105.00
2	FRONT BUMPER REINFORCEMENT BRACKETS @ \$205.00 (CONSISTENT)	BENT	410.00	410.00
1	OIL COOLER (CONSISTENT)	PUNCTURE	620.00	620.00
1	OIL COOLER HOSE (CONSISTENT)	NOT NECESSARY	30.00	
1	RADIATOR (CONSISTENT)	DISTORTED	885.00	716.00
1	RADIATOR FAN ASSY (CONSISTENT)	CRACKED / JAMMED	820.00	621.70
2	FRONT FOG LAMP COVERS @ \$95.00 (CONSISTENT)	TWISTED	190.00	190.00
2	FRONT FOG LAMPS @ \$258.00 (CONSISTENT)	CRACKED	516.00	516.00
	LESS 10% DISCOUNT		+	-1,563.53
			43,940.70	14,071.77
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (4 PCS) (SN) (CONSISTENT)	SHORTED	380.00	200.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	
1	SET REAR FLOOR PANEL INSULATOR (SN) (CONSISTENT)	NOT NECESSARY	300.00	
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	
1	REAR FENDER GLASS SEALANT N/S (SN) (CONSISTENT)	NOT NECESSARY	50.00	
1	SET REAR VIEW CAMERA CAM (SN) (CONSISTENT)	NOT NECESSARY	500.00	
1	REAR WINDSCREEN SOLAR FILM (SN) (CONSISTENT)	NOT NECESSARY	300.00	
1	REAR LICENCE PLATE W/HOLDER (SN) (CONSISTENT)	NOT NECESSARY	50.00	
1	FRONT LICENCE PLATE W/HOLDER (SN) (CONSISTENT)	BENT	50.00	40.00
1	BOT RADIATOR COOLANT (SN) (CONSISTENT)	NECESSARY	50.00	30.00
	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	The second secon	1,780.00	270.00

Report Ref No. CC4/ASM19011472/Upa3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX REAR EXHAUST.		150.00	60.00
	TO DISMANTLE & REPLACING REAR FENDER GLASS N/S.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX, SEAT, CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	
	TO SPRAY RUST PROOFING.		180.00	100.00
	TO REFILL AIR CON GAS.		150.00	100.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO TRANSFER TAILGATE COMPONENTS.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL.		3,000.00	1,200.00
	TO PUTTY & SPRAY PAINTING.		3,000.00	1,600.00
			8,170.00	3,220.00
	GRAND TOTAL		53,890.70	17,561.77

RECOMMENDED COST OF LUMP SUM REPAIRS	14,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM19011472/Upa3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.