



CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



Company Reg No. 200609327M
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Leong Eng Chai		Cust No/Name	/Leong Eng Chai
Blk 275A Bishan St 24		Reg No/Reg Date	SGY8558R / 05/07/2012
#10-118		Date In/Mileage	/ 0
Singapore 571275		Chassis No	VF7UA5FV8CJ538536
Contact No Mobile: 91540439		Engine No	10FJBS1423436
		Make/Model	CIT/GC4P DYNAMIQUE 1.6 EGS
		Colour/Trim	T6M / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	26/06/2019/ 12:42	BLC	442 / CocoLu	14497

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000				900 1200.00
RENEW FRT DOOR LH, WINDMIRROR LH				180 300.00
E PNT88000				630 840.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS TO FACILITATE REPAIR				
E PNT98000				
SPRAY PAINT FOR FRT DOOR LH, WINDMIRROR LH				50.00
A 54900099				300.00
CHECK WIRING & ELECTRICAL SYSTEM				
A 54900099				40 50.00
CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				
M SUNDRY				20.00
APPLY SEALANT FOR ACCIDENT PORTION				
M SUNDRY				
Sundry				
M FRONT DOOR LH	1.00	1277.00	0.00	1277.00
M DOOR HINGE LH SUP	1.00	114.00	0.00	114.00
M DOOR HINGE LH INF	1.00	114.00	0.00	114.00
M DR WEATHERSTRIP LH	1.00	73.00	0.00	73.00
M SIDE SILL SEAL LH	1.00	73.00	0.00	73.00
M DOOR PROTECTOR LH	1.00	172.00	0.00	172.00
M WINDOW OUTSIDE LH	1.00	49.00	0.00	49.00
M EXT VIEW MIRROR LH	1.00	613.00	0.00	613.00

SURVEYOR NAME: Ram-409001006

SURVEYOR SIGNATURE: [Signature]

DATE: 22/07/19 12:40

REMARKS: 4 days

Ready before paint

Confirm & accepted by

Parts	2,485.00
Labour	2,690.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	70.00
Total(w/o GST)	5,245.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : Rasul - LKK
Company : EQ
DOA : 26/06/2019
CSE : Coco
Date of Survey : 22/07/2019

VEHICLE NO : SGY8558R
MODEL : CIT/ GC4P DYNAMIQUE 1.6 EGS
WIP : 14497

Email :

Material	:	\$	2,427.00
Labour	:	\$	2,120.00
Sub-Total	:	\$	4,547.00
	:		
Less Excess	:	\$	-
Total	:	\$	4,547.00
GST 7%	:	\$	318.29
Grand Total	:	\$	4,865.29
Finalise By/Date	:	JoJo dtd	06/08/2019

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 4 WORKING DAYS + Days () Weekends
+ Days () Public Holiday
+ 1 Survey - 22/07/2019 - Mon
TOTAL DAYS REPAIR TOOK = 5

☒ TP Claim EQ - GBG4569P

☒ Claim GIA / LTA fee \$ 2.00

☐ Claim Loss ☐ Use ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
EQ INSURANCE COMPANY LIMITED MOTOR CLAIM DEPARTMENT 5 MAXWELL ROAD #17-00 TOWER BLOCK, MND COMPLEX SINGAPORE 069110 Contact No	Cust No/Name /Leong Eng Chai Reg No/Reg Date SGY8558R*CC1/ 05/07/2012 Date In/Mileage 22/07/2019/ 138454 Chassis/Package VF7UA5FV8CJ538536 /NOT Engine No 10FJBS1423436 Make/Model CIT/GC4P DYNAMIQUE 1.6 EGS Colour/Trim T6M / BK



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CTP00073	Cash	06/08/2019/ 13:49	TLC	881 / Jojo Cheng	14497	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT DOOR LH, WINDMIRROR LH				✓ 900.00 ✓
E PNT88000 REMOVE & INSTALL FRONT DOOR TRIMS AND GLASS TO FACILITATE REPAIR				✓ 180.00 ✓
E PNT98000 RESPARY FRONT DOOR LH, WINDMIRROR LH				✓ 630.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 50.00 ✓
A 54900099 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				✓ 300.00 ✓
M SUNDRY APPLY SEALANT FOR DAMAGED PORTION				✓ 40.00 ✓
M SUNDRY SUNDRY				✓ 20.00 ✓
X FRONT DOOR LH	1.00	1277.00	0.00	✓ 1277.00 ✓
X DR WEATHERSTRIP LH	1.00	73.00	0.00	✓ 73.00 ✓
X SIDE SILL SEAL LH	1.00	73.00	0.00	✓ 73.00 ✓
X DOOR PROTECTOR LH	1.00	172.00	0.00	✓ 172.00 ✓
X EXT VIEW MIRROR LH	1.00	613.00	0.00	✓ 613.00 ✓
X BADGE	1.00	52.00	0.00	52.00
X WINDOW MECH LH] supp	1.00	167.00	0.00	167.00
Z TEXT EQ TP CLAIM GBG4569P DOA: 26/06/2019 SURVEYOR: RASUL LKK 22/07/2019				

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	2,427.00	Nett	4,547.00
Labour	2,060.00	7% GST on	318.29
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	4,865.29
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	60.00	Total Due	4,865.29
Total(w/o GST)	4,547.00		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



Exceptional Journeys

SUPPLEMENTARY

INSURANCE CO : EQ INSURANCE COMPANY LIMITED

REGISTRATION NO : SGY8558R

S/N	Description	Qty	Unit Price	Disc%	Amount
PARTS					
1	BADGE <i>new /</i>	1.00	52.00	0.00	52.00
2	WINDOW MECH LH <i>4 /</i>	1.00	167.00	0.00	167.00
Total Parts					219.00
7 % GST					15.33
Grand Total					234.33

Thank You.

Yours faithfully

CYCLE & CARRIAGE FRANCE PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554

Car No: SG1855JR WIP 14497

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? / Supp	PSA Sign	Photo Taken	Remarks
1	FA Failer (090)	? / Supp	<i>[Signature]</i>	<i>25.01.2019</i>	8665RV
2	Art poor water reducer (4H)	? / Supp			9221 CV
3		? / Supp			
4		? / Supp			
5		? / Supp			
6		? / Supp			
7		? / Supp			
8		? / Supp			
9		? / Supp			
10		? / Supp			
11		? / Supp			
12		? / Supp			
13		? / Supp			
14		? / Supp			
15		? / Supp			
16		? / Supp			
17		? / Supp			
18		? / Supp			
19		? / Supp			
20		? / Supp			

DATE	TAKEN BY
24.7.2019	<i>[Signature]</i>
Model:	<u>Rashid</u>
Surveyor:	<u>CF</u>
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF DAMAGED PARTS (DPS)	
PHOTO OF CEILITE BENCH	
REMOVE & INSTALL ENGINE	
REMOVE & INSTALL DASHBOARD	
PHOTO 34 SUSP & U/C REMOVE	

