



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Leong Eng Chai		Cust No/Name	/Leong Eng Chai
Blk 275A Bishan St 24		Reg No/Reg Date	SGY8558R / 05/07/2012
#10-118		Date In/Mileage	/ 0
Singapore 571275		Chassis No	VF7UA5FV8CJ538536
Contact No Mobile: 91540439		Engine No	10FJBS1423436
		Make/Model	CIT/GC4P DYNAMIQUE 1.6 EGS
		Colour/Trim	T6M / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	26/06/2019/ 12:42	BLC	442 / CocoLu	14497

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000				900 1200.00
RENEW FRT DOOR LH, WINDMIRROR LH				180 300.00
E PNT88000				630 840.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS TO FACILITATE REPAIR				
E PNT98000				
SPRAY PAINT FOR FRT DOOR LH, WINDMIRROR LH				50.00
A 54900099				300.00
CHECK WIRING & ELECTRICAL SYSTEM				
A 54900099				40 50.00
CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				
M SUNDRY				20.00
APPLY SEALANT FOR ACCIDENT PORTION				
M SUNDRY				
Sundry				
M FRONT DOOR LH	1.00	1277.00	0.00	1277.00
M DOOR HINGE LH SUP	1.00	114.00	0.00	114.00
M DOOR HINGE LH INF	1.00	114.00	0.00	114.00
M DR WEATHERSTRIP LH	1.00	73.00	0.00	73.00
M SIDE SILL SEAL LH	1.00	73.00	0.00	73.00
M DOOR PROTECTOR LH	1.00	172.00	0.00	172.00
M WINDOW OUTSIDE LH	1.00	49.00	0.00	49.00
M EXT VIEW MIRROR LH	1.00	613.00	0.00	613.00

SURVEYOR NAME: Ram-4090010008SURVEYOR SIGNATURE: [Signature]DATE: 22/07/19 @ 1240REMARKS: 4 days
Resy before paint

Confirm & accepted by

Authorized signatory and company stamp

Parts	2,485.00
Labour	2,690.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	70.00
Total (w/o GST)	5,245.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.