



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: Great Eastern General Insurance Limited

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/06/2019
Vehicle Reg. No.:	SKR8099M	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	MOHAMED SARHAN BIN MOHAMED SALLEH		
Make/Model:	VOLKSWAGEN JETTA, 1.4 (A)	Vehicle Reg. Date:	10/03/2015
Vehicle Colour:	BLACK	Chassis No:	WVWZZZ16ZFM002459
Engine No:	CAXE89341		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	-		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	LKK Auto Consultants hence notify	Amount
Parts	the Repairer of the following:	0.00
Miscellaneous Items	• To resurvey before/after spray painting	11.00
Labour	• To display damaged part(s) during resurvey	660.00
Paintwork Labour	• Parts prices are subject to confirmation	0.00
Towing	• Third party survey is on a "Without Prejudice" basis	0.00
	• No illegal modification(s) is allowed	
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
	Gross Total (\$\$)	671.00
	+ GST 7.00% (\$\$)	46.97
	Nett Amount (\$\$)	717.97

This claim is handled by: BOBO

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2019)**Parts:** 143 VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKR8099M)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER - REPAIR	10.00	0.00	-
Total Parts (S\$)						0.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR REAR BUMPER, REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	200 300.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	200 300.00
3	TO REMOVE & REFIX REVERSE SENSOR TEST & CHECK WIRING	New	30 60.00
Gross Labour Cost (S\$)			660.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >