

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE PTE
Chassis No: JHMGK3850GX220094
License No: SKZ3545H
Mileage: 56665
Engine No: L13B11010122

Document No: SVO19045286
Printed By: SHNG
Order Date: 15. July 2019
Order Time: 2:52:01 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUA KIEN SOON OWNER INSURER: TOKIO ACC DATE: 26/07/2019 SURVEYED BY: RASUL DATE: 15/07/2019 REF NO: TP INSURER: AXA TP VEH: GBE5942Z						
91505-TM8-003	CLIP, BUMPER	4	2.30 ✓	25	6.90	0.48	7.38
04711-T5A-000ZZ	FACE, FR. BUMPER	1	504.60 ✓	25	378.45	26.49	404.94
71190-T5A-000	BRACKET, L. HEADLIGHT	1	21.90 ✓	25	16.42	1.15	17.57
91505-TM8-003	CLIP, BUMPER	17	2.30 ✓	25	29.32	2.05	31.37
	SUM PARTS:				431.09	30.17	461.26
BOSUN	0701 SUNDRIES	1	30.00 ✓		30.00	2.10	32.10
BML01I	0701 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS. (N)	1	180.00 ✓		180.00	12.60	192.60
BKBH01M	1729 CUT OFF & RENEW BULKHEAD. STRAIGHTEN ALIGN CHASSIS & RENEW DAMAGE PARTS.	1	560.00 ✓		560.00	39.20	599.20
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	450.00 ✓		450.00	31.50	481.50
	SUM LABOUR:				1,220.00	85.40	1,305.40
	TOTAL SGD				1,651.09	115.57	1,766.66
	Total Payable (SGD)						1,766.66

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No: M200050223
Company Ref. No: S60FC1380G

Customer	: AXA INSURANCE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19002836	Page	1
Registration No	: SKZ3545H	Date	: 27. Jun 2019		
Chassis No	: JHMGK3850GX220094	Customer No.	: WZA006		
Model	: JAZZ 1.3LXR CVT 16YM	Svc Advisor	: NG SIN HAI		
Owner's Name	: CHUA KIEN SOON	Engine No	: L13B11010122		
Ins Policy No.	:	Date Time	: 27. Jun 2019 7:51:47 PM		
Date of Accident	: 27/6/2019	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (JINO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
33150-T5A-J81	HEADLIGHT ASSY.L ?	1	479.70	25	359.77	25.18	384.95
60100-T5A-000ZZ	HOOD COMP X	1	537.50	25	403.12	28.22	431.34
71105-T5A-000	COVERFR.GRILLE X	1	12.00	25	9.00	0.63	9.63
71120-TAR-003	GRILLE ASSYFR. X	1	258.10	25	193.57	13.55	207.12
91505-TM8-003	CLIP.BUMPER m	4	2.30	25	6.90	0.48	7.38
04711-T5A-000ZZ	FACE.FR.BUMPER 7mm	1	504.60	25	378.45	26.49	404.94
71102-T5A-000	LOWER GRILLEFR.BUMPER ?	1	28.30	25	21.22	1.49	22.71
71103-T5A-000	GARNISHR.FR.BUMPER ?	1	11.30	25	8.47	0.59	9.06
71104-T5A-000ZF	COVERFR.TOWING X	1	14.50	25	10.87	0.76	11.63
71108-T5A-000	GARNISHL.FR.BUMPER X	1	11.30	25	8.47	0.59	9.06
71110-T5A-000	SPOILERFR.BUMPER LIP X	1	58.00	25	43.50	3.05	46.55
71130-T5A-000ZZ	BEAM COMPFR.BUMPER	1	223.80	25	167.85	11.75	179.60
71140-T5A-000	BRACKETR.HEADLIGHT X	1	24.10	25	18.07	1.26	19.33
71145-T5A-000	BASEFR.LICENCE PLATE X	1	52.00	25	39.00	2.73	41.73
71190-T5A-000	BRACKETL.HEADLIGHT X	1	21.90	25	16.42	1.15	17.57
71193-T5A-000	SPACERR.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP.BUMPER m	17	2.30	25	29.32	2.05	31.37

Printed on 27/6/2019 7:59:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual items.

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	AXA INSURANCE PTE LTD	Document No.	SQT19002836	Page	2
	8 SHENTON WAY	Date	27 Jun 2019		
	#27-01 AXA TOWER	Customer No.	WZA006		
	SINGAPORE 068811	Svc Advisor	NG SIN HAI		
Registration No.	SKZ3545H	Engine No.	L13B11010122		
Chassis No.	JHMGK3850GX220094	Date Time	27 Jun 2019 7:51:47 PM		
Model	JAZZ 1.3LXR CVT 16YM	Surveyor Name			
Owner's Name	CHUA KIEN SOON	Survey Date			
Ins Policy No.		Authorisation Date			
Date of Accident	27/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
60261-T5R-A00ZZ	PANELL FR.FENDER X	1	398.60	25	298.95	20.93	319.88
74100-T5A-000	FENDER ASSY FR INNER X	1	73.30	25	54.97	3.85	58.82
90682-SEA-003	CLIP BUMPER X	6	2.60	25	11.70	0.82	12.52
91501-TR0-003	CLIP INNER FENDER X	22	2.80	25	46.20	3.23	49.43
60400-T5B-310ZZ	BULKHEAD COMPFR X	1	361.70	25	286.27	20.04	306.31
80100-T5B-003	CONDENSER ASSY X	1	704.40	25	528.30	36.98	565.28
19010-SR1-901	RADIATOR COMP X	1	1211.20	25	908.40	63.59	971.99
08CLA-P9911LKE	COOLANT ANTI-FREEZE TYPE 2 X	6	23.20	25	104.40	7.31	111.71
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J X	1	836.00	25	627.00	43.89	670.89
Sum Item					4640.78	324.86	4,965.63
B05UN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	1	380.00	X 30	380.00	26.60	406.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS	1	330.00	X 30	330.00	23.10	353.10
BKBH01M	CUT OFF & RENEW BULKHEAD STRAIGHTEN	1	2500.00	X 50	2500.00	175.00	2675.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	1	2000.00	X 45	2000.00	140.00	2140.00
BKBU01R	REMOVE AND RENEW LHF RIM	1	50.00	X 10	50.00	3.50	53.50
Sum Labor					5540.00	387.80	5,927.80

Survey By	RASUL - Hp 90010068	Total Amount	10,180.78	712.66	10,893.45
Date & Time	15/6/19 @ 1435	Total (Inclusive of GST)			10,893.45
Excess	3 days				
Status					
Signature	Razzy 54 print				

Printed on 27/6/2019 7:59:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$55.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

LEK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to fluctuation
- Third party survey is on a "Best Bid" basis
- No illegal modification is allowed
- Supplementary item(s) must be recommended and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: