



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19002836	Page	1
	8 SHENTON WAY	Date	: 27. Jun 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: NG SIN HAI		
Registration No	: SKZ3545H	Engine No	: L13B11010122		
Chassis No	: JHMGK3850GX220094	Date Time	: 27. Jun 2019 7:51:47 PM		
Model	: JAZZ 1.3LXR CVT 16YM	Surveyor Name	:		
Owner's Name	: CHUA KIEN SOON	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
33150-T5A-J81	HEADLIGHT ASSY,L. ?	1	479.70	25	359.77	25.18	384.95
60100-T5A-000ZZ	HOOD COMP X	1	537.50	25	403.12	28.22	431.34
71105-T5A-000	COVERFR.GRILLE X	1	12.00	25	9.00	0.63	9.63
71120-TAR-003	GRILLE ASSYFR. X	1	258.10	25	193.57	13.55	207.12
91505-TM8-003	CLIP,BUMPER m	4	2.30	25	6.90	0.48	7.38
04711-T5A-000ZZ	FACE,FR.BUMPER 2mm /	1	504.60	25	378.45	26.49	404.94
71102-T5A-000	LOWER GRILLEFR.BUMPER ?	1	28.30	25	21.22	1.49	22.71
71103-T5A-000	GARNISHR.FR.BUMPER ?	1	11.30	25	8.47	0.59	9.06
71104-T5A-000ZF	COVERFR.TOWING X	1	14.50	25	10.87	0.76	11.63
71108-T5A-000	GARNISHL.FR.BUMPER X	1	11.30	25	8.47	0.59	9.06
71110-T5A-000	SPOILERFR.BUMPER LIP X	1	58.00	25	43.50	3.05	46.55
71130-T5A-000ZZ	BEAM COMPFR.BUMPER X	1	223.80	25	167.85	11.75	179.60
71140-T5A-000	BRACKETR.HEADLIGHT X	1	24.10	25	18.07	1.26	19.33
71145-T5A-000	BASEFR.LICENCE PLATE X	1	52.00	25	39.00	2.73	41.73
71190-T5A-000	BRACKETL.HEADLIGHT X ?	1	21.90	25	16.42	1.15	17.57
71193-T5A-000	SPACERR.FR.BUMPER 1.7	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER m	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER m	17	2.30	25	29.32	2.05	31.37

Printed on 27/6/2019 7:59:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No : SKZ3545H

Chassis No : JHMGK3850GX220094

Model : JAZZ 1.3LXR CVT 16YM

Owner's Name : CHUA KIEN SOON

Ins Policy No. :

Date of Accident : 27/6/2019

Document No. : SQT19002836

Date : 27. Jun 2019

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : L13B11010122

Date | Time : 27. Jun 2019 7:51:47 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
60261-T5R-A00ZZ	PANELL.FR.FENDER X	1	398.60	25	298.95	20.93	319.88
74100-T5A-000	FENDER ASSYR.FR.INNER X	1	73.30	25	54.97	3.85	58.82
90682-SEA-003	CLIP ABUMPER X	6	2.60	25	11.70	0.82	12.52
91501-TR0-003	CLIP,INNER FENDER X	22	2.80	25	46.20	3.23	49.43
60400-T5B-310ZZ	BULKHEAD COMPFR. X	1	381.70	25	286.27	20.04	306.31
80100-T5B-003	CONDENSER ASSY X	1	704.40	25	528.30	36.98	565.28
19010-5R1-901	RADIATOR COMP X	1	1211.20	25	908.40	63.59	971.99
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 X	6	23.20	25	104.40	7.31	111.71
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J X	1	836.00	25	627.00	43.89	670.89
Sum Item					4640.79	324.86	4,965.65
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	380.00	X	380.00	26.60	406.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	330.00	X	330.00	23.10	353.10
BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN	1	2500.00	560	2500.00	175.00	2675.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2000.00	450	2000.00	140.00	2140.00
BKBU01R	REMOVE AND RENEW LHF RIM	1	50.00	X	50.00	3.50	53.50
Sum Labor					5540.00	387.80	5,927.80

Survey By

Date & Time

Excess

Status

Signature

RASUL - Hp 90010068

15/6/19 @ 1435

3 days

Resy 54 paint

Total Amount 10,180.79 712.66 10,893.45

Total (Inclusive of GST) 10,893.45

Printed on 27/6/2019 7:59:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: