


**FALCON-AIR AUTO SERVICES PTE LTD**CO. REG. NO.: 1995-01140-D  
GST REG. NO.: 19-9501140-D

FALCON-AIR

SONG LIN RESTAURANT  
15 JALAN TEPONG  
#03-19 JURONG FOOD HUB SINGAPORE 619336Attention : Motor Claim Department  
Contact : 93274959

Estimate : ES003482

Date : 27/06/2019  
Vehicle Num. : GBF876J  
Make/Model : NISSAN NV350  
Chassis/Eng# : JN1MC2E26Z0006415  
Accident Date : 26/06/2019  
Claim No. :  
Reference : TP NTUC VS AXA  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|                                       |   |                             |  |                    |
|---------------------------------------|---|-----------------------------|--|--------------------|
| NETT ITEMS :                          |   |                             |  |                    |
| 1.                                    | 1 | TAILGATE                    |  | 1,740.00 <i>bt</i> |
| 2.                                    | 1 | TAILGATE LOCK               |  | 261.00 <i>?</i>    |
| 3.                                    | 1 | TAILGATE LOGO               |  | 59.70 <i>neu</i>   |
| 4.                                    | 1 | TAILGATE EMBLEM NV350/URVAN |  | 101.30 <i>neu</i>  |
| 5.                                    | 1 | REAR BUMPER                 |  | 600.50 <i>de</i>   |
| 6.                                    | 1 | REAR BUMPER BEAM            |  | 169.00 <i>?</i>    |
| 7.                                    | 1 | REVERSE SENSOR              |  | 200.00 <i>neu</i>  |
| Nett Total S\$ :                      |   |                             |  | 3,131.50           |
| 10.00% Discount S\$ :                 |   |                             |  | 313.15             |
|                                       |   |                             |  | 2,818.35           |
| SPECIAL NETT ITEMS :                  |   |                             |  |                    |
| 1.                                    | 1 | SEALANT                     |  | 45.00 <i>4 One</i> |
| 2.                                    | 1 | 70 KM/HR STICKER            |  | 10.00 <i>neu</i>   |
| 3.                                    | 1 | 8 PAX STICKER               |  | 10.00 <i>neu</i>   |
| Special Nett Total S\$ :              |   |                             |  | 65.00              |
| LABOUR :                              |   |                             |  |                    |
| TO REMOVE/REFIX REAR WINDSCREEN GLASS |   |                             |  | 120.00 <i>100</i>  |

CONTINUE / ...

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

MONDAY

LKK

Page 2 / 2

## FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D  
GST REG. NO.: 19-9501140-D

FALCON-AIR

SONG LIN RESTAURANT  
15 JALAN TEPONG  
#03-19 JURONG FOOD HUB SINGAPORE 619336

Attention : Motor Claim Department

Contact : 93274959

Estimate : ES003482

Date : 27/06/2019  
Vehicle Num. : GBF876J  
Make/Model : NISSAN NV350  
Chassis/Eng# : JN1MC2E26Z0006415  
Accident Date : 26/06/2019  
Claim No. :  
Reference : TP NTUC VS AXA  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|  |  |                                                                   |  |             |
|--|--|-------------------------------------------------------------------|--|-------------|
|  |  | TO TRANSFER TAILGATE PARTS/MECHANISM                              |  | 50.00 40.   |
|  |  | TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING                   |  | 80.00 30.   |
|  |  | SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER              |  | 700.00 500. |
|  |  | TO REPAIR REAR END PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS |  | 600.00 400. |
|  |  | Labour Total S\$ :                                                |  | 1,550.00    |

Tauki 97495749  
- up,  
19/8/19 @ 255  
Ready before paint  
Tauki & Indarto work  
04 days

E. &amp; O.E.

Total S\$ : 4,433.35



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg