

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5343L**AAD1906-234***Not Authored
Resony B4 paint*

27 JUN 2019

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHD 5343L

JTDKB3FU203078888

TOYOTA

PRIUS

26.6.19

AXA

11/1/2019

		PART		LIST	
1	1	REAR BUMPER	\$	<i>RM</i> 458.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$	318.80	?
3	1	REAR BUMPER TOWING COVER	\$	<i>RM</i> 14.70	✓
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>RM</i> 552.60	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$	<i>RM</i> 112.70	X
6	1	REAR BUMPER SIDE RETAINER RH	\$	<i>RM</i> 112.70	X
7	1	REAR TAILGATE	\$	<i>RM</i> 1,547.27	X
8	1	REAR TAILGATE OUTER GARNISH	\$	<i>CMT</i> 905.10	✓
9	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>RM</i> 54.70	} X
10	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>RM</i> 54.70	
11	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>RM</i> 93.60	
12	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>RM</i> 93.60	
13	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>RM</i> 55.40	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>RM</i> 55.40	
15	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>RM</i> 254.40	
16	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>RM</i> 51.20	
17	1	REAR TAILGATE WEATHERSTRIP	\$	<i>RM</i> 365.20	
18	1	REAR END PANEL	\$	<i>RM</i> 602.10	
19	1	TAILLAMP LOWER RH	\$	<i>RM</i> 548.40	
20	1	TAILLAMP UPPER RH	\$	<i>RM</i> 557.90	
21	1	REAR BUMPER SIDE RH	\$	<i>RM</i> 232.00	
22	1	REAR BUMPER SIDE LH	\$	<i>RM</i> 232.00	
23	1	TAILLAMP LOWER LH	\$	<i>RM</i> 548.40	
24	1	TAILLAMP UPPER LH	\$	<i>RM</i> 557.90	
25	1	REAR FENDER RH	\$	<i>RM</i> 817.50	
26	1	REAR FENDER LH	\$	<i>RM</i> 817.50	
27	1	BOARD, BACK DOOR TRIM	\$	<i>RM</i> 220.70	
28	1	PANEL SUB-ASSY, QUARTER, LH	\$	<i>RM</i> 836.70	
29	1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	<i>RM</i> 290.50	

Trans-cab Auto Services Pte Ltd

AAD1906-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5343L

30	1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>nn</i>	836.70	}	<i>X</i>
31	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	<i>nn</i>	290.50		
32	1	PAN, REAR FLOOR	\$	<i>nn</i>	572.10		
33	1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	<i>nn</i>	77.00		
34	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	<i>nn</i>	192.90		
35	1	EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	<i>nn</i>	77.00		
36	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	<i>nn</i>	192.90		
TOTAL			\$		13,601.37		
25%			\$		3,400.34		
			\$		10,201.03		

Special Nett

1	1SET	PARKING AID	\$	SL	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	22.00	—
3	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	} X
4	1	WINDSCREEN MOULDING	\$	nn	100.00	
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
6	1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00	
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	
10	1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	
11	1	REAR BUMPER PROTECTOR	\$	nn	100.00	3000
12	1	REAR WHEEL RIM	\$	SL	1,570.55	X
13	1	REAR WHEEL RIM COVER	\$	SL	175.80	X
14	1	SPARE WHEEL RIM	\$	SL	1,570.55	X
15	1	SPARE WHEEL RIM COVER	\$	SL	175.80	X
TOTAL			\$		4,908.10	

TOTAL PARTS \$ 15,109.13**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 7,500.00 *4801*

Trans-cab Auto Services Pte Ltd**AAD1906-234**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5343L

To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	501 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	2501
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	4 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	4 380.00	X

LKK Auto Consultants hence notify the Repairer of the following:
To resurvey before/after spray painting
To check if there is any third party survey

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL	\$	18,270.00
Over All Total	\$	33,379.13

(PART-BY-PART) Repair Days**25 Days****2 days**