

1552/10

INS. CASE OWNER:

ECON 90A

CC 3/CTI1901

1490

C^{a3} h^h 2/19

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

27/6/19

Date / Time:

27/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJW 3833D

Name of Insured:

Wb Tek Kiong

Insured Tel No.:

HP:

26/6/19

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MB Qinhxin

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SWMLAD 212038

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHC 571P

INSRS:
WSP:
Tel:
Liability:
RMKS:Trans
cabINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHC 571P - X

SJW 3833D - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 11/07/19 - vic

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

11/07/19

- MIB REQUESTED. OLD EXTING FROM
GUP ROAD. SEND LETTER & EMAIL TO
OI TO NOTIFY TP CLAIM & NCD- EMAIL TO TP & REQUEST VIDEO
FOOTAGE.

- TYPE REPORT WHILE PENDING TP LOD.

- REPORT DONE

- ORIGINAL TP LOD IN.

21/08/19

- GIVE MANDATE APPROVAL TO OI

13/03/2020

- OI APPROVED MANDATE. SEND 1st OFFER
TO TP.

17/03/2020

- RECEIVED BV. TP ACCEPTED OFFER.

- ALL DONE IN ORDER

PRELIMINARY ADVICE

Date/Time:

28/06/19

Sent By:

K3

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L19

SS

4,100.00

(3

days)

Reduction:

91

%

Email

Call

FINAL SETTLEMENT

Date/Time:

13/03/2020

Confirm with

WAI YIN

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

1

If NO or B 28, Ass. Lia:

Repair Cost:

(W/GSC)

SS

4,387.00

Loss of Rental (LOR):

SS

297.39

(3

days)

x \$99.13

Loss of Use (LOU):

SS

-

(S

x

days)

Loss of Income (LOI):

SS

150.00

x 3

days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS

7.19

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost:

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Total:

SS

4,841.88

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4,840.00

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

COPY SENT
17/13/2020* BV - is company chap.
try to submit.

ASS. REC. BY:

REF:

CTZ1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 5771P Yr Regn: 07, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Renault Latitude c.c. 1995Colour M. White IRW A/C: Insured / Std / NI / NASp. Reading 452864 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIF1ABL 15AUC 281588Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal. 8 mm - R/Bal. 8 mmL/Bal. 8 mm - L/Bal. 8 mmD.O.A. 26/6/19 D.O.I. 27/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to11 Lm @ 4100kCRD: \$46,909.79/91%

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

☐ : Interview (\$ _____)

Fees: _____

☐ : Tech Invs (\$ _____)

Others: _____

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19011490/Khb3

Date: 28.06.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC5771P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.06.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	51,009.79
Revised Estimate Amount	: S\$	4,100.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P**AAD1906-237***Not Authored*
1 Sup @ 4100

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5771P

VF1ABL15AUC281588

RENAULT

LATITUDE

26.6.19

CHINA TAIPING

10/7/2015

PART		LIST	
1	DOOR PANEL REAR LH	\$	2,844.66
1	DOOR GUIDE REAR LH	\$	176.82
1	DOOR HINGE UPPER LH	\$	274.50
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	203.06
1	DOOR LOCK REAR LH	\$	908.75
1	DOOR HANDLE OUTER REAR LH	\$	126.49
1	DOOR HANDLE CAP REAR LH	\$	35.52
1	DOOR HANDLE SEAL REAR LH	\$	7.89
1	DOOR HANDLE COVER REAR LH	\$	13.22
1	DOOR HANDLE MODULE REAR LH	\$	133.60
1	DOOR REGULATOR REAR LH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH	\$	423.10
1	DOOR MOULDING REAR LH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH	\$	1,509.06
1	DOOR WATER SHIELD REAR LH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR GRAB HANDLE REAR LH	\$	210.96
1	DOOR BLIND REAR LH	\$	741.80

Trans-cab Auto Services Pte Ltd

AAD1906-237

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P

1	DOOR WHEATHESTRIIP REAR LH	\$	Sn	410.66	}	X
1	DOOR SEAL REAR LH	\$	Sn	162.02		
1	DOOR GLASS RUNNER SEAL REAR LH	\$	Sn	229.31		
1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn	334.69		
1	DOOR WAIST SEAL INNER REAR LH	\$	Sn	115.64		
1	DOOR PANEL FRT LH	\$	M	2,844.66		
1	DOOR CHECK FRT LH	\$	Sn	194.77		
1	DOOR LOCK FRT LH	\$	M	908.75		
1	ROCKER PANEL INNER GARNISH LH	\$	Sn	466.51		
1	ROCKER PANEL INNER LH	\$	M	1,024.79		
1	ROCKER PANEL OUTER LH	\$	M	1,184.99		
1	ROCKER PANEL CENTER LH	\$	M	990.25		
1	DOOR MIRROR ASSY LH	\$	Sn	1,483.40		
1	DOOR HARNESS WIRE LH	\$	Sn	2,670.00		
1	FENDER PANEL REAR LH	\$	M	3,299.13		
1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	}	X
1	WHEELARCH REAR LH	\$	M	543.47		
1	TAILLAMP LH	\$	Sn	552.55		
1	TAILLAMP PANEL LH	\$	M	986.70		
1	BUMPER COVER REAR	\$	Bu	1,108.46		
1	BUMPER LOWER REAR	\$	Sn	768.84		
1	BUMPER BRACKET CTR REAR	\$	Sn	113.47		
1	BUMPER BRACKET SIDE LH REAR	\$	Sn	135.97		
1	BUMPER RETAINER LH REAR	\$	Sn	44.99		
1	BUMPER REFLECTOR LH	\$	Sn	43.61		
1	BUMPER BEAM REAR	\$	M	777.52		
1	BUMPER BEAM BRACKET LH REAR	\$	M	225.95		
1	FUEL FLAP	\$	Sn	343.57		
TOTAL		\$		33,306.51		
10%		\$		3,330.65		
		\$		29,975.85		

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	M	100.00	basn
1	FRONT DOOR STICKER 'Trans-Cab'	\$	Sn	80.00	X
1	FRONT DOOR STICKER 'Classic'	\$	Sn	80.00	X
1	DOOR CHECK BOLT	\$	Sn	22.69	X
1	DOOR GUIDE SCREW	\$	Sn	10.85	X

Trans-cab Auto Services Pte Ltd**AAD1906-237**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P

1	DOOR HINGE BOLT	\$	Sh	10.85	
1	DOOR HINGE NUT LH	\$	Sh	14.60	
1	DOOR CHECK NUT	\$	Sh	3.75	
1	DOOR LOCK SCREW L70Y	\$	Sh	6.12	
1	DOOR CATCH SCREW L70Y	\$	Sh	10.06	
1	REAR LEFT TYRE	\$	Sh	300.00	
1	REAR LEFT TYRE RIM	\$	Sh	380.00	
1	FENDER INNER TRIM CLIP LH	\$	nn	28.00	
1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	
1	REAR WINDSCREEN MOULDING	\$	nn	120.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
1	TAILLAMP CLIP LH	\$	nn	5.00	
1SET	PARKING AID	\$	Sh	700.00	
1SET	REAR BUMPER CLIP	\$	nce	66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	X
TOTAL		\$		2,303.94	
TOTAL PARTS		\$		32,279.79	

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 601

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 7,500.00 500

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1906-237

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	7,500.00 <i>600</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 <i>600</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
To rust-proofing of the affected areas.	\$	170.00 <i>300</i>
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 <i>X</i>
To transfer of Rear Bumper fittings, attachment and perform water seepage test.	\$	380.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
TOTAL	\$	18,730.00
Over All Total	\$	51,009.79

LUMP SUM (REPAIR DAY)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25 DAYS*3 days**51,009.79*

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5771P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002770
Chassis No.:	VF1ABL15AUC281588
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Jul 2015
First Registration Date:	10 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$53,004.00
COE Rebate Amount:	\$26,735.00
Total Rebate Amount:	\$41,733.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Jun 2019

OK

Shu Pei (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 9 July 2019 1:38 PM
To: Shu Pei (LKKAUTO)
Subject: RE: OUR REF: SNM19D203038/CHONGBS - Direct Settlement - Accident Involving SJW3833D (OI : CTI - TBA) AND SHC5771P (TP : LKK REF - CC3/CTI19011490/Khb3) on 26.06.2019
Attachments: insured report.PDF

Dear Shu Pei,

Insured report.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 9 July, 2019 9:38 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D203038/CHONGBS - Direct Settlement - Accident Involving SJW3833D (OI : CTI - TBA) AND SHC5771P (TP : LKK REF - CC3/CTI19011490/Khb3) on 26.06.2019

Dear Boon Sen,

Kindly advice whether insured has reported.

If not, kindly lets us have your letter to insured.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Tuesday, 2 July 2019 4:12 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D203038/CHONGBS - Direct Settlement - Accident Involving SJW3833D (OI : CTI - TBA) AND SHC5771P (TP : LKK REF - CC3/CTI19011490/Khb3) on 26.06.2019

Dear Boon Sen,

Kindly advice whether insured has reported.

If not, kindly lets us have your letter to insured for non-reporting.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Monday, 1 July 2019 1:42 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Subject: RE: OUR REF: SNM19D203038/CHONGBS - Direct Settlement - Accident Involving SJW3833D (OI : CTI - TBA) AND SHC5771P (TP : LKK REF - CC3/CTI19011490/Khb3) on 26.06.2019

Dear Shu Pei,

Insured yet to report.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Lim Shu Min

Sent: Monday, 1 July, 2019 1:34 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Subject: OUR REF: SNM19D203038/CHONGBS - Direct Settlement - Accident Involving SJW3833D (OI : CTI - TBA) AND SHC5771P (TP : LKK REF - CC3/CTI19011490/Khb3) on 26.06.2019

Dear Boon Sen,

Please assist and revert LKK.

***** Officer-In-Charge – Chong Boon Sen – 63896171 (file with OIC).**

Thank you

Lim Shu Min

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Shu Pei (LKKAuto) [<mailto:shupe@lkkauto.com>]

Sent: Friday, June 28, 2019 3:47 PM

To: Claims Dept of CTI

Cc: Admin A; Vic (LKKAuto)

Subject: Direct Settlement - Accident Involving SJW3833D (OI : CTI - TBA) AND SHC5771P (TP : LKK REF - CC3/CTI19011490/Khb3) on 26.06.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 5771P at M/s Trans-cab Auto Services Pte Ltd – Ang Mo Kio on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2360.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI19011490/Kha3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 24-03-2020	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJW 3833D	Veh. Inspected	SHC 5771P	
Policy No.	DMPCSN1403651905	Coverage (\$)	0.00	
Claim No.	SNM19D203038/CHONGBS	Excess (\$)	0.00	
Assign From		Assign Date	27/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC281588	Colour	METALLIC WHITE / RED	
Odometer	452664	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2019	Inspection Date	27/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5771P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DOOR PANEL REAR LH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH / RH L70Y	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH	TO REPAIR SEE LABOUR	893.75	-
1	DOOR REGULATOR NUT REAR L70Y	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	SERVICEABLE	6.91	-
1	DOOR CASING REAR LH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-

Report Ref No. CC3/CTI19011490/Kha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR LH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR LH	SERVICEABLE	115.64	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR CHECK FRT LH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH	TO REPAIR SEE LABOUR	908.75	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER LH	TO REPAIR SEE LABOUR	990.25	-
1	DOOR MIRROR ASSY LH	SERVICEABLE	1,483.40	-
1	DOOR HARNESS WIRE LH	SERVICEABLE	2,670.00	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH	TO REPAIR SEE LABOUR	543.47	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-

Report Ref No. CC3/CT119011490/Kha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	FUEL FLAP	SERVICEABLE	343.57	-
	LESS 10% DISCOUNT		-3,330.65	-395.32
			29,975.85	3,557.80
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER '6555-3333' (SN)	NECESSARY	100.00	60.00
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER 'CLASSIC' (SN)	NOT NECESSARY	80.00	-
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT LH (SN)	SERVICEABLE	14.60	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	SERVICEABLE	10.06	-
1	REAR LEFT TYRE (SN)	SERVICEABLE	300.00	-
1	REAR LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-

Report Ref No. CC3/CTI19011490/Kha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
			2,303.92	159.00
	LABOUR			
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND RELIGN HE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER LH, DOOR HINGE LOWER LH, DOOR LOCK REAR LH, DOOR REGULATOR REAR LH, DOOR REGULATOR MOTOR REAR LH, DOOR FINISHER BRACKET INNER REAR LH, DOOR PANEL FRT LH, DOOR LOCK FRT LH, ROCKER PANEL INNER LH, ROCKER PANEL OUTER LH, ROCKER PANEL CENTER LH, FENDER PANEL REAR LH, WHEELARCH REAR LH, TAILLAMP PANEL LH, BUMPER BEAM REAR AND BUMPER BEAM		7,500.00	500.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	660.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CC3/CTI19011490/Kha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
			18,730.00	1,390.00
GRAND TOTAL			51,009.77	5,106.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CC3/CTI19011490/Kha3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.