

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P**AAD1906-237***Not Authored*
1 Sup 841001

Vehicle No.:

Chassis No.:

27 JUN 2019

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5771P

VF1ABL15AUC281588

RENAULT

LATITUDE

26.6.19

CHINA TAIPING

10/7/2015

PART		LIST	
1	DOOR PANEL REAR LH	\$	2,844.66
1	DOOR GUIDE REAR LH	\$	176.82
1	DOOR HINGE UPPER LH	\$	274.50
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	203.06
1	DOOR LOCK REAR LH	\$	908.75
1	DOOR HANDLE OUTER REAR LH	\$	126.49
1	DOOR HANDLE CAP REAR LH	\$	35.52
1	DOOR HANDLE SEAL REAR LH	\$	7.89
1	DOOR HANDLE COVER REAR LH	\$	13.22
1	DOOR HANDLE MODULE REAR LH	\$	133.60
1	DOOR REGULATOR REAR LH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH	\$	423.10
1	DOOR MOULDING REAR LH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH	\$	1,509.06
1	DOOR WATER SHIELD REAR LH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR GRAB HANDLE REAR LH	\$	210.96
1	DOOR BLIND REAR LH	\$	741.80

Trans-cab Auto Services Pte Ltd

AAD1906-237

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P

1	DOOR WHEATHESTRIIP REAR LH	\$	Sn	410.66	}	X
1	DOOR SEAL REAR LH	\$	Sn	162.02		
1	DOOR GLASS RUNNER SEAL REAR LH	\$	Sn	229.31		
1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn	334.69		
1	DOOR WAIST SEAL INNER REAR LH	\$	Sn	115.64		
1	DOOR PANEL FRT LH	\$	M	2,844.66		
1	DOOR CHECK FRT LH	\$	Sn	194.77		
1	DOOR LOCK FRT LH	\$	M	908.75		
1	ROCKER PANEL INNER GARNISH LH	\$	Sn	466.51		
1	ROCKER PANEL INNER LH	\$	M	1,024.79		
1	ROCKER PANEL OUTER LH	\$	M	1,184.99		
1	ROCKER PANEL CENTER LH	\$	M	990.25		
1	DOOR MIRROR ASSY LH	\$	Sn	1,483.40		
1	DOOR HARNESS WIRE LH	\$	Sn	2,670.00		
1	FENDER PANEL REAR LH	\$	M	3,299.13		
1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	}	X
1	WHEELARCH REAR LH	\$	M	543.47		
1	TAILLAMP LH	\$	Sn	552.55		
1	TAILLAMP PANEL LH	\$	M	986.70		
1	BUMPER COVER REAR	\$	Bu	1,108.46		
1	BUMPER LOWER REAR	\$	Sn	768.84		
1	BUMPER BRACKET CTR REAR	\$	Sn	113.47		
1	BUMPER BRACKET SIDE LH REAR	\$	Sn	135.97		
1	BUMPER RETAINER LH REAR	\$	Sn	44.99		
1	BUMPER REFLECTOR LH	\$	Sn	43.61		
1	BUMPER BEAM REAR	\$	M	777.52	}	X
1	BUMPER BEAM BRACKET LH REAR	\$	M	225.95		
1	FUEL FLAP	\$	Sn	343.57		
TOTAL		\$		33,306.51		
10%		\$		3,330.65		
		\$		29,975.85		

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	M	100.00	60sn
1	FRONT DOOR STICKER 'Trans-Cab'	\$	nn	80.00	X
1	FRONT DOOR STICKER 'Classic'	\$	nn	80.00	X
1	DOOR CHECK BOLT	\$	Sn	22.69	X
1	DOOR GUIDE SCREW	\$	Sn	10.85	X

Trans-cab Auto Services Pte Ltd**AAD1906-237**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P

1	DOOR HINGE BOLT	\$	Sh	10.85	}
1	DOOR HINGE NUT LH	\$	Sh	14.60	
1	DOOR CHECK NUT	\$	Sh	3.75	
1	DOOR LOCK SCREW L70Y	\$	Sh	6.12	
1	DOOR CATCH SCREW L70Y	\$	Sh	10.06	
1	REAR LEFT TYRE	\$	Sh	300.00	
1	REAR LEFT TYRE RIM	\$	Sh	380.00	
1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
2	REAR WINDSCREEN SEALANT	\$	na	80.00	
1	REAR WINDSCREEN MOULDING	\$	na	120.00	}
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1	TAILLAMP CLIP LH	\$	na	5.00	
1SET	PARKING AID	\$	Sh	700.00	
1SET	REAR BUMPER CLIP	\$	na	66.00	}
1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	X
TOTAL		\$		2,303.94	

TOTAL PARTS	\$	32,279.79
--------------------	-----------	------------------

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	601
----	--------	-----

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	7,500.00	504
----	----------	-----

To check steering geometry and computer wheel alignment

\$	na	220.00	X
----	----	--------	---

To transfer of rear windscreen fittings and conduct water seepage test.

\$	na	170.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd**AAD1906-237**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	7,500.00 <i>66d</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 <i>60d</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20d</i>
To rust-proofing of the affected areas.	\$	170.00 <i>30d</i>
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 <i>X</i>
To transfer of Rear Bumper fittings, attachment and perform water seepage test.	\$	380.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60d</i>
TOTAL	\$	18,730.00
Over All Total	\$	51,009.79

LUMP SUM (REPAIR DAY)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25 DAYS*3 days*