

ASS. REC. BY:

REF: CS/FCI/9011501/Ascl3n2

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Joanne

of FCI

Date/Time: 28.6.19 3.06pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PBL 9815U

Insured: SHC 8397S

at Workshop m/s JEC Automotive

Tel: 92327457

of 1 Kiki Bula Avenue 6 #03-11

Policy No:

Claim No: D1900 4213 MP54

Sum Insured:

Excess:

Make of Veh:

D.O.A. 18.6.2019

(Client's Record)

1.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28.6.19 3.10pm

Person Contacted: An Xian

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 8397S: CC3/CT17017140/Klub 3n2 D.O.A. 02/09/2017

FBL 9815U: X

01/07/19 @ 17:20 pm revert pending estimate from repairer to Joanne via email

(08/11/13)

REF PCL

ASS. REC. BY: Adrian

ASSIGNMENT

From: Date: 1.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBL 9815U

at Workshop n/s JEC Auto motive

of 1 Kaki Bukit Ave 6 #02-11 Autobay

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBL9815U Yr Regn: 2017 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kymco K-XCT c.c. 199

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 56298 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RFB082000141000341

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/80 R14

R: 150/70 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Mitas

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 01/07/19

Survey held at JEC

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

15/07/19 Confirmed HS \$ 3,700/- @ 6 days with Adrian
(\$ 4,356.50 Red - 54%)

RECEIVED 15 JUL 2019

Date/Time, File Pass to?

15/07/19
Typist

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

3 + RS. 34

Photos

Others

TOTAL

170
50
50+50
53
373

Report Format:

Lump Sum / I.B.L. (\$ 3,700/- 4/5)

MOTOR SURVEY ASSIGNMENT

Date	27-06-2019	Our Ref No. D19004218MFSH
Accident Date	18-06-2019	Claim Type. Third Party
Insured Vehicle	SHC8397S	Third Party Vehicle. FBL9815U
Survey Location	1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY @KAKI BUKIT	
Contact Person.	AH XIAN	
Contact No.	92327457/ 92327457	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	JEC AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	KANNAN SG	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 1 July 2019 5:20 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D19004218MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle FBL 9815U on 01/07/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 28 June 2019 3:20 PM
To: SUR <sur@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D19004218MFSH/1

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 28 June, 2019 3:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004218MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0713Z
Vehicle Details	
Vehicle No.:	FBL9815U
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	KYMCO
Vehicle Model:	K-XCT200I
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	SK40B1000361
Chassis No.:	RFBD82000H1000341
Maximum Power Output:	-
Open Market Value:	\$3,960.00
Original Registration Date:	31 May 2017
First Registration Date:	31 May 2017
Transfer Count:	1
Actual ARF Paid:	\$594.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,301.00
COE Rebate Amount:	\$4,984.00
Total Rebate Amount:	\$4,984.00

The information contained herein is correct as at 01 Jul 2019

OK

JEC AUTO SERVICE

1 Kaki Bukit Ave 6 #02-11 Autobay, Singapore 417883
 Hp: 9232 7457@Ah Xian Tel: 6509 6585 Fax: 6509 6584
 Email: jecautoservice@yahoo.com.sg

7 p 1st Cap
 Shirley.

Vehicle No.: FBL 9815 U

Model: Kymco K-XCT 200

Qty	Description	Amt S(\$)
	<u>List Items</u>	
1	Front fender <i>new</i>	\$ 185.00 ✓
1	Front fork assy <i>new</i>	\$ 1,020.00 ✓
1	Side mirror assy <i>new</i>	\$ 178.00 ✓
1	Handle-bar <i>new</i>	\$ 188.00 ✓
1	Handle-bar balancer <i>new</i>	\$ 60.00 ✓
1	Handle bar grip (1 set) <i>new</i>	\$ 100.00 ✓
1	<i>Broke</i> Clutch lever <i>new</i>	\$ 78.00 ✓
1	Front cowling <i>new</i>	\$ 420.00 ✓
1	Front side cowling <i>new</i>	\$ 320.00 ✓
1	Lower belly panel <i>new</i>	\$ 238.00 ✓
1	Footstep panel <i>new</i>	\$ 168.00 ✓
1	Exhaust assy <i>new</i>	\$ 1,380.00 ✓
1	Exhaust end cap cover <i>new</i>	\$ 120.00 ✓
1	Rear fender <i>new</i>	\$ 195.00 ✓
1	Engine cover assy <i>new</i>	\$ 425.00 ✓
1	Air filter box assy <i>new</i>	\$ 320.00 ✓
1	Main stand <i>new</i>	\$ 145.00 ✓
1	Rear rim <i>new</i>	\$ 320.00 ✓
1	Engine mounting bracket <i>new</i>	\$ 280.00 ✓
1	Rear reflector <i>new</i>	\$ 45.00 ✓
1	Rear side cover <i>new</i>	\$ 285.00 ✓
1	Headlamp <i>new</i>	\$ 840.00 ✓
		\$ 7,310.00
	Less 10%	\$ 731.00
		\$ 6,579.00

3787
~~3477.30~~

3612
 3250.80

<u>Special Nett Items</u>			
1	Front number plate <i>Re ar</i>	\$	28.00 <i>x</i>
1	Steering cone (1 set) <i>Re ar</i>	\$	185.00 <i>x</i>
1	Rear box <i>at</i>	\$	750.00 <i>480</i>
1	Rear box bracket <i>Motor Bent</i>	\$	150.00 <i>x</i>
3	Engine oils <i>Re</i>	\$	120.00 <i>60</i>
		\$	1,233.00

<u>Labour Charges</u>			
1	To provide towing service.	\$	50.00 <i>90</i>
2	To check wiring and reset headlamp focusing	\$	80.00 <i>30</i>
3	To provide labour.	\$	480.00 <i>500</i>
4	To respray painting.	\$	800.00 <i>300</i>
		\$	1,410.00

ESTIMATE PARTS AND LABOUR TOTAL \$

\$ 8,056.50
9222

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 01/07/19
06 days
total. 461080
L/S: 3.7K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011501/Asd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8397S	Veh. Inspected	FBL 9815U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004218MFSH	Excess (\$)	0.00	
Assign From	JOANNEY	Assign Date	28/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	KYMCO K-XCT	c.c	199	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RFBD82000H1000341	Colour	BLACK	
Odometer	56298	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/80 R14	MITAS	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	150/70 R13	MITAS	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/06/2019	Inspection Date	01/07/2019	
Survey held at	JEC AUTOMOTIVE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 9815U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	NOT NECESSARY	185.00	-
1	FRONT FORK ASSY	NOT NECESSARY	1,020.00	-
1	SIDE MIRROR ASSY	CUT	178.00	178.00
1	HANDLE-BAR	NOT NECESSARY	188.00	-
1	HANDLE-BAR BALANCER	CUT	60.00	60.00
1	SET HANDLE-BAR GRIP	NOT NECESSARY	100.00	-
1	BRAKE LEVER	CUT	78.00	78.00
1	FRONT COWLING	CUT	420.00	420.00
1	FRONT SIDE COWLING	CUT	320.00	320.00
1	LOWER BELLY PANEL	CUT	238.00	238.00
1	FOOTSTEP PANEL	CUT	168.00	168.00
1	EXHAUST ASSY	NOT NECESSARY	1,380.00	-
1	EXHAUST END CAP COVER	NOT NECESSARY	120.00	-
1	REAR FENDER	NOT NECESSARY	195.00	-
1	ENGINE COVER ASSY	CRACKED	425.00	425.00
1	AIR FILTER BOX ASSY	CRACKED	320.00	320.00
1	MAIN STAND	NOT NECESSARY	145.00	-
1	REAR RIM	NOT NECESSARY	320.00	-
1	ENGINE MOUNTING BRACKET	BENT	280.00	280.00
1	REAR REFLECTOR	NOT NECESSARY	45.00	-
1	REAR SIDE COVER	CUT	285.00	285.00
1	HEADLAMP	CRACKED	840.00	840.00
	LESS 10% DISCOUNT		-731.00	-361.20
			6,579.00	3,250.80
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	185.00	-
1	REAR BOX (SN)	CUT	750.00	480.00
1	REAR BOX BRACKET (SN)	BENT	150.00	150.00

Report Ref No. CS/FCI19011501/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
3	ENGINE OILS (SN) <u>LABOUR</u> TO PROVIDE TOWING SERVICES. TO CHECK WIRING AND RESET HEADLAMP FOCUSING. TO PROVIDE LABOUR. TO RESPRAY PAINTING.	NECESSARY	120.00	60.00
			1,233.00	690.00
			50.00	40.00
			80.00	30.00
			480.00	300.00
			800.00	300.00
			1,410.00	670.00
GRAND TOTAL			9,222.00	4,610.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CS/FCI19011501/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.