

1	BONNET SEAL <i>nc</i>	1	M51.76.7.351.349	\$ 64.09	\$ 64.09	(A)
2	DEFORMATION LH <i>bt</i>	1	M51.11.7.351.521	\$ 123.63	\$ 123.63	(A)
	TOTAL PARTS			\$ 8,721.22	\$ 9,645.27	
					\$ -	
	TOTAL PARTS COST			\$ 8,721.22	\$ 9,645.27	
	Labour Description					
1	TO REPLACE BONNET, FRONT BUMPER & TO REPAIR ALL			\$ 1,680.00	\$ 2,520.00	
	AREAS AFFECTED BY THE ACCIDENT.					
2	TO RESPRAY BONNET, FRONT BUMPER .			\$ 1,600.00	\$ 1,800.00	
3	TO REMOVE & REPLACE CONDENSER AND RADIATOR FAN ASSY.			\$ 840.00	\$ 840.00	
4	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.			\$ 250.00	\$ 500.00	
5	TO INSTALL THE FRONT BONNET STICKER.			\$ 350.00	\$ 350.00	
6	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.			\$ 70.00	\$ 70.00	
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 150.00	\$ 250.00	
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 250.00	\$ 350.00	
9	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.			\$ -	\$ 200.00	
10	SUNDRIES.			\$ 30.00	\$ 100.00	
				TOTAL LABOUR	\$ 5,220.00	\$ 6,980.00
				TOTAL PARTS	\$ 8,721.22	\$ 9,645.27
				TOTAL	\$ 13,941.22	\$ 16,625.27
				LESS EXCESS	\$ -	\$ -
				TOTAL AFTER EXCESS	\$ 13,941.22	
				GST 7%	\$ 975.89	\$ -
				GRAND TOTAL	\$ 14,917.11	\$ -

NUMBER OF DAYS: 7 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)