

22/03/2002

ASS. REC. BY:

REF: CS/MSG19011516/R1td302

Special Instruction:

Survivor: Rasul

ASSIGNMENT (Office)

From (Person): Mhd Azik

of MS19

Date/Time: 28.6.19 16.14pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 340T

Insured: SLW 6009Z

at Workshop m/s Ding Automotive

Tel: 9329 9929

of 31 Corporation Road

Policy No: 29125248

Claim No: 598178

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26.6.2019

(Client's Record)

1.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28.6.19 4.52pm

Person Contacted: Ah Guang

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 6009Z - X
	SHA 340T CS/EG117022343/T11b2 D.O.A. 22/11/2019
217-	Revised via menmen preli advise
	lump sum \$60007- (Red: 9103.03 : 60%)

ASSIGNMENT

From: Date: 1.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHA 340T

at Workshop m/s Ding Automotive

of 31 Corporation Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHA 340T Yr Regn: 2017 / 86P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRINS HYBRID 1.8 c.c 1798

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 214750 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKB3FH20356277

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 26/06/19

D.O.A. 01/07/19

Survey held at

DING AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRS O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rasul,

AS per my remarks.

RECEIVED 26 AUG 2019

23/8/2019

Date/Time, File Pass to?

☐

Preli. Report

1) 26/8 Typst

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

G + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 6000)

200

11

21

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2019 14:45		28 Jun 2019 16:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

HENG LI LIAN, ID: S6805179G

Main Claimant:

CITYCAB PTE LTD, Co. Reg. No.: 199502839G

Vehicle Reg. No.:

SHA340T

Claim Type:

TP

Vehicle Reg. No. (Insured):

SLW6009Z

Repairer:

Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/06/2019]

Driver/Custodian (Insured):

HENG LI LIAN (), NRIC: S6805179G Email:

Adj Asg. Remarks:

on WP. Liab: Dispute. TP agree on SJE - Assign LKK. Contact: Vadivelan @ 9689 1857 / 6265 7130.

Date of Loss:

26/06/2019 00:00 - :59
[21 Months and 21 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

29125248QMY
Coverage: 16/06/2019 - 15/06/2020

Policy No. (Claimant):

Excess:

Created by insurer

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

View All

Search Tasks

Create New Task

Complete

No results.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 02 Jul 2019

Preliminary Advice

Insured Vehicle No	: SLW6009Z	Accident Date	: 26/06/2019
TP Vehicle No	: SHA340T	Assignment Date	: 28/06/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 6.00
Date of Inspection	: 01/07/2019		
Inspection At	: DING AUTOMOTIVE PTE LTD (HQ) 31 CORPORATION ROAD SINGAPORE 649825		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,103.03
Revised Amount	:S\$	9,850.21
Check Items (Estimated)	:S\$	767.11
Total	:S\$	10,617.32

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/06/2019 17:20
Date Of Accident	26/06/2019 20:35
Exact Location Of Accident	ALONG AYE TOWARDS CLEMENTI AVE 4
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHA340T
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	
Driver	
Name of Driver	TAN HUI SENG
NRIC No	S8107441J
Date Of Birth	09/03/1981
Occupation	OUTDOOR
Date Of Driving Pass	31/05/2001
Driving Experience	18 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81280505
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 572 CHOA CHU KANG STREET 52 #03-268 SINGAPORE
Postcode	680572
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE NOT SUITABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW6009Z
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: V601
NRIC/FIN No.:

Accident Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 26 JUNE 2019 ABOUT 20:35 HOURS I WAS TRAVELLING WITH MY TAXI (SHA 340 T) WITH 2 PASSENGERS TOWARDS CLEMENTI AVENUE 4. ON MY WAY BEFORE EXIT CLEMENTI AVE 4, I VEHICLE (SLW 6009 Z) MAZDA SUDDENLY SQUZBE INTO MY LANE. AT TIME MY FRONT, HAVE 1 LORRY AND ALREADY SLOW DOWN AND THIS VEHICLE (SLW 6009 Z) SQUZBE IN AND I CANT AVOID EVEN AT TIME I ALREADY SLOW DOWN MY TAXI. I TRIED TO AVOID FROM COLLISIONS BUT DUE TO VERY CLOSE DISTANCE MY TAXI COLLIDED WITH OTHER VEHICLE. NO INJURY WAS INVOWED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: VED1.
NRIC/FIN No.:

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

28/06/2019 16:28

JOB-NO: 50111786

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA0340T TRANS: AUTO
 MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT
 OWNER'S INSURER: MS First Capital Insurance Limited
 JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: JTDKB3FU203562771
 ENGINE: 2ZRS059681

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	700 ✓
2 REMOVE & REFIT WIREHARNES & TWO FUSE BOX ASSY	1.00	350.00	0.00	350.00		Y	150 ✓
3 REMOVE & REFIT DASH BOARD ASSY - TO REPLACE FRONT WIREHARNES	1.00	350.00	0.00	350.00 (photo)		Y	150? X
4 RUST PROOFING	1.00	80.00	0.00	80.00		Y	60 ✓
5 SUNDRIES	1.00	50.00	0.00	50.00		Y	20 ✓
6 TO CALIBRATE HEAD LAMP ECU RH	1.00	200.00	0.00	200.00		Y	100/20 ✓
7 ADJUST HEADLAMP AIM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	180.00	0.00	180.00		Y	80 ✓
8 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200 ✓
9 RESPRAY FRONT FENDER RH	1.00	250.00	0.00	250.00		Y	200 ✓
10 RESPRAY FRONT DOOR RH	1.00	250.00	0.00	250.00		Y	X ✓
11 RESPRAY BONNET	1.00	250.00	0.00	250.00		Y	200 ✓
12 RESPRAY WHOLE FRONT RH SIDE PANEL	1.00	250.00	0.00	250.00		Y	150 ✓
TOTAL:		3,460.00	0.00	3,460.00			

MATERIALS

1 FRONT BUMPER <i>100%</i>	1.00	490.50	122.63	367.87 ✓	L	Y	
2 FRONT BUMPER RETAINER LH <i>Xsu</i>	1.00	92.30	23.08	69.22 ✓	L	Y	
3 FRONT BUMPER RETAINER RH <i>ca</i>	1.00	92.30	23.08	69.22 ✓	L	Y	
4 FRONT BUMPER TOWING CAP RH <i>de</i>	1.00	36.30	9.08	27.22 ✓	L	Y	
5 FRONT BUMPER UPPER GRILLE <i>de</i>	1.00	389.20	97.30	291.90 ✓	L	Y	
6 FRONT BUMPER LOWER GRILLE <i>? su</i>	1.00	189.60	47.40	142.20 <i>Xsu</i>	L	Y	
7 FRONT BUMPER REINFORCEMENT CENTER <i>RXsu</i>	1.00	715.90	178.98	536.92 <i>Xsu</i>	L	Y	
8 FRONT BUMPER REINFORCEMENT SPONGE <i>ca</i>	1.00	98.89	24.72	74.17 ✓	L	Y	
9 FOG LAMP RH <i>ca</i>	1.00	950.70	237.68	713.02 ✓	L	Y	
10 HEAD LAMP RH <i>bro</i>	1.00	2,751.60	687.90	2,063.70 ✓	L	Y	
11 HEAD LAMP ECU RH <i>? ca</i>	1.00	633.21	158.30	474.91 ✓	L	Y	
12 FRONT FENDER RH <i>bi</i>	1.00	933.10	233.28	699.82 ✓	L	Y	
13 FRONT FENDER EMBLEM LOGO-HYBRID RH <i>ca</i>	1.00	51.60	12.90	38.70 ✓	L	Y	
14 FRONT FENDER QTR GARNISH RH <i>me</i>	1.00	93.90	23.48	70.42 ✓	L	Y	
15 FRONT FENDER UPPER SEAL RH <i>Xsu</i>	1.00	65.90	16.48	49.42 <i>X</i>	L	Y	
16 FRONT FENDER INNERSHIELD RH <i>Xsu</i>	1.00	201.67	50.42	151.25 <i>X</i>	L	Y	
17 FRONT WINDSCREEN OUTER MOULDING RH <i>Xsu</i>	1.00	165.20	41.30	123.90 <i>X</i>	L	Y	
18 WIPER TANK <i>new</i>	1.00	149.60	37.40	112.20 ✓	L	Y	
19 WIPER TANK INLET NECK <i>de</i>	1.00	89.30	22.33	66.97 ✓	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
20 BONNET HINGE RH <i>photo</i>	1.00	46.80	11.70	35.10 ✓	L	Y	
21 FRONT WIRING HARNESS - HEADLAMP & FOG LAMP & HORN <i>price repair</i>	1.00	6,577.28	644.32	4,932.96 ✓	L (Lebar) ✓	Y	
22 HEAD LAMP UPPER PANEL RH <i>photo</i>	1.00	89.20	22.30	66.90 ✓	L	Y	
23 BRACE SUB-ASSY, FENDER APRON, RH <i>photo</i>	1.00	224.70	56.18	168.52 ✓	L	Y	
24 FRONT FENDER SIDE BRACKET RH <i>photo</i>	1.00	68.70	17.18	51.52 ✓	L	Y	
25 FRONT BUMPER CLIP SET <i>photo</i>	1.00	35.00	0.00	35.00 ✓	S	Y	
26 HEAD LAMP SIGNAL LIGHT BULB RH <i>photo</i>	1.00	15.00	0.00	15.00 ✓	S	Y	
27 FRONT FENDER HOLDER & GROOMET SET RH <i>photo</i>	1.00	25.00	0.00	25.00 ✓	S	Y	
28 FRONT FENDER INNERSHIELD CLIP SET RH <i>photo</i>	1.00	35.00	0.00	35.00 ✓	S	Y	
29 FRONT WINDSCREEN OUTER MOULDING CLIP SET RH <i>photo</i>	1.00	35.00	0.00	35.00 ✓	S	Y	
30 REPAIR BONNET <i>photo</i>	1.00	0.00	0.00	0.00 ✓	S	Y	
31 REPAIR FRONT DOOR RH <i>photo</i>	1.00	0.00	0.00	0.00 ✓	S	Y	
32 FRONT DOOR STICKER-COMFORT DELGRO RH <i>photo</i>	1.00	100.00	0.00	100.00 ✓	S	Y	
TOTAL:		15,442.45	799.42	11,643.03			
TOTAL PARTS & LABOUR:		18,902.45	3,799.42	15,103.03			

EXCESS/LOADING:\$S 0.00

No. Of Day:

*6 days*RE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM: \$SDATE OF SURVEY: 01 107 119 @ 1135

SURVEYED BY:

RASH

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*L-2080**S/N - 65**P - 5392.16**T - 7537.16**202**6029.72**L/S - 6,000**6 days*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jun 2019 14:45		28 Jun 2019 16:14 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HENG LI LIAN , ID: S6805179G								
Main Claimant:	CITYCAB PTE LTD , Co. Reg. No.: 199502839G								
Vehicle Reg. No.:	SHA340T	Date of Loss:	26/06/2019 21:00 - :59 [21 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 598178	Policy/Cover Note No.:	29125248 (Comprehensive) Coverage: 16/06/2019 - 15/06/2020						
Vehicle Reg. No. (Insured):	SLW6009Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/07/2019]								
Driver/Custodian (Insured):	HENG LI LIAN (), NRIC: S6805179G Email:								
Adj Asg. Remarks:	on WP. Liab: Dispute. TP agree on SJE - Assign LKK. Contact: Vadivelan @ 9689 1857 / 6265 7130.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA340T (598178)

[SLW6009Z]




































TP

CITYCAB PTE LTD

Jun 26 2019 9:00PM

[HENG LI LIAN]

Ding Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View In Browser	
Assessment Reports			1 per page <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/07/19 16:02	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/08/19 10:13	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/08/19 10:13	General View	 Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/08/19 10:13	General View	Load JPG	<input checked="" type="checkbox"/>
36	26/08/19 10:13	General View	Load JPG	<input checked="" type="checkbox"/>
37	26/08/19 10:13	General View	Load JPG	<input checked="" type="checkbox"/>
38	26/08/19 10:13	General View	Load JPG	<input checked="" type="checkbox"/>
39	26/08/19 10:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	26/08/19 10:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	26/08/19 10:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	26/08/19 10:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	26/08/19 10:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	26/08/19 10:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	26/08/19 10:13	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	26/08/19 10:14	Photo After repair	Load JPG	<input checked="" type="checkbox"/>
47	26/08/19 10:14	Photo After repair	Load JPG	<input checked="" type="checkbox"/>
48	26/08/19 10:14	Photo After repair	Load JPG	<input checked="" type="checkbox"/>
49	26/08/19 10:14	Photo After repair	Load JPG	<input checked="" type="checkbox"/>
50	26/08/19 10:14	Photo After repair	Load JPG	<input checked="" type="checkbox"/>
51	26/08/19 10:14	Photo After repair	Load JPG	<input checked="" type="checkbox"/>
52	26/08/19 10:14	Photo After repair	Load JPG	<input checked="" type="checkbox"/>
53	26/08/19 10:14	Photo After repair	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/06/19 14:50	Email - PRI	Load PDF	
2	28/06/19 14:51	Email to TP that we will proceed to assign LKK	Load PDF	
3	28/06/19 14:52	SHA340T GIA Rpt	Load PDF	
4	28/06/19 14:53	SLW6009Z GIA Rpt	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19011516/R1TD3E2

Date: 26/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29125248

Claimant Vehicle No : SHA340T

Insured Vehicle No : SLW6009Z

Date of Loss: 26/06/2019

Nature of Claim: TP Claim No: 598178

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA340T

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS059681

Reg. Date: 05/09/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU203562771

Colour: Yellow

Odometer: 214750 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Triangle 6 mm

Rear Left Side: Triangle 6 mm

Front Right Side: Triangle 6 mm

Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,693.09	5,677.20	6,015.89	51.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	1,860.00	1,550.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,103.09	7,537.20	7,565.89	50.09
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	15,103.09	6,000.00	9,103.09	60.27
+ GST 7.00/7.00% (\$\$)	1,057.22	420.00	637.22	60.27
Nett Amount (\$\$)	16,160.31	6,420.00	9,740.31	60.27

INSPECTION

Date of Assignment: 28/06/2019

Date Inspected: 01/07/2019 Inspected At:

Ding Automotive Pte Ltd (HQ)
31 CORPORATION ROAD
Singapore 649825

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Aug 2019)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA340T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	490.50 FL	*490.50 FL
2	1		*FRONT BUMPER RETAINER LH	Serviceable	92.30 FL	*- FL
3	1		*FRONT BUMPER RETAINER RH	Cracked	92.30 FL	*92.30 FL
4	1		*FRONT BUMPER TOWING CAP RH	Deformed	36.30 FL	*36.30 FL
5	1		*FRONT BUMPER UPPER GRILLE	Deformed	389.20 FL	*389.20 FL
6	1		*FRONT BUMPER LOWER GRILLE	Serviceable	189.60 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT CENTER	Serviceable	715.90 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	98.89 FL	*98.89 FL
9	1		*FOG LAMP RH	Cracked	950.70 FL	*950.70 FL
10	1		*HEAD LAMP RH	Broken	2,751.60 FL	*2,751.60 FL
11	1		*HEAD LAMP ECU RH	Cracked	633.21 FL	*633.21 FL
12	1		*FRONT FENDER RH	Buckled	933.10 FL	*933.10 FL
13	1		*FRONT FENDER EMBLEM LOGO - HYBRID RH	Necessary	51.60 FL	*51.60 FL
14	1		*FRONT FENDER QTR GARNISH RH	Missing	93.90 FL	*93.90 FL
15	1		*FRONT FENDER UPPER SEAL RH	Serviceable	65.90 FL	*- FL
16	1		*FRONT FENDER INNERSHIELD RH	Serviceable	201.67 FL	*- FL
17	1		*FRONT WINDSCREEN OUTER MOULDING RH	Not Necessary	165.20 FL	*- FL
18	1		*WIPER TANK	Torn	149.60 FL	*149.60 FL
19	1		*WIPER TANK INLET NECK	Deformed	89.30 FL	*89.30 FL
20	1		*BONNET HINGE RH	Bent	46.80 FL	*46.80 FL
21	1		*FRONT WIRING HARNESS - HEADLAMP & FOG LAMP & HORN (LOCAL REPAIR)	Cut	4,932.96 FS	*200.00 FS
22	1		*HEAD LAMP UPPER PANEL RH	Bent	89.20 FL	*89.20 FL
23	1		*BRACE SUB-ASSY, FENDER APRON, RH	Bent	224.70 FL	*224.70 FL
24	1		*FRONT FENDER SIDE BRACKET RH	Bent	68.70 FL	*68.70 FL
25	1		*SET FRONT BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
26	1		*HEAD LAMP SIGNAL LIGHT BULB RH	Cracked	15.00 FS	*15.00 FS
27	1		*FRONT FENDER HOLDER & GROOMET SET RH	Necessary	25.00 FS	*15.00 FS
28	1		*FRONT FENDER INNERSHIELD CLIP SET RH	Not Necessary	35.00 FS	*- FS
29	1		*FRONT WINDSCREEN OUTER MOULDING CLIP SET RH	Not Necessary	35.00 FS	*- FS
30	1		*FRONT DOOR STICKER - COMFORT DELGRO RH	Not Necessary	100.00 FS	*- FS
31	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,848.13 7,474.60

- List Item Discount on L Items 25.00/25.00% (\$\$) 2,155.04 1,797.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					11,693.09	5,677.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,000.00	700.00
2	REMOVE & REFIT WIREHARNESS & TWO FUSE BOX ASSY	New	350.00	150.00
3	REMOVE & REFIT DASH BOARD ASSY - TO REPLACE FRONT WIREHARNESS	New	350.00	0.00
4	RUST PROOFING	New	80.00	60.00
5	TO CALIBRATE HEAD LAMP ECU RH	New	200.00	120.00
6	ADJUST HEADLAMP AIM & DIAGNOSTIC (CLEAR FAULT CODE)	New	180.00	80.00
7	RESPRAY FRONT BUMPER	New	250.00	200.00
8	RESPRAY FRONT FENDER RH	New	250.00	200.00
9	RESPRAY FRONT DOOR RH	New	250.00	0.00
10	RESPRAY BONNET	New	250.00	200.00
11	RESPRAY WHOLE FRONT RH SIDE PANEL	New	250.00	150.00
12	REPAIR BONNET (NPA)	New	0.00	0.00
13	REPAIR FRONT DOOR RH (NPA)	New	0.00	0.00
Gross Labour Cost (S\$)			3,410.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >