



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving	1 2018 TOYOTA VIOS 1.5 (SMC4338E)
Date of Loss	27 June 2019
Time of Loss	11.30
Loss Description	SMC4338E (INSD) HIT REAR OF GBH1020U (TP)
Comment	<input type="text"/>

### Workshop Details

Total Rebate Amount	<input type="text" value="45569"/>
Nett Loss Amount	\$29,431.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration# SMC4338E

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

29/06/2018



Mileage

16062

Age of Vehicle

0

CATEGORY

POLICY INFORMATION

ASSESSMENT  
INFORMATIONManufacturing  
Year

2018

2018

Make

TOYOTA

TOYOTA

Model

VIOS 1.5

VIOS G (AUTO)

### Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY  
INFORMATION

Driver Name

TAN TAT CHUAN

Date of Birth

6 September 1957

dd/mm/y

Age

61

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No	MR2B23F3X01134197	<input type="text" value="MR2B23F3X01134"/>
Engine No	2NR5239907	<input type="text" value="2NR5239907"/>
Engine Capacity		<input type="text" value="1496"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="75000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	3	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/y"/> 
License Expiration Date		<input type="text" value="dd/mm/y"/> 
Address	BLK 235 YSIHUN STREET 21, #10-452, 760235, Singapore	<input type="text" value=""/>
Address type	Residential	<input type="text" value=""/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text"/>
Marital status	Single	<input type="text"/>
Identification #	S12666821	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

28/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

Other Excess

### Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

### Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195/50R16

Rear Tyre Size

195/50R16

Front left side

BRIDGESTONE6mm

Rear left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

## Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

### Parts

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		FRONT BUMPER GRILLE (WCP) (10%)	Deformed	0	231	No					231	Reviewing	
<input type="checkbox"/>		0	1		L/F BUMPER COVER (WCP) (10%)	Cut	0	93.5	No					93.5	Reviewing	
<input type="checkbox"/>		0	1		FRONT BUMPER (WCP)(10%)	Damaged	0	264	No					264	Reviewing	
<input type="checkbox"/>		0	1		L/F BUMPER BRACKET (WCP)(10%)	Necessary	0	60.5	No					60.5	Reviewing	
<input type="checkbox"/>		0	1		R/F BUMPER BRACKET (WCP)(10%)	Necessary	0	60.5	No					60.5	Reviewing	
<input type="checkbox"/>		0	1		CLIP FASTENING (WCP)(10%)	Necessary	0	22	No					22	Reviewing	
<input type="checkbox"/>		0	1		GRILLE (WCP) (10%)	Cracked	0	66	No					66	Reviewing	
<input type="checkbox"/>		0	1		GRILLE MOULDING (WCP)(10%)	Cracked	0	104.5	No					104.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		CLIP FASTENING (WCP)(10%)	Necessary	0	22	No				22	22	Reviewing	
<input type="checkbox"/>		0	1		BONNET (WCP)(10%)	Damaged	0	363	No				363	363	Reviewing	
<input type="checkbox"/>		0	1		L/F HINGE (WCP)(10%)	Bent	0	38.5	No				38.5	38.5	Reviewing	
<input type="checkbox"/>		0	1		R/F HINGE (WCP)(10%)	Bent	0	38.5	No				38.5	38.5	Reviewing	
<input type="checkbox"/>		0	1		BONNET LOCK	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		LEFT HEADLAMP ASSY (WCP) (10%)	Damaged	0	401.5	No				401.5	401.5	Reviewing	
<input type="checkbox"/>		0	1		RIGHT HEADLAMP ASSY	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		L/F WING (WCP)(10%)	Damaged	0	324.5	No				324.5	324.5	Reviewing	
<input type="checkbox"/>		0	1		L/F WHEELHOUSE COVER	Serviceable	0	0	No				0	0	Deny	
<input type="checkbox"/>		0	1		L/FASTENING CLIP (WCP) (10%)	Necessary	0	22	No				22	22	Reviewing	
<input type="checkbox"/>		0	1		FRONT PANEL CPL (WCP) (10%)	Buckled	0	330	No				330	330	Reviewing	
<input type="checkbox"/>		0	1		L/UPP RADIATOR BRKT (WCP) (10%)	Damaged	0	44	No				44	44	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		L/F AIR DUCT (WCP)(10%)	Deformed	0	55	No				55	55	Reviewing	
		0	1		COWL (WCP) (10%)	Cracked	0	308	No				308	308	Reviewing	
		0	1		WINDSCREEN (WCP)(10%)	Cracked	0	473	No				473	473	Reviewing	
		0	1		WINDSCREEN BOND KIT (NPA)	Serviceable	0	0	No				0	0	Deny	
		0	1		FRT SCREEN SEAL KIT (NPA)	Serviceable	0	0	No				0	0	Deny	
		0	1		CONDENSER (WCP)(10%)	Dented	0	418	No				418	418	Reviewing	
		0	1		RADIATOR CPL (WCP) (10%)	Dented	0	495	No				495	495	Reviewing	
		0	1		RADIATOR SHROUD	Serviceable	0	0	No				0	0	Deny	
		0	1		FAN MOTOR	Serviceable	0	0	No				0	0	Deny	
		0	1		COOLING FAN	Serviceable	0	0	No				0	0	Deny	
		0	1		L/GRILLE CHROME (WCP)(10%)	Cracked	0	66	No				66	66	Reviewing	
		0	1		L/DAYLIGHT (WCP)(10%)	Cracked	0	242	No				242	242	Reviewing	
		0	1		AIR CLEANER BOX (WCP) (10%)	Cracked	0	396	No				396	396	Reviewing	
		0	1		AIR DUCT	Serviceable	0	0	No				0	0	Deny	

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
	0	1		L/WIPPER CORNER (WCP)(10%)	Deformed	0	38.5	No					38.5	Reviewing	
	0	1		SUPPORT TOP GARNISH (WCP)(10%)	Deformed	0	121	No					121	Reviewing	
	0	1		HORN (WCP) (10%)	Dented	0	55	No					55	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		113.0 WU X 45.00 SGD/H	0	477	0	0	Reviewing		
	0		LABOUR COST 99.0 WU X 45.00 SGD/H	0	463.5	0	0	Reviewing		
	0		MATERIAL COST	0	218.23	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 8 DAYS	Reviewing		0		
<input type="checkbox"/>		0	NUMBER PLATE	Reviewing		35	BENT	
<input type="checkbox"/>		0	RADIATOR COOLANT	Reviewing		20	NECESSARY	
<input type="checkbox"/>		0	AIRCON COOLANT	Reviewing		50	NECESSARY	

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	FRT WINDSCREEN GUM	Reviewing		60	NECESSARY	
		0	ERP BRACKET	Reviewing		15	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Estimated Claim  
Amount

\$0.00

Adjusted Claim Amount

\$6,492.23

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$5,153.50

Labour

\$0.00

\$1,158.73

Miscellaneous

\$0.00

\$180.00

[Submit for Review](#)