

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: GEP.569.17.ct

Date: 06th January 2020

Our Ref: CS1/LAW19011523/Uvd3s2

M/s Low Yeap Toh & Goon LLP 20 Maxwell Road #12-01 Maxwell House Singapore 069113

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO PB 9988R INSURED VEHICLE GW 9774L ACCIDENT DATE 15/11/2014

We thank you for your instruction on 27/06/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PB 9988R from M/s FormTeam Consultancy Pte Ltd.
- b) Survey report by MIC Survey & Assessment Service with colour photographs.
- c) Singapore Accident Statement of Vehicles PB 9988R and GW 9774L.
- d) Colour damaged vehicle photographs of PB 9988R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number

: PB 9988R

Make & Model

: Toyota Hiace Comm D

Year of Registration

: 1997

Chassis Number

: LH1150003174

Engine Capacity

: 2779 cc

- We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.