

FormTeam Consultancy Pte Ltd

Vehicle No: PB 9988R

Workshop: Precise Auto Service

Accident Date: 15 November 2014

No. 33 Ubi Ave 3
#02-15 Vertex
Singapore 408868


Tel : (65) 6509 1788
Fax : (65) 6509 6221


Email: motorsurvey@fta.com.sg
www.fta.com.sg

Co. Reg No: 200819280D


GST Reg. No: 200819280D













← Rear Tailgate
lower panel outer







4





Difference



Rear of body
point near back rear







35 pcs