

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/0800/2019/DY  
Date : 29-Jun-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

Your insured vehicle No : **SKS 8393 H**

## AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

**Attn: Motor Claims Dept**

**Tel: 6880 4602 - Fax 6880 4838**

Owner's Name : Mr. Pang Van Khuen  
Address : Blk 825 Woodlands St 81  
#09-46  
Singapore 730825  
Telephone : (HP)+65 98765211  
Type of Claim : Third Party Claims  
Policy No. : 2100312493-06  
Vehicle No : **SKN 6688 Y**  
Model Code : Audi A6 C7 2.0 TFSI MU  
Model / Year : Aug-12  
Engine No : CDN 279606  
Chassis No : WAUZZZ4G8DN008751  
Mileage : -  
Date In : -  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 27-Jun-19  
Place of Accident : 1 NorthPoint Drive, B3 Carpark

# Premium Automobiles


55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SKN 6688 Y

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew rear bumper assy. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 800 ✓	✓
3	To respray rear bumper.	\$ 1,000.00 800 ✓	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$2,752.00</u>	





# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKN 6688 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Regis</i>	\$ 2,343.00	*
2	REAR BUMPER STICKY PAD	4 \$ 21.00	*
3	REAR BUMPER FIXING PARTS	\$ 249.00	*
4	REAR BUMPER SPOILER <i>Ken</i>	\$ 316.00	*
5	REAR BUMPER SEAL RING	\$ 5.00	*
6	SUNDRIES <i>one</i>	\$ 300.00	*
TOTAL SPARE PARTS		\$ 3,234.00	
TOTAL LABOUR		\$ 2,752.00	
GRAND TOTAL		\$ 5,986.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lj  
Surveyed Date : 03/07/19.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 days

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant