

ASS. REC. BY:

REF: CS / CTI 19011550 / Ksd3^{SV}

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

main

From (Person): Elaine Chong of CTL Date/Time: 28.6.19 17:43 PM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 8433R Insured: SKE 5838K

at Workshop m/s S & H Motor Tel: 64534930

of 160 SN mng Drive # 07-02

Policy No: DMPCSA 30337319011 Claim No: SNM 191020989

Sum Insured: Excess:

Make of Veh: D.O.A. 25.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 17.19 8:55 a.m Person Contacted: Cynthia Vehicle (IN) OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SKE 5838K : X
	GBH 8433R : X
23/6/19	@ 08:46 am Kenneth say L/S basis.

ASS. REC. BY:

ASSIGNMENT

From: Date: 1.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBH 8433R at Workshop m/s S & H Motor of 160 sn ming Drive #07-02

Insured:

Policy No.:

Claims No.:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.0B.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBH 8433R Yr Regn: 10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Proak m) c.c 1 PPZ

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 41218 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: YAR VFA14KMG 2062476

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 25/6/19 D.O.I. 1/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/10/19 Confirmed HS \$ 6,800/- @ 6 days with Kenneth (\$ 1,963.12 Red - 22%)

RECEIVED 29 OCT 2019

Date/Time, File Pass to?

29/10/19

[] : Preli. Report

[x] : Final Report

1) Typist

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: [] : Site Insp (\$)

[] : Interview (\$)

[] : Tech. Invs (\$)

[] : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ 6,800/- HS)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jun 2019 Sendback Est	28 Jun 2019 16:43 S\$8,763.12	28 Jun 2019 17:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	-, ID: -		
Main Claimant:	LEOMAX, Co. Reg. No.: -		
Vehicle Reg. No.:	GBH8433R	Date of Loss:	25/06/2019 18:00 - :59 [8 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202989-(PRS) CHEONGML	Policy/Cover Note No.:	DMPCSN30337319011
Vehicle Reg. No. (Insured):	SKE5838K	Policy No. (Claimant):	60013680
		Excess:	S\$1,000.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/07/2019]		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Enquiry <enquiry@sh-motor.com>
Sent: Saturday, 26 October 2019 4:17 pm
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: RE: GBH 8433R FINALIZE DOA - 25/06/2019

Dear Shirley

Noted....Thank....lump sum cost \$6,800.00

Thank

Doris

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 23 October 2019 10:13 AM
To: enquiry@sh-motor.com
Cc: SUR
Subject: GBH 8433R FINALIZE DOA - 25/06/2019

Dear Cyhthia,

Please confirm final fig \$ 6,800.00 (lump sum) @ 6 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2019 12:38
Date Of Accident	25/06/2019 18:00
Exact Location Of Accident	JALAN BUKIT MERAH TOWARDS CITY NEAR BLK 115
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH8433R
Insured/Policyholder	
Name Of Registered Owner	LEOMAX
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92393733
Alternative Phone No	OFFICE-92393733

Vehicle Particulars

Manufacturer	TOYOTA
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	60013680
Cover Note Number	

Driver

Name of Driver	NEO SENG HOCK
NRIC No	S1596321B
Date Of Birth	29/07/1963
Occupation	INDOOR
Date Of Driving Pass	09/11/1981
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92393733
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7935C
Vehicle Details	
Vehicle No.:	GBH8433R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PROACE COMFORT MEDIUM 2.0 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	AH014009365
Chassis No.:	YARVFAHKHGZ062476
Maximum Power Output:	-
Open Market Value:	\$31,597.00
Original Registration Date:	09 Oct 2018
First Registration Date:	09 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,580.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$26,708.00
COE Rebate Amount:	\$21,366.00
Total Rebate Amount:	\$21,366.00

The information contained herein is correct as at 26 Jun 2019

OK

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Claim Reference:
 Assessment number: 009215
 Version: 1810
 Date calculated: 28/06/2019 4:29 PM

Full Report
 Registration: GBH8433R
 Printed: 28/06/2019 4:29 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	23.30	233.0	978.60
Total of Labour			978.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR PANEL NEW PART PAINTING	22.0
	L/WING DOOR SKIN NEW PART PAINTING	16.0
	R/WING DOOR SKIN NEW PART PAINTING	16.0
	L/R WING SURFACE PAINT	19.0
	R/R WING SURFACE PAINT	9.0
	REAR FLOOR PANEL SURFACE PAINT	13.0

Paint Material Per Part

Code	Description	Price SGD
2715	REAR PANEL NEW PART PAINTING	26.95
3085	L/WING DOOR SKIN NEW PART PAINTING	45.92
3086	R/WING DOOR SKIN NEW PART PAINTING	45.92
3481	L/R WING SURFACE PAINT	75.45
3482	R/R WING SURFACE PAINT	29.63
3901	REAR FLOOR PANEL SURFACE PAINT	49.05

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		95.0	
Preparation Main Work Metal	2.50	25.0	105.00
Total	10 WU/h	120.0	504.00

Material Cost - Paint	Price SGD
New Part Painting	118.79
Surface-/Blend Paint	154.13
Material-constant Metal Preparation	28.60
Total	301.52

Spare Parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary charges must be made
- is subject to final approval from Ins

Acknowledged by Repairer
 Signature:
 Date:

prices as at 2015-06-01/01

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Claim Reference:
 Assessment number: 009215
 Version: 1810
 Date calculated: 28/06/2019 4:29 PM

Full Report
 Registration: GBH8433R
 Printed: 28/06/2019 4:29 PM

Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	SU001 A3231		Bu 870.00 ✓
2606	REAR BUMPER CAP	SU001 A4398		Nil 39.00 ✓
2618	R/R OUT BUMPER BRKT	SU001 A4396		Nil 39.00 ✓
2623	RR CTR BUMPER BRKT	SU001 A4250		R1 180.00 ✓
2640	REAR BUMPER C-MEMBER	SU001 A4489		R1 490.00 ✓
2715	REAR PANEL	SU001 A4567		R1 380.00 ✓
2944	WING DOOR SEALS	SU001 A6030		Nil / R1 280.00 ✓
2946	REAR VANE DOOR SEAL	SU001 A6100		Nil 230.00 ✓
3023	BADGE TOYOTA	SU001 A5101		Nil 38.00 ✓
3024	BADGE MODEL	SU001 A5104		Nil 42.00 ✓
3085	L/WING DOOR SKIN	SU001 A4163		R1 1,600.00 ✓
3086	R/WING DOOR SKIN	SU001 A4162		R1 1,600.00 ✓
3118	R/R LOWER DOOR LOCK	SU001 A4175		R1 230.00 ✓
3179	L/R SCREEN GLUE KIT	PZ49I 00C1131		Nil 0.00
3180	R/R SCREEN GLUE KIT	PZ49I 00C1131		Nil 0.00
3281	L/R LAMP	SU001 A4081		CM 320.00 ✓
3414	R/R REFLECTOR	81920 0H020		CM 65.00 ✓
1000	RH win moulding	RH tail door		Nil 50.00 ✓
1001	LH win moulding	LH tail door		Nil 45.00 ✓
1002	RH tail door PROACE	RH tail door		Nil 45.00 ✓
1003	Rear end panel inner	Rear end panel		R1 220.00 ✓
	f: OEM Parts			
	n: Non-OEM Parts			
	u: Used parts			
	Savings			0.00
	Subtotal			6,763.00
	Fixed Sundry Parts Price			Nil 100.00
	Total			6,863.00

Extras

Code	Description	Price SGD
1004	Electrical work Electrical work	25.00* ✓
1005	Rear number plate Rear No Plate	Sm 35.00* X
1006	LH rear win sealant LH tail door	Nil 20.00* ✓
1007	RH rear win sealant RH tail door	Nil 20.00* ✓
1008	8 Pax sticker Rear sticker	Nil 8.00* ✓
1009	70 KMH Sticker	Nil 8.00* ✓
	Total Extras	116.00

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Claim Reference:
 Assessment number: 009215
 Version: 1810
 Date calculated: 28/06/2019 4:29 PM

Full Report
 Registration: GBH8433R
 Printed: 28/06/2019 4:29 PM

Final Calculation

	SGD	SGD
Parts	6,763.00	
Fixed Sundry Parts Price	100.00	
Total Parts		6,863.00
Labour Time Base 10 WU/h		
Total 233.0 WU X 42.00 SGD/h	978.60	<i>768.60</i>
Total of Labour		978.60
Total Of Extras		116.00
Paint Work Time Base 10 WU/h		
Labour Cost 120.0 WU X 42.00 SGD/h	504.00	
Material Cost	301.52	
Total Paint Including Material		805.52
Repair Cost Excludes GST		8,763.12
GST (+7.0%)		613.42
Repair Cost Included GST		9,376.54

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: 009215
Date calculated: 23/10/2019 10:06 AM

Full Report
Registration: GBH8433R
Printed: 23/10/2019 10:06 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	25/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle			
Manufacturer:	TOYOTA		
Model:	PROACE		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 PA 01		
Registration:	GBH8433R		
VIN number:			
Odometer:			
Model Specs			
RR WING DOOR W/GLASS VAN	TWO COAT METALLIC	PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All
Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	STRIP + RETRIM REAR END PANEL INCLUDES: R + R REAR BUMPER		15.0	63.00
NO NUMBER	RENEW REAR END PANEL		48.0	201.60
NO NUMBER	R + R LEFT TAILLAMP		2.0	8.40
NO NUMBER	RENEW REAR BUMPER		3.0	12.60
NO NUMBER	R + R LEFT REAR WING DOOR		6.0	25.20
NO NUMBER	R + R RIGHT REAR LOADING DOOR		5.0	21.00
NO NUMBER	STRIP + RETRIM LEFT REAR SWIVEL DOOR		9.0	37.80
NO NUMBER	STRIP + RETRIM RIGHT REAR SWIVEL DOOR		5.0	21.00
NO NUMBER	RENEW L/R WING DOOR SKIN		25.0	105.00
NO NUMBER	RENEW R/R WING DOOR SKIN		25.0	105.00
NO NUMBER	ADDITIONAL: R + R L/R DOOR WINDOW		5.0	21.00
NO NUMBER	ADDITIONAL: R + R R/R DOOR WINDOW		5.0	21.00
NN	Rear end panel inner R&R / NEW PARTS		30.0*	126.00
3901	REAR FLOOR PANEL REPAIR			
Labour Cost			Hrs	WU
Panel / Mechanical Labour			18.30	183.0
Total of Labour				768.60

Paint

Code	Description - TWO COAT METALLIC	SYSTEM AZT	Time Basis 10 WU/h	
			WU	Price SGD
	REAR PANEL NEW PART PAINTING		22.0	
	L/WING DOOR SKIN NEW PART PAINTING		16.0	
	R/WING DOOR SKIN NEW PART PAINTING		16.0	
	L/R WING SURFACE PAINT		19.0	
	R/R WING SURFACE PAINT		9.0	
	REAR FLOOR PANEL SURFACE PAINT		13.0	

Paint Material Per Part

Code	Description	Price SGD
2715	REAR PANEL NEW PART PAINTING	26.95
3085	L/WING DOOR SKIN NEW PART PAINTING	45.92
3086	R/WING DOOR SKIN NEW PART PAINTING	45.92
3481	L/R WING SURFACE PAINT	75.45
3482	R/R WING SURFACE PAINT	29.63
3901	REAR FLOOR PANEL SURFACE PAINT	49.05

Labour Cost - Paint

	42.00 SGD/h	Hrs	WU	Price SGD
Factor			95.0	
Time Paint				
Preparation Main Work Metal		2.50	25.0	105.00
Total	10 WU/h	12.00	120.0	504.00

Material Cost - Paint

New Part Painting
 Surface-/Blend Paint
 Material-constant Metal Preparation
Total

Price SGD
118.79
154.13
28.60
301.52

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2581	REAR BUMPER	SU001 A3231		870.00
2606	REAR BUMPER CAP	SU001 A4398		39.00
2618	R/R OUT BUMPER BRKT	SU001 A4396		39.00
2623	RR CTR BUMPER BRKT	SU001 A4250		180.00
2640	REAR BUMPER C-MEMBER	SU001 A4489		490.00
2715	REAR PANEL	SU001 A4567		380.00
2944	WING DOOR SEALS	SU001 A6030		280.00
2946	REAR VANE DOOR SEAL	SU001 A6100		230.00
3023	BADGE TOYOTA	SU001 A5101		38.00
3024	BADGE MODEL	SU001 A5104		42.00
3085	L/WING DOOR SKIN	SU001 A4163		1,600.00
3086	R/WING DOOR SKIN	SU001 A4162		1,600.00
3118	R/R LOWER DOOR LOCK	SU001 A4175		230.00
3179	L/R SCREEN GLUE KIT	PZ49I 00C1131		0.00
3180	R/R SCREEN GLUE KIT	PZ49I 00C1131		0.00
3281	L/R LAMP	SU001 A4081		320.00
3414	R/R REFLECTOR	81920 0H020		65.00
1000	RH win moulding	RH tail door		50.00
1001	LH win moulding	LH tail door		45.00
1002	RH tail door PROACE	RH tail door		45.00
1003	Rear end panel inner	Rear end panel		220.00
				Savings
				0.00
				Subtotal
				6,763.00
				Fixed Sundry Parts Price
				100.00
				Total
				6,863.00

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Extras

Code	Description	Price SGD
1004	Electrical work Electrical work	20.00*
1006	LH rear win sealant LH tail door	20.00*
1007	RH rear win sealant RH tail door	20.00*
1008	8 Pax sticker Rear sticker	8.00*
1009	70 KMH Sticker	8.00*
Total Extras		76.00

Final Calculation

	SGD	SGD
Parts	6,763.00	
Fixed Sundry Parts Price	100.00	
Total Parts		6,863.00
Labour Time Base 10 WU/h		
Total 183.0 WU X 42.00 SGD/h	768.60	
Total of Labour		768.60
Total Of Extras		76.00
Paint Work Time Base 10 WU/h		
Labour Cost 120.0 WU X 42.00 SGD/h	504.00	
Material Cost	301.52	
Total Paint Including Material		805.52
Repair Cost Excludes GST		8,513.12
GST (+7.0%)		595.92
Repair Cost Included GST		9,109.04

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

Author	Date	Text
LKKAUTO	23/10/2019 10:06 AM	L/S \$ 6,800.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jun 2019 Sendback Est	28 Jun 2019 16:43 S\$8,763.12	28 Jun 2019 17:43 Edit Adj Rpt	S\$6,800.00 Edit Estimates	S\$6,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	-, ID: -								
Main Claimant:	LEOMAX , Co. Reg. No.: -								
Vehicle Reg. No.:	GBH8433R	Date of Loss:	25/06/2019 18:00 - :59 [8 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202989-(PRS)CHEONGML	Policy/Cover Note No.:	DMPCSN30337319011						
Vehicle Reg. No. (Insured):	SKE5838K	Policy No. (Claimant):	60013680						
		Excess:	S\$1,000.00						
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/07/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBH8433R (SNM19D202989-(PRS)CHEONGML)
[SKE5838K]
 TP
LEOMAX
 Jun 25 2019 6:00PM
 [-]
S & H Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail Print
1	28/06/19 16:43	Repairer Estimates	<input checked="" type="checkbox"/> Load HTM
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
2	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
3	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
4	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
5	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
6	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
7	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
8	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
9	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
10	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
11	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
12	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
13	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
14	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
15	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
16	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
17	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
18	23/10/19 10:09	General View	<input checked="" type="checkbox"/> Load JPG
19	23/10/19 10:10	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
20	23/10/19 10:10	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
21	23/10/19 10:10	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
22	23/10/19 10:10	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
23	23/10/19 10:10	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
24	23/10/19 10:10	Reinspection Photo	<input checked="" type="checkbox"/> Load JPG
Documentation			1 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	29/10/19 09:43	GBH8433R - AUDATEX.pdf	<input checked="" type="checkbox"/> Load PDF

Linked Accident Report Documents

			View View in Browser ▼
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail Print
1	26/06/19 15:14	Accident Statement	<input checked="" type="checkbox"/> Load HTM
2	26/06/19 15:23	Addendum Sheet	<input checked="" type="checkbox"/> Load TIF
3	26/06/19 15:27	Accident Statement Addm. #1	<input checked="" type="checkbox"/> Load HTM

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	26/06/19 15:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/06/19 12:48	Sketch Plan	Load TIF	
2	26/06/19 15:26	Accident Sketch Plan	Load TIF	
3	26/06/19 15:26	Accident Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011550/KSD3S2

Date: 31/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30337319011
 Claimant Vehicle No: GBH8433R Insured Vehicle No: SKE5838K
 Date of Loss: 25/06/2019 Nature of Claim: TP Claim No: SNM19D202989-(PRS)CHEONGML

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH8433R**
 Make & Model: TOYOTA PROACE COMFORT MEDIUM, 2.0 (M) Engine No: AH014009365
 Reg. Date: 09/10/2018 (Man. Year: 2016) Chassis No: YARVFAHKHGZ062476
 Colour: Metallic Silver Odometer: 41218 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,763.00	6,763.00	0.00	0.00
Miscellaneous Items	216.00	176.00	40.00	18.52
Paintwork Materials	301.52	301.52	0.00	0.00
Labour	978.60	768.60	210.00	21.46
Paintwork Labour	504.00	504.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,763.12	8,513.12	250.00	2.85
Approved Total (Overridden) (S\$)		6,800.00		
(S\$)	8,763.12	6,800.00	1,963.12	22.40
+ GST 7.00/7.00% (S\$)	613.42	476.00	137.42	22.40
Nett Amount (S\$)	9,376.54	7,276.00	2,100.54	22.40

INSPECTION

Date of Assignment: 28/06/2019 Present Location: S & H Motor Pte Ltd (Sin Ming)
 Date Inspected: 01/07/2019 Inspected At: S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming AutoCity
 Singapore 575722
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 31 Oct 2019)**Parts:** N/A TOYOTA PROACE COMFORT MEDIUM 2.0 (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBH8433R)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare parts		6,763.00 F	*- F
2	1		*REAR BUMPER	Buckled	-	*870.00 F
3	1		*REAR BUMPER CAP	Missing	-	*39.00 F
4	1		*R/R OUT BUMPER BRKT	Distorted	-	*39.00 F
5	1		*RR CTR BUMPER BRKT	Bent	-	*180.00 F
6	1		*REAR BUMPER C-MEMBER	Bent	-	*490.00 F
7	1		*REAR PANEL	Bent	-	*380.00 F
8	1		*WING DOOR SEALS	Distorted / Dented	-	*280.00 F
9	1		*REAR VANE DOOR SEAL	Distorted	-	*230.00 F
10	1		*BADGE TOYOTA	Necessary	-	*38.00 F
11	1		*BADGE MODEL	Necessary	-	*42.00 F
12	1		*L/WING DOOR SKIN	Bent	-	*1,600.00 F
13	1		*R/WING DOOR SKIN	Bent	-	*1,600.00 F
14	1		*R/R LOWER DOOR LOCK	Dented	-	*230.00 F
15	1		*L/R SCREEN GLUE KIT (NPA)	Not Necessary	-	*- F
16	1		*R/R SCREEN GLUE KIT (NPA)	Not Necessary	-	*- F
17	1		*L/R LAMP	Cracked	-	*320.00 F
18	1		*R/R REFLECTOR	Cracked	-	*65.00 F
19	1		*RH WIN MOULDING	Necessary	-	*50.00 F
20	1		*LH WIN MOULDING	Necessary	-	*45.00 F
21	1		*RH TAIL DOOR PROACE	Necessary	-	*45.00 F
22	1		*REAR END PANEL INNER	Bent	-	*220.00 F

F=Franchise part.

Total Parts (\$\$)	6,763.00	6,763.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Materials				
1	1	Paintwork material	301.52	301.52
Miscellaneous Items				
2	1	70 KMH STICKER (NECESSARY)	-	8.00
3	1	8 PAX STICKER REAR STICKER (NECESSARY)	-	8.00
4	1	ELECTRICAL WORK ELECTRICAL WORK.	-	20.00
5	1	FIXED SUNDRY PARTS PRICE (NECESSARY)	-	100.00
6	1	LH REAR WIN SEALANT LH TAIL DOOR (NECESSARY)	-	20.00
7	1	Misc	216.00	0.00
8	1	REAR NUMBER PLATE REAR NO PLATE (SERVICEABLE)	-	0.00
9	1	RH REAR WIN SEALANT RH TAIL DOOR (NECESSARY)	-	20.00
Sub Total (S\$)			517.52	477.52

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Labour for paintwork	New	504.00	504.00
Labour Items				
2	Labour for mechanical/panel	New	978.60	768.60
Gross Labour Cost (S\$)			1,482.60	1,272.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >