



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLP 4804 U

Parts	(a) Cost / List Price Items	<i>Finalised</i> \$ <i>2940.85</i>	5,245.43
	Plus/Less 25%	\$ <i>735.21</i>	1,311.36
	Total of Cost / List	\$ <i>2205.64</i>	3,934.07
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
	Total Parts Cost	\$	4,284.07
Labor		\$ <i>1460.00</i>	2,770.00
Total		\$ <i>4165.64</i> ✓ <i>ok</i>	7,054.07

The above total will be subjected to 7% G.S.T.

Name of Surveyor : *Kenneth*
Company : *CLC*
Survey conducted on : *28/6/18* at _____

Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : *07* day(s)
- (c) Resurvey : Required / ~~Not~~ Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : *Le* Date: *28/6/18*

*Not Authorized
Personnel Repairing*



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLP 4804 U
TOYOTA PRIUS

Submit By :
Year Manufacture :
Engine No. :

Carmen Lim

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door	1	\$1,211.40		✓
2	LH rear door hinge top	1	\$78.34		X
3	LH rear door hinge bottom	1	\$78.34		X
4	LH rear door weatherstrip	1	\$198.70		X
5	LHR door glass outer moulding	1	\$107.80		X
6	LHR power window motor	1	\$187.90		X
7	LHR power window regulator	1	\$570.60		X
8	LH rear fender	1	\$883.60		✓
9	LH rear fender undershield	1	\$92.30		X
10	LH rear fender undershield clip	10	\$30.00		X
11	LH rear fender air duct	1	\$115.60		X
12	LH rear tyre	1	\$350.00	S.N	X
13	LH rear hub cap	1	\$195.65		✓
14	Rear bumper	1	\$497.50		✓
15	Rear bumper clip	10	\$40.00		✓
16	Rear bumper side retainer LH	1	\$112.70		✓
17	Rear bumper side retainer RH	1	\$112.70		X
18	Rear bumper lower garnish centre	1	\$582.60		X
19	Rear bumper lower garnish LH	1	\$149.70		X
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2440.75



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLP 4804 U**

Submit By : **Carmen Lim**

Make & Model : **TOYOTA PRIUS**

Year of Manufacture : **0**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHF DOOR, LHR DOOR, LHR FENDER, REAR BUMPER)	\$1,000.00	800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHF DOOR, LHR DOOR, LHR FENDER, REAR BUMPER)	\$1,000.00	800
3	TO Check wiring	\$50.00	20
4	To do wheel alignment.	\$120.00	60
5	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
6	To tuff coat.	\$150.00	60
7	To remove & refit inner seat & upholstery to assist work load.	\$150.00	100
8	To remove & refit petrol tank to assist work load.	\$150.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.