

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 332B -

ROEL

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 332B - ROEL
 JTDER12W003001036*
 TOYOTA
 WISH 1.8
 30.11.2014
 AXA

		PART	LIST	
1	1	Front Bumper Cover ✓	\$	487.80
2	1	Front Bumper Lower Absorber ✓	\$	108.33
3	1	Front Bumper Reinforcement ✓	\$	265.09
4	1	Front Bumper Side Support LH ✓	\$	63.50
5	1	Front Bumper Side Support RH ✗	\$	63.50
6	1	Front Bumper Retainer RH ✗	\$	68.50
7	1	Front Bumper Retainer LH ✓	\$	68.50
8	1	Front Bumper Lower Grille ✗	\$	215.60
9	1	Front Bumper Fog Lamp Cover RH ✗	\$	17.60
10	1	Front bumper Fog Lamp Cover LH ✓	\$	17.60
11	1	Bonnet ✗	\$	849.30
12	1	Bonnet Insulator ✗	\$	436.72
13	1	Bonnet TOYOTA Badge ✗	\$	189.00
14	1	Bonnet Hinge RH ✓	\$	68.00
15	1	Bonnet Hinge LH ✓	\$	68.00
16	1	Bonnet Lock ✗	\$	75.02
17	1	Bonnet moulding ✗	\$	161.97
18	1	Front Support Panel ✗ repair	\$	1,018.60
19	1	Front Brace Panel ✗	\$	79.57
20	1	Front Fender RH ✗	\$	698.00
21	1	Front Fender LH ✓	\$	698.00
22	1	Front Fender Liner LH ✓	\$	307.62
23	1	Front Headlamp RH ✗	\$	800.02
24	1	Front Headlamp LH ✓	\$	800.02
25	1	Radiator Assembly ✗	\$	1,890.20
26	1	Radiator Grille ✗	\$	169.80
27	1	Aircon Condenser ✗	\$	1,488.00
28	1	Front shock absorber assy LH ✗	\$	465.00
29	1	Front lower arm LH ✗	\$	517.14
30	1	Front knuckle arm LH ✗	\$	408.95

TOTAL	\$	12,564.95
25%	\$	3,141.24
	\$	9,423.71

Specical Nett

1	Front Licence Plate	✓	\$	80.00
1	Front CNG Sticker	✓	\$	15.00
1Set	Front Bumper Fastener Clip	✓	\$	12.00
1Set	Bonnet insulator clip	✓	\$	35.00
1Set	Bonnet Under Weatherstrip Seal Clips	✓	\$	18.00
2 Set	Front Fender Liner clip	LH/ RH ✓	\$	24.00 12
1Set	Radiator Grille Clip	✓	\$	18.00
1	Front tyre LH	✓	\$	180.00
1	Front tyre rim LH	✓ repair	\$	120.00
1	Front tyre rim hub cap LH	✓	\$	50.00

TOTAL \$ 552.00

TOTAL PARTS \$ 9,975.71

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 800
Putty And Spray Painting Of The Affected	\$	2,700.00 600
To Rust-proofing Of The Affected Areas.	\$	220.00 40
To Check Electrical Lighting Concerned.	\$	120.00 30
To Check Steering Geometry And Computer Wheel Alignment.	\$	220.00 ✓
To Transfer Of Tire, Rim And On Wheel	\$	170.00 ✓
To Replace, Refix And Top Up Coolant For Radiator	\$	120.00 ✓
To Dismantle And Refit Front End Suspension, Undercarriage Parts, Final Checking And	\$	270.00 ✓
To Pull And Jack Out Chassis Frame And Correct It To Symmetrical Position With The Aid Of Hydraulic Pneumatic Jack.	\$	380.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 332B -To vacuum, replace, refix and recharge air
condenser

\$

~~380.00~~ XTo dismantle and refit aircon assy and
attachment, vacuum and charge-in-gas.

\$

~~380.00~~ X**Towing Fees**

\$

~~120.00~~ 70**TOTAL** \$ 7,880.00**Over all total** \$ 17,855.71**REPAIRE DAYS****10 DAYS**

Kalu (Kle)

2/12/14

4 Repair Dgs.

Lump Sum Repair

After Repair photo